

UNCLASSIFIED

AD NUMBER AD911983 **NEW LIMITATION CHANGE** TO Approved for public release, distribution unlimited **FROM** Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; 26 JUL 1973. Other requests shall be referred to Headquarters, Department of The Army, Attn: DAFD-DOS, Washington, DC 20310. **AUTHORITY** OACSFOR, D/A Itr, 13 Se 1973







UNCLASSIFIED

ARMY CONCEPT TEAM IN VIETNAM APO San Francisco 96243




EMPLOYMENT OF CV-28 COMPANY IN COUNTER-INSURGENCY OPERATIONS (U)





Best Available Copy



ARMY CONCEPT TEAM IN VIETNAM APO San Francisco 96243

FINAL REPORT. 1 May 52 3 LOG 64.

EMPLOYMENT OF CY-2B COMPANY (U)


JUL 26 1973

pent pent saul

PAUL L. BOGEN
Colonel, Armor
Chief

DOWNGRADED AT 8-YEAR INTERVALS
DECLASSIFIED AFTER 12 YEARS
DOD DIR 5200.10

CUTH HE DA OACSFOR
THATE DOWNGRATED 18 JUL 7 3
IDENT (PER & AGENCY) CHILF, DAFD DOS



137 35

AUTHORITY

Letter AGAM-P(M) (17 Jul 64), AGSFOR DA (31 Jul 64), subject: Army Troop Test Program in Vietnam (U), as amended.

CINCPAC Message DTG 030426Z March 1964.

Letter, MACJ311, Hq COMUSMACV, 8 June 1964, subject: Employment of CV-2B in Counterinsurgency Operations (U).

ACKNOWLEDGMENTS

The Army Concept Team in Vietnam acknowledges the cooperation and assistance of the following units in the conduct of this evaluation:

United States Army Support Command, Vietnam 765th Transportation Battalion 61st Aviation Company 5th Special Forces Group

PROJECT OFFICER

Lt. Colonel Homer L. Walker, Infantry

EVALUATORS

Lt. Colonel Dewey F. Moser, Transportation Corps Major Nesbert L. Miller, Transportation Corps Major Herbert M. Smith, Jr., Artillery Captain James M. Henderson, Jr., Artillery

CONTENTS

			Page
I.	PRE	EFACE	
	A.	Abstract	1
	В.		1
	¢.	Summary of Conclusions	3
II.	INT	TRODUCTION	
	A.	Purpose	5
	В.	Background	5
	Ç.	Scope	5
	D.	Background	7
III.	DIS	SCUSSION	
	Α.	Objective 1 - Operations	9
	в.	Objective 1 - Operations	26
	С.	Objective 3 - Evaluation of TOE	32
	D.	Objective 4 - Logistics	46
	E.	Objective 5 - Navigation and Communication Equipment	62
IV.	CON	NCLUSIONS AND RECOMMENDATIONS	
	Α.	Conclusions	73
	В.	Recommendations	75
	ANN	NEXES	
	Α.	Pnemy, Weather, and Terrain	A-1
	В.		B-1
	C.		C-1
		the Commanding Officer, 5th Special Forces Group	
	D.		D-1
		Recommended Changes to TOE 1-59D	E-1
	F.	Data Collection Forms	F-1
	G.	Distribution	G-1

FIGURES

<u>Figure</u>					Page
1.	Command and Control Structure for Allocation and Employment of CV-2B Aircraft in RVN	,	٠	æ	10
2.	Corps Areas in the RVN During the Evaluation	٠	•	٠	12
3.	Present-for-Duty Aviator Strength During the Evaluation	•	ø	•	13
4.	Present-for-Duty Aircraft Mechanic Strength During the Evaluation	•	•	•	14
5،	Aviator Experience Level upon Joining Company	•	•	•	16
6.	Viet Cong Captives Boarding a Caribou		3	•	17
7.	Special Forces Medic Prepares a Montagnard Man for Medical Evacuation	٠	٠	•	17
8.	CV-2B Support Provided to Corps	•	٠		18
9.	Work Performed Per Aircraft-Day in Each Corps	•	٠	•	19
10.	Cargo Delivered to Special Forces Compared to Cargo Delivered to All Other Users During the Evaluation	c	•	•	21
11.	Frequency Relationship of Delivery Methods .	٠	٠		22
12.	Distribution of CV-2B Flying Hours Among . Supported Units	•	•	a	23
13.	Aircraft Hits by Corps and by Month	0	٠	۰	24
14.	Aircraft Hits at Various Altitudes		•	•	25
15.	Typical Jungle Drop Zone	•	,	•	28
16.	IOLEX and Paradrop Comparison	5	,	**	30
17.	LOLEX Delivery	•	,	,	31
18.	Aviator Flying Time Per Month			_	36

FIGURES

Figur	<u>re</u>	Page
19.	Standard Maintenance Stand	41
20.	Proposed Maintenance Stand (Side View)	42
21.	Proposed Maintenance Stand (Top View)	43
22.	Standard Maintenance Hoist	44
23.	Abbey Hydraulic Hoist	45
24.	Maintenance Flow	47
25.	CV-2B Availability Rate in RVN by Month	50
26.	Average Daily CV-2B Availability and Utilization	50
27.	Man-Hours Expended by Echelon for Normal Periodic Inspections	51
28.	Man-Hours Expended by Unit on Demand-Maintenance	52
29.	Man-Hours Expended on Battle-Damaged Caribou	54
30.	Requisition Channels (Code O2)	56
31.	Number of Days CV-2B's Were Grounded for Parts	57
32.	Code 02 Requisition Dats ,	58
33.	Code 05 Requisition Data	59
34.	Code 12 Requisition Data	60
35.	Code 17 Requisition Data	61
36.	Facilities at Vung Tau Airfield	63
37.	Navigation Facilities in RVN	65
38.	Ground Control Facilities in RVN	66
39.	CV-2B Electronic Configuration, 61st	69

v

FIGURES

Figur	<u>a</u>			Page
40.	Signal Work Orders		, ,	71
41.	Signal Requisition Data			72
A-1.	Annual Precipitation			A-2
A-2.	Major Topographic Regions of South Vietnam			A-4
D-1.	Tako Special Forces Drop Zone			D-3
D-2.	Construction Details, 48-inch Skidboard Assembly	,		D-/*
D-3.	Lashing Down a LOLEX Load			D-5
D-4.	Securing a LOLEX Load	,		p-6
D-5.	Pilot Checks Installation of Extraction Chute in Pendulum Release Rack			ъ-6
D-6.	Schematic of a LOLEX approach		• ;	8 -0
D-7.	Extraction Chute at Release Point	. ,		D+10
D-8.	Extraction Chute Prior to Deployment	, ,	e c	9-11
D-9.	Extraction Chute Deployed			D-12
D-10.	First Load Extracted			D-13
D-11.	First Load Slides to a Stop as Second Extraction Begins			D-14
D-12.	Second Pallet Slides to a Stop as the Caribou . Initiates the Pullup	•		D-15
E-1.	Aviation Company (Airmobile - Fixed-Wing) Organization			E-1

I. (U) PREFACE

a. Abstract

Data on the CV-2B (Caribou) company were collected by the Army Con-Cept Team in Vietnem (ACTIVE during counterinsurgency operations in the Republic of Vietnam (RVN), From 1 May to 31 October 1964. The data analyzed in the present report supplement data discussed in the ACTIV final report, "Caribou Airplane in Support of Counterinsurgency Warfare" (U), dated 30 August 1963.

The ACTIV project officer and evaluators participated as crew members on each type of mission flown in each of the corps zones. Their observations, interviews, and official records form the basis of this report. No missions were generated solely for the purpose of collecting data.

The CV-2B, under operational control of the corps senior advisors, special forces in Vietnam, or United States Overseas Mission (USOM), provided effective and responsive support to counterinsurgency operations in Vietnam.

The short takeoff and landing (STOL) characteristics of the CV-2B aided by reversible pitch propellers, its capability to fly in and out of short airstrips under all but the most severe weather conditions, and its maneuverability in restricted terrain, rendered the Caribou exceptionally well-suited for sustained support of counterinsurgency operations in Vietnam. Reversible pitch propeller modification and AN/ANP-158 (WP-103) weather avoidance radar enhanced the effectiveness of the CV-2B in Vietnam.

The low-level extraction (LOLEX) technique for aerial delivery of cargo provided flexibility in selection of delivery methods, resulted in a significant reduction in cost of air items (equipment needed to rig for aerial delivery), and reduced rigging and recovery time.

Data collected in the areas of operations, supply, and maintenance indicated that TOE 1-59D, Aviation Company (Airmobile - Fixed-Wing), dated 27 March 1964, is inadequate for counterinsurgency operations

B. OBJECTIVES AND METHODS

1. Objective 1 - Operations

Document the operations of the CV-2B Caribou company and the support provided to the counterinsurgency effort in Vietnam.

Methods for meeting Objective 1 were:

- 1) catistical data were gathered from official records and reports. Interviews were made with operational and maintenance personnel.
- Evaluators and the project officer flew each type of mission in each corps zone, recorded specific data, and made general observations.

2. Objective 2 - Airdrop Techniques

Evaluate the airdrop techniques used by the Caribou company.

Methods for meeting Objective 2 were:

- 1) Observation was made of each technique. Specific data concerning accuracy of delivery were recorded. Interviews were made with special forces personnel who received the bulk of the supplies delivered.
- 2) An evaluator or the project officer flew as a crew member/observer on missions employing each type of aerial delivery technique.

3. Objective 3 - Evaluation of TOE

Evaluate the TOE under which the Caribou company operated.

Methods for meeting Objective 3 were:

- 1) Interviews were made with key personnel of the 61st Aviation Company and the Aviation Support Battalion.
- 2) Records were searched.
- 3) Observations of the suitability of the TOE were made.

4. Objective 4 - Logisitics

Document the logistical support requirements for the Caribou company employed in support of counterinsurgency operations in Vietnam.

Methods for meeting Objective 4 were:

- 1) Interviews were conducted.
- 2) Records were searched.
- 3) Observations of the supply system were made.

5. Objective 5 - Navigation and Communications Equipment

Document the operational use of navigation and communications equipment installed on the CV-2B Caribou.

Methods for meeting Objective 5 were:

- Interviews were conducted with crews and communications personnel.
- 2) Observations were made during operational missions.

C. SUMMARY OF CONCLUSIONS AND RECOMMENDATIONS

The CV-2B demonstrated its versatility in the movement of troops and cargo in and to the outlying areas of Vietnam. Its cargo capacity and its operational capabilities, when coupled with the LOLEX delivery technique, made it extremely valuable for resupplying isolated special forces camps and long-range patrols.

Since the 5th Special Forces Group has a routine requirement for US Army aerial support, CV-2B's should be allocated to the group. In order to increase effectiveness, simplify maintenance, and provide flexibility in aircraft scheduling, the modification to equip all Caribous in Vietnam with reversible pitch propellers should be expedited. Since the counterinsurgency situation in Vietnam precludes an elaborate radar network, CV-2B's operating in a counterinsurgency environment should be equipped with weather avoidance radar. In addition, during periods of poor visibility, some type of pertable terminal guidance equipment should be provided to assist aircraft in locating the positions of isolated units operating in remote areas. The technique of placing the CV-2B under operational control of the supported units proved effective and responsive and should be considered as the normal means of control in a counterinsurgency situation. TOE 1-59D, Aviation Company (Airmobile - Fixed-Wing), dated 27 March 1964, should be augmented with additional personnel and equipment for counterinsurgency operations in order to provide an adequate command control and an effective maintenance structure.

THIS PAGE NOT USED

II. (C) INTRODUCTION

A. PURPOSE

The purpose of this evaluation was to collect and analyze data on performance of the US Army CV-2B (Caribou) company during support of counterinsurgency operations in the Republic of Vietnam (RVN).

B. BACKGROUND

The 1st Aviation Company (Fixed-Wing Light Transport) was deployed from CONUS to Joint Task Force 116 in Thailand on 23 July 1962. The company was moved to Vung Tau, Vietnam in December 1962 to support counterinsurgency operations in the RVN. A second Caribou company, the 61st Aviation Company (Fixed-Wing Light Transport), was self-daployed from the United States, arriving in Vung Tau in July 1963.

The first evaluation of the Caribou in support of counterinsurgency operations was conducted by the Army Concept Team in Vietnam (ACTIV) from 1 February to 31 July 1963. The final report covering the first evaluation, "Caribou Airplane in Support of Counterinsurgency Operations" (U), dated 30 August 1963, was distributed in September 1963.

The 1st Aviation Company was returned to the United States in December 1963. The 61st Aviation Company, however, continued to support the counterinsurgency effort in Vietnam, with the aircraft placed under operational control of the corps senior advisors. A second Caribou company arrived in Vietnam on 23 October 1964 but was not operational during the evaluation period.

The second evaluation was conducted from 1 May to 31 October 1964 and covers operations of the 61st Aviation Company.

C. SCOPE

1. Definition of Project

Particular emphasis during the evaluation was placed on:

- a) Support provided to US advisor teams, Army of the Republic of Vietnam (ARVN) corps and divisions, special forces, and the United States Overseas Mission (USOM)
- b) Command and control
- c) Aviator training

- d) Airdrop techniques
- e) Flight techniques
- f) TOE
- g) Logistical support requirements
- h) Navigation, communications, and radar equipment installed on the CV-2B.

2. Setting of Project

a. Environment

The 61st Aviation Company provided support to US advisory teams, 5th Special Forces Group, ARVN, and USOM in all corps areas of the Republic of Vietnam. The Caribou flew operational missions under all but the most severe weather conditions in Vietnam, and used airfields located in all types of terrain. During the evaluation period, part of the 61st Aviation Company was flying in an area of Vietnam affected by the southwest monsoon rains while the remainder was flying in an area not affected by the monsoon. Where the physical environment had significant effect on operations, the facts have been noted. See annex A for a discussion of the enemy, weather, and terrain.

b. Military Elements

(1) Units

The documentation of operations of the 61st Aviation Company forms the basis of this report. Data were also gathered from the following units:

- a) 326th Maintenance Detachment
- b) 611th Direct Support Company
- c) 330th General Support Company
- d) 5th Special Forces Group

(2) Equipment

The CV-2B, modified with reversible pitch propeller, was the aircraft evaluated. The items used for low-level extraction (LOLEX) were standard air items procured by and for the special forces. The WP-103 weather avoidance radar was installed on three CV-2B's. No special equipment was procured during the evaluation.

(3) Mission

The mission of the 61st Aviation Company as stated in MACV Directive Number 44, dated 11 December 1963, is to aircraft in the corps tactical zones (CTZ) as directed, in direct support of corps for forward area transport.

D. EVALUATION DESIGN

The primary sources of data for the evaluation of the CV-2B were observation of and documentation of the administrative, operational, and maintenance activities of the 61st Aviation Company. Information was drawn not only from official records, reports, and summaries, but was also acquired from reports of operational missions flown by the project officer and evaluators.

Descriptions of flight techniques, support missions performed by the CV-2B, and maintenance and supply procedures were developed from observations and interviews. Investigation of aircraft availability, maintenance man-hours expended, and number and types of support missions flown resulted in numerical data which were tabulated and analyzed.

1. Methodology

a. Data Collection Methods

Data were extracted from unit records, reports, and summaries, and were placed on ACTIV forms specially designed for the evaluation. Two additional forms were designed to record data on operational missions. These data, interviews with key personnel, debriefing of crews, and opinion samplings were recorded both on questionnaires and in narrative form. Data collection forms are shown in annex F.

b. Analysis Methods

Narrative and functional descriptions provided the sources for qualitative analyses. Opinion sampling was a secondary means. Quantitative analysis was based on unit records.

2. Limitations and Variables

Missions were not scheduled solely for the purpose of generating data. Under the operational conditions prevailing in the RVN, the nature of the data collected required empirical rather than theoretical forms of analysis.

3. Support Requirements

The second secon

Support requirements were provided as directed in Military

Assistance Command (MACV) letter MACJ311, dated 8 June 1964, subject: Evaluation of the CV-28 Company in Counterinsurgency Operations.

4. Time Schedule

The Caribou company was in-country and performing operational missions prior to the initiation of the present evaluation. Evaluators joined the 61st Aviation Company after they had received two days of orientation. Data were collected and analyzed during a 195-day period.

III. (C) DISCUSSION

A. (C) OBJECTIVE 1 - OPERATIONS


1. Command and Control

The 61st Aviation Company (Fixed-Wing Light Transport) was attached to the 765th Transportation Battalion (formerly the Support Battalion). The battalion commander exercised command, but not operational control of unit aircraft. The US Army aviation element of the Joint Operations Center (JOC) had the authority to coordinate directly with the 61st Aviation Company on matters pertaining to allocation and employment of CV-2B aircraft. (See figure 1.)

The corps senior advisors were allocated most of the available CV-2B's and were responsible for stationing and controlling aircraft and for assigning missions. The corps senior advisors exercised operational control through the US Army aviation element within the corps tactical operations center (CTOC). Missions were received and approved at the CTOC. Approved preplanned missions were coordinated with the flight sections of the 61st Aviation Company the day before execution. Add-on missions, emergency missions, or changes in missions were assigned directly to the aircraft commander by the CTOC. Personnel of the US Army aviation element at CTOC conducted briefings as considered necessary. Reaction time to a mission for aircraft on stand-by was the sum of briefing and takeoff time. When sufficient time was not available it was standard procedure to brief the crews over the telephone or by radio after the aircraft was airborne. The CTOC could communicate with the aircraft through the CTOC FM net. A change in mission could be transmitted directly from CTOC to the aircraft. When USOM and special forces were allocated CV-2B aircraft, these agencies exercised operational control.

Military Assistance Command, Vietnam message, MACJ324, dated 16 September 1964, allocated CV-2B aircraft with the following priorities:

Using Agency	Number of Aircraft	Priority
USOM	1	1
Senior advisor I Corps	3	6, 10, 14
Senior advisor II Corps	3	5, 9, 13
Senior advisor III Corps	3	3, 7, 11



Command and control structure for allocation and employment of CV-2B aircraft in RVN. (U) FIGURE 1.

Using Agency	Number of Aircraft	Priority
Senior advisor IV Corps	3	4, 8, 12
JUSMAAGTHAI (Bangkok)	1	2
General support	1	15
61st Aviation Company	1	16
	Total 16	


The 16th aircraft, although allocated to the 61st Aviation Company for training, was never available because of the low priority.

When necessary, MACV temporarily changed aircraft allocations to meet urgent requirements for additional aircraft in a particular area of operations. The aircraft were then returned to the agency having initial control as soon as the requirement was satisfied.


Aircraft were stationed in accordance with the desires of the senior advisor in accordance with the tactical situation. The 61st Aviation Company, minus the one flight platoon allocated to I and II Corps, was located at Vung Tau and provided support to III and IV Corps from this location. For increased response, the aircraft allocated to I Corps were stationed at Da Nang, where I Corps Headquarters was located. Aircraft for II Corps were located at Pleiku, home of II Corps. (See figure 2.)

2. Training


When the 61st Aviation Company was deployed to Vietnam in July 1963, the unit was at full strength in both officers and enlisted men. The problem resulting from all original personnel returning home at the same time was anticipated and a plan was developed to return the officers and enlisted men in three increments. One increment would return at the end of the eleventh, twelfth, and thirteenth months, respectively. There was also an attempt to ensure continuity through the intra-theater transfer of personnel. Rotation commenced in May 1964 and was completed in August 1964. However, a delay in receiving officer and enlisted replacement adversely affected both the maintenance and operational capabilities of the unit. Figures 3 and 4 show the percent present-forduty strength of aviators and mechanics during the evaluation. Shortages, coupled with the receipt of many replacement officers and enlisted men with little or no operational experience, placed a severe training load on the organization, while operational requirements remained unchanged. Aircraft availability, as recorded on DA Form 1352, was not affected. Maintenance personnel worked nights and weekends to maintain the maximum number of flyable aircraft.



(U) FIGURE 2. Corps areas in the RVN during the evaluation.



(U) FIGURE 3. Present-for-duty aviator strength during the evaluation,



(U) FIGURE 4. Present-for-duty aircraft mechanic strength during the evaluation.

The experience level of newly assigned aviators varied widely. Figure 5 shows the total fixed-wing and CV-2B flying times of pilots and copilots for all replacement aviators on their arrival in Vietnam.

The tactical situation and the type of flying in Vietnam required that newly assigned aviators be given a detailed orientation in operational and communications procedures, the terrain, weather, and airfields. Many aviators required additional instruction in short takeoff and landing (STOL) procedures. The amount of time required before an aviator was operationally qualified varied with the individual and was not related to his previous flying time. Because the aircraft alloted was not actually available to the unit for training, all checkouts were conducted in conjunction with operational missions. This procedure, although adequate for local orientation, added many weeks and hours of unproductive straight-and-level flying time before an aviator was qualified. It required an average of 40 hours flying time and 27 days to complete a checkout while flying operational missions. The 16th aircraft, originally intended for training, was never available because aircraft availability was never 100 percent. The unit standardization officer estimated that the average time for qualification could have been reduced to 3 days and about 10 hours flying time if a training aircraft had been available.

The instructor-pilots of the 61st Aviation Company found two main areas of weakness in the training of replacement aviators: Unfamiliarity with the total capabilities of the aircraft, and a lack of proficiency in STOL. Operational flying in the counterinsurgency environment in Vietnam called for complete familiarity with the aircraft and a high proficiency in STOL.


Transition from peacetime flying to operational flying in Vietnam required that each aviation unit organize and maintain a standardization program, not only for new arrivals, but for the more experienced aviators. Each aviator in the 61st Aviation Company was required to take one standardization flight each month with an instructor pilot. This flight, like all other training, was conducted during a regular combat support mission.

Although training conducted concurrently with operational missions succeeded in producing a thoroughly oriented and confident pilot, it had the disadvantages of extending the checkout period, overworking the instructor pilots, and producing an unnecessary flight safety hazard.

3. CV-2B Support Provided to US Advisor Teams

The Caribou allocated to the corps senior advisors were employed similarly in each corps zone. Forward area resupply of isolated advisor teams and special forces strike companies, medical evacuation,






(U) FIGURE 5. Aviator experience level upon joining company.

displacement of command posts, and transportation of Viet Cong captives (figure 6), RVN troops, and their dependents were the missions normally assigned to the flight sections.

In II, III, and IV Corps, routine missions were accomplished using a system of scheduled courier flights to each of the airfields. Recurring transportation requirements were not heavy enough to justify scheduled courier flights in I Corps. All flights in I Corps were scheduled on a mission basis as approved by CTOC.

Medical evacuation by Caribou was an mally preplanned for large scale operations. Helicopters transported casualties to the closest airstrip where they were evacuated by Caribou to the nearest hospital. This procedure maximized the use of helicopters by shortening their turnaround time. (See figure 7.)


Delivery of supplies by paradrop was more frequent in I, III, and IV Corps area. In II Corps, where the special forces had a LOLEX rigging capability at their supply base at Nha Trang, the paradrop requirement was less frequent. Low-level extraction was more effective and more economical than the paradrop methods. (See objective 2.) Figures 8 and 9 show the amount and type of support provided to each of the four corps.



(U) FIGURE 6. Viet Cong captives boarding a Caribou.





(U) FIGURE 7. Special forces medic prepares a Montagnard man for medical evacuation.





(U) FIGURE 8. CV-25 support provided to corps.

1 CV-28 FLOWN DURING) DAY # 1 3/RCRUET DAY # 1 TY TY LORPS CORPS CORPS









AVESTSV CARGO (POUNDS) THANSPORTED PER AMERAFT-DAY

(U) FIGURE 9. Work performed per aircraft-day in each corps.

Narrative descriptions of typical CV-2B missions are in annex B. Annex C contains corps senior advisors' comments relative to US Army CV-2B support provided.

4. CV-2B Support Provided Special Forces

Special forces detachments were under operational control of the senior advisor of the corps in which they were located. Caribou support was requested by special forces and provided on a mission basis from the aircraft allocated to the corps. Each mission requested was either approved or disapproved by the CTOC based on the immediate situation.

There were 42 "A" and 4 "B" special forces detachments in Vietnam. Thirty-six were located on or near airfields. The Caribou with reversible pitch propellers could land at all of these airfields except Hai Yen in IV Corps which was too narrow to permit turnaround.


Approximately 72 percent of the special forces aerial resupply effort originated at the Special Forces Logistical Support Center at Nha Trang. The supplies were flown directly to the "A" detachments in the field. No CV-2B aircraft were specifically allocated to the center. Support from Nha Trang was limited to special or opportune missions and when requested by "B" detachments using an aircraft made available by the corps senior advisor.

Figure 10 portrays the amount of cargo in tors, divided into that delivered to special forces and to all other users, that was transported by CV-2B during the evaluation. This support was provided by aircraft allocated to the corps. Figure 11 portrays the frequency relationship, by percent, of the methods used to deliver cargo to special forces detachments.


Using all types of aircraft that were available, special forces delivered by paradrop approximately 920,000 pounds of all types of supplies each month. According to estimates of special forces headquarters approximately 552,000 pounds, or 60 percent, of the supplies that were airdropped could have been airlanded or delivered by LOIEX using CV-2B aircraft. Comments of the commanding officer, 5th Special Forces Group, relative to CV-2B support are in annex C.

5. Other CV-2B Support Provided

CV-2B aircraft were allocated to USOM on a mission basis. These missions were generally in support of civic action programs throughout Vietnam. Blankets for Montagnard tribes, well digging rigs, and sugar cane sprouts are examples of the type of cargo transported. The crew reported to the senior USOM official for briefing. This official maintained operational control of the aircraft until the mission was completed.



(U) FIGURE 10. Cargo delivered by CV-2B to special forces compared to cargo delivered to all other users during the evaluation.





(U) FIGURE 11. Frequency relationship of delivery methods.

A classified out-of-country mission to provide five aircraft, less crews, to a US Government agency for an indefinite period was received in May 1964. On 27 May 1964, three aircraft left Vietnam, followed by two more on 5 June 1964. The crews and maintenance support were provided by the gaining agency. The loss of these aircraft reduced the support available in-country accordingly. Figure 8 indicates the marked increase in support starting 1 September when the mission was terminated for the 61st Aviation Company.


6. Total CV-2B Support Provided

The majority of the missions flown during the evaluation were in direct support of the four corps. Forward area support was provided in varying weather conditions, enemy situations, and terrain. The Caribou was able to land at all but one airfield in Vietnam as listed in the MACV directory of airfields. No attempt was made to measure the effectiveness of the CV-2B in terms of total passengers or total tonnage carried. Mission effectiveness could only be related in terms of responsiveness to the commander and mission accomplishment. Figure 12 shows the distribution of support provided from 1 May to 31 October 1964 in terms of flying hours. Special forces support is included in the corps figures.






AIRGRAFT HITS BY CORPS TACTICAL ZONE



(U) FIGURE 13. Aircraft hits by corps and by month.



(U) FIGURE 14. Aircraft hits at various altitudes.

aircraft were able to complete their mission before returning for repairs. There were three hits received in the pilot's compartment, with injuries sustained by a pilot and a copilot. Two passengers were injured from ten hits received in the cargo compartment.

Standard aircraft approach to an airfield was at 2,500 feet altitude, with a rapid letdown to 2,000 feet at 110 knots airspeed as the aircraft passed over the field. A 270 or 180 degree approach was then executed with 15 degrees of flaps on the turn to downwind, and a gradual slowing of the aircraft. A close-in steep approach was made with 30 degrees of flaps applied on base leg. If necessary, 40 degrees of flaps were used on the final approach. This steep, slow, close-in approach kept the aircraft within forced landing distance of the airfield and away from possible VC antiaircraft teams that might be operating in the vicinity. When ceilings were below 1,000 feet in the delta region, the Caribou flew in the clouds enroute, letting down to contact conditions as the aircraft neared the point of intended landing. In the mountains, contour flying was used. (See objective 5 for a discussion of low-level navigation in Vietnam.)

The amount of antiaircraft fire received varied with the aggressiveness of the VC and the flight techniques used by the crews. Crew members were flak jackets, and some armor protection was provided in the pilot's compartment. In Vietnam it was not necessary to provide

air cover or suppressive fire to protect the Caribou while performing any of the assigned missions. However, on occasions, air cover was available.

8. Conclusions

it a real requirement of the corps sent or actions and operating of the corps sent or actions a responsive means of accomplishing the aerial movement of personnel and supplies in the corps forward areas.

b. CV-2B qualified aviators arriving in Vietnam received a comprehensive area checkout and required additional flight first ruction in STOL procedures before they were released for operational missions. and responsive means of accomplishing the orial movement of a responsive means of accomplishing the orial movement of a responsive means of accomplishing the orial movement of a responsive means of accomplishing the orial movement of a responsive and supposed a more effective unit standardization programors while a in received and received and required and ition. This has not accomplished to the first and supplies to special forces camp sites that were previously resupplied by paradrop.

Blook OBJECTIVE 2012 ATROROP TECHNIQUES

Aerial delivery of supplies in Vietnam was accomplished primarily in support of special forces. US Air Force C-123 and C-17 transport afficient were allocated for this purpose. UV-28 aircraft were made available to special forces on a mission basis from the corps allocation of aircraft. The Caribou, used as opportune airlift to assist in reducing supply backlog, performed airlanded, gravity drop, paradrop, and IDLEX missions in support of isolated special forces camp atribe force operations.

1. Gravity Drop

There were seven gravity drop missions performed during the evaluation period. These drops were primarily in support of construction activity. Sandags, barbed wire, and barbed wire pickets were the predominant supplies delivered. Gravity drop was a rapid and economical method for delivering bulk supplies and, additionally, appreciably reduced turnaround time for the aircraft, since only one low pass over the drop zone (DZ) was required to deliver the cargo.

composition operational
often in initiate for another is

To reduce exposure time of the aircraft, a steep approach was made to a DZ. Flaps were used to slow the aircraft. The pass over the DZ was made at 90 knots and at an altitude of 20 to 50 feet. With foller conveyers installed in the Caribou, the palletized cargo was easily pushed from the aircraft. After the cargo had been dropped, maximum except for takeoff (METO) power was applied and a steep climb executed until the aircraft had reached 1,500 feet terrain clearance. Normal

climb power (35 inches of manifold pressure and 2,000 rpm) was then maintained until 2,500 feet clearance was reached.

Gravity drop was a standard drop technique with limited, but valuable, application in Vietnam. The rear loading ramp and installed roller conveyors made the CV-2B suitable for employing this delivery technique.

2. Paradrop

The majority of paradrop missions flown by the CV-2B in Vietnam were in support of isolated special forces camp sites and the long range strike force patrols composed of local recruits trained, equipped, and advised by US special forces.

There were 146 paradrop missions executed from 1 May to 31 October 1964 in which 654,576 pounds of supplies were delivered. The cargo dropped on each mission averaged 4,647 pounds. The S-4,5th Special Forces Group, Vietnam estimated that approximately 10 percent of the airdropped supplies delivered by the CV-2B, C-123, and C-47 were either lost, damaged, or destroyed. His estimate was based on reports received from the field.

Resupply of strike force units on long range patrols in jungles and jungle-covered mountains presented a unique problem in Vietnam. Brop somes were too small to execute accurate drops. There were few clearings or level areas to permit delivery by LOLEX and gravity drop was not suitable for soft supplies. In many cases, the patrols could not be seen because of the jungle canopy even though communication by FM radio was possible (figure 15).

A technique for paradrop which had reasonable success was developed by the CV-2B crews and special forces "B" team attached to I Corps. Many times it was impossible to paradrop from the normal 400 foot altitude in the mountains because of the restrictive valleys, streams, and ridges selected as DZ's. The strike force was instructed to select DZ's that had open approaches. But because the jungle canopy restricted observation of surrounding terrain, experience showed that the strike force could seldom select an adequate DZ.

It was difficult to preplan the selection of DZ's for use on subsequent days because progress in the jungle could not be predicted accurately. However, it was attempted. The patrol at the predesignated time attempted to gain radio contact with the approaching Caribou. If a stream bed or open ridge was used as the DZ, panels and make were used to mark it. If the jungle canopy prevented the use of panels, then only smoke was used. Upon sighting the smoke, the Caribou executed a dive, pulling up about 400 feet from the smoke and about 150 feet above the jungle. The crew chief released two bundles just as the



(U) FIGURE 15. Typical jungle drop zone.

aircraft pulled up to avoid the trees surrounding the DZ. Additional passes were made as necessary, adjusting the dive angle and release point according to information received from personnel on the ground. When dropping in mountainous areas, the standard technique of maintaining 400 feet terrain clearance many times caused the load to be released one to three thousand feet above the DZ. With the unpredictable winds in the mountains there was no assurance of accurate delivery. In some cases where the standard paradrop technique was used in dropping into restricted areas, the higher drop altitude caused large errors in delivery. This resulted in a high percentage of cargo that could not be located or recovered because of the terrain or enemy activity. Based on patrol reports, however, special forces "B" team at Da Nang estimated that 90 percent of the equipment was recovered when delivered by the dive technique. Evaluators who flew on such missions substantiated this estimate.

3. Low-Level Extraction (IOLEX)

Low-level extraction is a method of delivering supplies from a rear-loading aircraft flying five to eight feet above the ground, at about 70 knots indicated airspeed. The supplies, packed on pallets, are placed on two sets of rollers running the length of the aircraft cargo compartment. By means of an extraction chute, the cargo is pulled from the aircraft. The pallets contact the ground in a level attitude decelerating to a stop in about 90 feet. The system requires a reasonably cleared and level area 400 feet long for the extraction of one pallet containing 3,000 pounds of cargo. A double or tandem extraction (6,000 pounds) can be made within an area approximately 700 feet long. Three pallets, each with 2,000 pounds of cargo, can be extracted in an area 1,000 feet long. Open fields and roads are ideal for LOLEX.

Low-level extraction uses standard air items and expendable pallets. It is basically the heavy drop system used at higher altitudes, minus the large cargo parachute. A qualified US Army rigger, MOS 464, 748.2, or 461A7 is required to accompany the load as drop master, to load the aircraft, install the air delivery system, and prepare the load for flight ejection. A full description of the LOLEX technique as used in Vietnam is in annex D.

At the suggestion of ACTIV, special forces procured the air items necessary to employ the LOLEX technique in Vietnam. On 19 July 1964, the first LOLEX mission executed in an operational area was flown, delivering 6,300 pounds of equipment on 3 pallets to the special forces camp site at Phrey Shrunh. This camp had previously been resupplied entirely by paradrop.

There were 55 LOLEX missions executed from 19 July to 31 October 1964, which delivered 325,502 pounds of equipment and supplies. Each mission delivered an average of 5,166 pounds of cargo. Figure 16 shows

the relative cost of the IOLEX missions executed in Vietnam, and the cost of delivering the same amount by paradrop, using the CV-2B aircraft.

Delivery Method	Rigging Time	Cost of Air Items	Lost and Damaged Supplies	Time Over DZ
LOLEX	1 Hour 10 Minutes	\$160.00	5 Percont (Actual)	6 Minutes
Paradrop	5 Hours	\$1600.00	10 Percent (Estimated)*	20 Minutes


^{*} Estimated by S-4, Special Forces Group, Vietnam.

(U) FIGURE 16. LOLEX and paradrop comparison.

Recovery of LOIEX delivered supplies could be accomplished by hitching the clevis on the pallet to a vehicle and dragging the pallet off the DZ. Compared to paradrop, LOIEX reduced recovery time significantly, although comparative times were not recorded. The time required for paradrop recovery depended on the dispersion of the paradropped bundles.

Damaged, destroyed, and lost equipment from LOLEX was 5.3 percent. Special forces estimated a loss of 10 percent from paradrop, based on after-action reports submitted by the "A" teams that were supported.

On a typical LOLEX mission, the Caribou approached the DZ at an altitude of 2,500 feet above the terrain for protection against ground fire. A letdown was executed so that the airplane arrived over the field at 2,000 feet with an airspeed of 110 knots and in a position to execute a 180 or 270 degree approach. On downwind, the gear was extended, flaps set at 15 degrees and airspeed was reduced to 90 knots. On turn to base, airspeed was reduced gradually and flaps set at 25 degrees. On short final, power was adjusted to maintain level flight 5 to 8 feet above the drop zone at 70 to 80 knots. Over the release point, the copilot activated the pendulum release on command of the pilot. After the pallets were extracted, a normal go-around was executed, and cruising altitude attained as quickly as possible. The average time the aircraft was at a vulnerable altitude, below 2,500 feet, was 6 minutes. To drop twelve 500-pound bundles by parachute at special forces airfields took an average of 4 passes at 400 feet altitude and approximately 20 minutes. Low-level extraction reduced the time of exposure to enemy antimircraft fire in the DZ by approximately 75 percent (see figure 17).



(U) FIGURE 17. LOLEX SLIVERY.

All IOLEX missions were executed in support of special forces at locations that had been previously supplied by paradrop. There were special forces camp sites in the delta region that were located on small raised portions of land, completely surrounded by flooded rice paddies, with only a narrow road leading into the camp. Supplies were delivered on these using IOLEX techniques. Annex D contains the data on each IOLEX mission performed in Vietnam during the period of the evaluation.

There were two limitations in Vietnam that affected employment of LOLEX. The requirement for an open, relatively flat DZ precluded its use in jungle and mountain operations where there were very few DZ's of adequate size. The requirement for qualified rigger personnel trained in the LOLEX system limited its use to special forces.

4. Conclusions

- a. In areas where it can be used, the LOLEX method of aerial delivery of supplies is more efficient and economical than the paradrop technique.
- b. Low-level extraction is the most accruate airdelivery technique used by the CV-2B aircraft in Vietnam.
- c. The CV-2B STOL characteristics and LOLEX capability provided 5th Special Forces Group with flexibility in selecting the most effective method for aerial delivery of supplies to isolated camp sites and patrol bases.

C. (U) OBJECTIVE 3 - EVALUATION OF TOE

During the evaluation, the 61st Aviation Company operated under TOE 1-107T which was designed for a U-1A (Otter) company. Approved changes to TOE 1-107T provided additional mechanics, clerks, and communications personnel, and adjusted MOS's to properly support the CV-2B aircraft. The major personnel deficiencies noted in TOE 1-107T were a shortage of aircraft mechanics, aircraft technical inspectors, and maintenance supervisors. Equipment deficiencies noted were unreliable generators, insdequate lighting sets for night maintenance, and inadequate maintenance stands. The requirements for a TOE for an organization in RVN would not apply worldwide; however, the counterinsurgency environment in Vietnam can serve as a model for the type of operation that might be required in many under-developed countries where there are extremes in weather and terrain and a lack of roads and modern airfield facilities. The information and data collected during the evaluation have been adjusted and applied to TOE 1-59D, dated 27 March 1964, which was approved by Department of the Army for the Aviation Company (Airmobile - Fixed-Wing). Specific recommendations for augmentation and changes to the TOE are in annex E. An extract of TOE 1-59D appears as appendix 1, anner E.

1. Personnel

a. Company Headquarters

The 61st Aviation Company was required to submitt 33 recurring reports to higher headquarters. The frequency of these reports were: 4 daily, 5 weekly, 17 monthly, 5 quarterly, and 1 annually, for an average of 6.3 reports per day. There were many requests for special one-time reports and information. Awards and decorations and computation of combat pay were also continuing requirements. The company operated throughout Vietnam, which required that the company commander be away from the company frequently to supervise operations, coordinate with support units, and be present in the active areas. An executive officer is required to supervise administrative functions and to allow the company commander the freedom of movement that his duties require.

TOE 1-59D, paragraph 01, line 06, authorizes one airplane technical inspector, MOS 679.40, E-6.

During the 6-month evaluation the 61st Aviation Company flew an average of 1,069 hours per month. To support this conthly flying required an average of 11 periodic inspections, 22 intermediate inspections, and 200 daily inspections.

Maintenance data collected during the period revealed that approximately 600 man-hours per month were devoted to the technical inspection portion of scheduled inspections and demand maintenance.

The 600 man-hours per month did not include the other normal duties of the technical inspector, such as:

- 1) Maintaining the technical library, including all changes and modifications to be performed
- 2) Preparing and submitting technical maintenance reports
- Maintaining an equipment improvement recommendations (EIR) file on EIR's submitted by the unit.

No attempt was made to establish the man-hours required to perform these duties. One technical inspector producing 195 man-hours per month could only accomplish something less than one-third of the work required. The remaining two-thirds of inspector duties were performed by platoon sergeants and maintenance supervisors. To provide adequate quality control and to release other maintenance personnel to perform their primary duty, two additional airplane technical inspectors, MOS 672.40, E-5, should be authorized.

b. Operations Section

TOE 1-59D authorizes one ground control approach (GCA) equipment repairman, MOS 282.2, for the maintenance of the GCA radar set AN/TPN-8. In addition to this radar set, the company is authorized one AN/APN-158 (WP-103) weather avoidance radar set and one AN/PX-44 transponder installed as auxilliary equipment on each of the 16 airplanes assigned. There is no maintenance capability for these sets within the company.

Two GCA equipment repairmen cross-trained on the AN/APN-158 weather avoidance radar and the AN/PX-44 transponder would provide the company with sufficient organizational maintenance capability in the operations area.

c. Airplane Sections

(1) Flight Platoon Aviators

With 9 or 10 aircraft committed each day, the flight platoon aviators were required to fly 2 consecutive days with the third off for rest and the performance of additional duties. Since the average flying day is 12 hours, crew rest takes on an added significance in Vietnam. During the 12 hours, an average of 2 missions were flown with 10 landings. An average of four landings were made into strips that required maximum performance from both the crew and aircraft. Enemy antiaircraft fire was received on the average of twice each week. During the monsoon season in the delta region, an average day might consist of 30 minutes of actual instrument flying at low altitude flown under conditions that would be considered uncontrolled by CONUS stariards. A typical 12-hour flying day is indicated below:

Briefing and flight planning	1 hour
Preflight	½ hour
Flight time	5 hours
Ground time in cockpit	2 hours
Lunch break	1 hour
Ground time and supervising loading and unloading	2 hours
Inspection of aircraft for ground fire damage	½ hour
Total	12 hours

The average monthly flying time for aviators of the 61st Aviation Company is shown in figure 18. Total flying time was well within limits recommended by AR 95-17. However, conditions under which they were flown, coupled with an average duty week of 70 hours, must be taken into consideration. TOE 1-59D, paragraphs 03 and 04, provide sufficient aviators to support 1200 flying hours per month and still provide adequate crew rest.


(2) Airplane Section Chief

Each airplane section operates in Vietnam with four flight engineers and four assistants. With a shortage of maintenance supervisors, it was not always possible to assign a section chief to each airplane section; however, an experienced maintenance man, whose primary duty was flight engineer, was designated the section chief and provided the required supervision of personnel and the daily and intermediate inspections.

With aircraft stationed in isolated areas away from maintenance facilities, it was essential that maintenance discrepancies be detected early and corrected before they developed into a grounding condition. One Staff Sergeant (E-6), MOS 672.6, was required to perform the duties of airplane section chief. Since the section chiefs were seldom available, the duties of the section chief had to be performed by the most senior experienced flight engineer.

(3) Assistant Flight Engineer

The 61st Aviation Company provided service to airfields and strips that in most cases did not have facilities for loading, unloading, and manifesting of passengers and cargo. These functions were performed by the US advisory personnel to RVN units that were located at the strips. These isolated advisory teams were serviced by a scheduled courier flight in II, III, and IV Corps. To remain on schedule it was necessary that ground time be reduced to a minimum. It was also essential that the flight engineer perform a thorough inspection of the aircraft for ground fire damage after each flight. To meet these requirements, an assistant flight engineer was placed on all CV-2B's operating in Vietnam. Specifically, he directly supervised the loading and unleading of cargo and passengers, secured the load, and signed for mail, cargo, and other accountable items. He assisted in the servicing of the aircraft after each landing. The assistant flight engineer performed valuable service by aiding the flight engineer in correcting maintenance discrerancies that occurred while the aircraft was away from maintenance facilities. For example, it requires two men to remove an engine cowling. When correcting a maintenance discrepancy in the vicinity of the engine and when no maintenance stand was available, the assistant was invaluable. Assistant flight engineers were provided from company resources. These personnel were selected from all sections of the company.



(U) FIGURE 18. Aviator flying time per month.

The primary justification for an assistant flight engineer was the handling of passengers and cargo so that the flight engineer would be free to inspect and maintain the aircraft at each stop.

d. Service Platoon Headquarters

The 61st Aviation Company found it necessary to have a WO assistant maintenance officer, although one was not authorized by the TOE. Even though the service platoon contains 50 percent of the enlisted personnel of the company and all of the trained specialists, it is authorized only 10 percent of the officer supervisory personnel.

It was necessary to have a day and night shift for aircraft maintenance. It was also necessary to dispatch maintenance crews to outlying airfields to perform demand maintenance. Test flying was a continuing requirement. To provide adequate supervision under these circumstances, an assistant maintenance officer was essential and was appointed from company resources.

e. Maintenance Sections

The 61st Aviation Company was unable to perform the required organizational maintenance to support an average monthly flying hour program of 1,069 hours. The 611th Direct Support Company and the 330th General Support Company, along with the attached 326th Maintenance Detachment, had to provide organizational maintenance support with the result that organic third and fourth echelon capabilities were reduced. Additional aircraft mechanics are required in the service platoon to correct this situation.

Based on six months of statistics taken from maintenance and operational records of the 61st Aviation Company and supporting units, it was determined that 9,899 organizational maintenance man-hours were required per month to support a 1,069 monthly flying hour program at a 67 percent aircraft availability rate. Flight engineers and assistants were normally on flying duty for two consecutive days. The third day was for crew rest or was spent performing daily or intermediate inspections. It must be emphasized that flight engineers and assistants were away from home station with the aircraft on an average of 11 hours a day when performing flight duty. Daily and intermediate inspections performed by the flight engineers accounted for 1,607 man-hours per month. The 16 flight engineers and 16 assistants were not available for other organizational maintenance. In considering maintenance hours available, only those aircraft mechanics and electricians of the service platoon who performed the demand maintenance and periodic inspections were considered. Demand maintenance and periodic inspections accounted for 8,291 man-hours a month.

The service platoon TOE 1-59D made available 6,630 manhours. Productive man-hours per man per month in Vietnam were computed as follows:

Man-hours per man-week Man-weeks per month Total man-hours per month	60.00 <u>× 4.33</u> 260.00
Total man-hours per month Constant factor for productive work	260.00 × 0.75
(Taken from SB 1-2) Total productive hours per man per month	195.00

Man-hours available in the service platoon were computed as follows:

Designation	MOS	Number
Aircraft mechanic	672.30	24
Aircraft mechanic helper	670.00	8
Elec equipment repairman	284.10	_2
	Personnel availabl	e 34
Productive man-hours per man-month		195
Personnel available		× 34
Total productive man-hours	a available	6,630

There was a deficit of 1,662 man-hours per month in the service platoon, computed as follows:

Total organizational maintenance man- hours required	9, 899
Less daily and intermediate inspection	- 1,607
Man-hours requirement for service platoon	8,292
Man-hours available	- <u>6,630</u>
Man-hour deficit	1,662

To enable the Caribou company to perform all of its organizational maintenance and to redirect the field maintenance effort, the

TOE should be augmented by eight aircraft mechanics. Augmentation was computed by dividing one man-month of 195 hours into maintenance deficit of 1,662 man-hours.

2. Equipment

Although much of the TOE equipment has not been used in Vietnam because of the static situation that has existed, it cannot be stated that it will never be used. Should the counterinsurgency operations escalate into a limited or conventional war, the circumstances under which the company has operated could change drastically. Therefore, equipment changes are recommended only where the equipment is deemed unsatisfactory regardless of environment.

a. Operations Section

Trailer-mounted generator set PU-294/G should be replaced by trailer-mounted generator set PU-253/U. The generator is provided to power the AN/TPN-8 GCA radar within the operation section. The GCA radar requires a source that will produce 110/207 volt, 400-cycle, 3-phase, 10-kw power. Generator PU-253/U meets the power requirement. PU-294/G is a 110/200 volt, 60-cycle, 5-kw generator.

Radio-teletypewriter set AN/GRC-46 should be replaced with radio-teletypewriter set AN/MRC-95. This would give the operations section the means for HF single-side-band voice communications with all aircraft that are equipped with the AN/ARC-102 HF single-side-band radios.

The AN/TRC-42 VHF radio set should be provided in the operations section for any aviation company employed in an overseas theatre. VHF is the standard air-to-ground communications for air traffic control worldwine. Inclusion of the VHF radio in the operations section would allow the air traffic control facilities of the company to be fully integrated with, and complement, the existing civilian facilities. The VHF radio would also provide the company with an alternate air-to-ground communications link with organic aircraft.

b. Service Platoon

The tool set, organizational maintenance, Army sircraft set C, is set up with a tool density in increments of three and does not provide sufficient tools for the four aircraft maintenance sections.

In addition, set C does not contain floodlights essential for night maintenance. An organization maintenance tool set should be designed specifically for the CV-2B aircraft. It should eliminate unnecessary tools found in the standard sets and include any special tools designed specifically for the CV-2B.

One such tool set is now undergoing tests with the 11th Air Assault Division. If adopted, it should replace set C now authorized. As an interim measure, the C set could be replaced by two each tool sets, organizational maintenance, Army aircraft, set A and set B; and one shop set, ground handling and servicing, field maintenance, Army aircraft, set A. This combination of tool sets gives sufficient tool density and provides floodlights for night maintenance.

c. Special Equipment

(1) Engine Maintenance Stand


The performance of periodic and intermediate inspections, engine repair, and sheet metal repair were hampered by inadequate maintenance stands. With the standard maintenance stand (figure 19), it was necessary to use two stands to work on one engine and mechanics wasted valuable time dismounting from one and mounting the other. Dropped tools generally bounced off the stand, resulting in more wasted time to recover them. The metal floor of the standard maintenance stand was often wet and slippery during the monsoon season and created a safety hazard. A maintenance stand for the engine section of the CV-2B should be U-shaped, have a safety railing, a skid-proof floor that protrudes three inches beyond the railing, and should allow for the installation of a detachable top for protection from sun and rain. The detachable top should be able to withstand winds up to 25 knots. During conditions of higher wind velocity, little maintenance is performed outside. Retractable wheels, similar to the ground handling wheels for the UH-1B helicopter, would permit towing. Figures 20 and 21 show a type of Ushaped maintenance stand that would fulfill this requirement.

(2) Hoist


A thorough inspection and maintenance of the vertical stabilizer, rudder, horizontal stabilizer, and elevators was practically impossible using the hoist in the shop set C. Inspections were made by jacking up the nose wheel as far as possible thereby lowering the tail. By using the hydraulic stand, the inspector was able to make a partial visual inspection. However, the stand was too low to permit a thorough inspection. In order to lubricate the piano hinges of the elevator trim tabs, a mechanic had to walk on the horizontal stabilizer. He climbed up the hoist from the C set to lubricate the rudder trim and to change the anticollision light. A fall from this height could be fatal. Figure 22 shows the hoist used by the 61st Aviation Company. Figure 23 shows the Abbey hoist, manufactured by the Abbey Corporation in Australia and used by the Royal Australian Air Force in Vietnam. The Abbey device is battery-powered, hydraulically-activated, trailer-mounted and airtransportable by C-130 aircraft. The batteries are rechargable. The lift capacity is 600 pounds. The Abbey device allows inspection and maintenance of the entire tail section. It is controlled by the mechanic on the work platform.




(U) FIGURE 19. Standard maintenance stands.




(U) FIGURE 20. Proposed maintenance stand (side view).





(U) FIGURE 22. Standard maintenance hoist.



(U) FIGURE 23. Abbey hydraulic hoist.

The Australian Air Force has on order another device which will not only perform the above functions, but additionally can tow aircraft, lift an engine and propeller assembly, load and unload aircraft, and provide a general purpose stand. This device, a Hyster Fork Truck, manufactured by the Hyster Corporation in Australia, costs approximately \$36,000. Both Abbey and Hyster are American corporations with plants in Australia. Either of these devices would meet the stated requirements for a safe and efficient hoist.

4. Conclusions

- a. TOE 1-59D, dated 27 March 1964, Aviation Company (Airmobile Fixed Wing) does not provide adequate command, control, and maintenance personnel and equipment for counterinsurgency operations.
- b. Since the aviation company (airmobile fixed wing) has the capability to establish and operate a company airfield, the AN/TRC-42 VHF radio should be included in the equipment for the operations section. This would permit the company to tie in with existing civilian air traffic control facilities.
- c. A maintenance stand designed specifically for the engine section of the CV-2B would expedite daily, intermediate, and periodic inspections and demand maintenance.
- d. A hoist platform similar to the Abbey or Hyster device provided at each airfield where CV-2B maintenance is performed would expedite maintenance on the tail section and eliminate a serious safety hazard.


D. '(U) OBJECTIVE 4 - LOGISTICS

The 61st Aviation Company was located adjacent to the 611th Direct Support Maintenance Company (DS) and the 330th General Support Company (GS) at Vung Tau. The advantage of being next door to maintenance backup and aircraft supply was exploited to the fullest. With the aircraft maintenance facilities co-located, time expended in processing work orders and requisitions was reduced to a minimum.


1. Aircraft Maintenance

a. Organization

The organic maintenance personnel of the Caribou company performed first and second echelon maintenance, and the attached 326th Maintenance Detachment performed third echelon maintenance. The 326th Maintenance Detachment and the 61st Aviation Company maintained separate maintenance facilities. Work orders were submitted for all maintenance requests. Figure 24 shows the maintenance flow. The service



一大学の大学を大学をあるというというないのでは、これではなっていることで



(U) FIGURE 24. Maintenance flow.

platoon leader of the 61st Aviation Company was the unit maintenance officer, but did not exercise any control over the attached maintenance detachment. Work orders were used to request maintenance and supply actions.

For maximum effectiveness, aircraft maintenance must be programmed. During peacetime conditions this does not present a problem. In Vietnam the operational requirements dictated by the tactical situation were the major factors influencing the hours flown and when they were flown. The company commander had the authority to switch aircraft as he desired; however, this did not prevent a maintenance backlog from developing because all available aircraft were flown each day. At times there were aircraft down for a periodic inspection with no maintenance crew available to perform the work. To keep the maximum number of aircraft flyable, the DS and GS companies accepted Caribou for periodic inspection, although this is a unit function. All maintenance units, irrespective of schelon, worked together to reduce the backlog.

Programming and coordinating maintenance to support tactical operations presented a continuous challenge to the unit maintenance officer. Operational considerations often took precedence over maintenance and a temporary backlog was the result.

b. Float Aircraft

During the first three months of the evaluation there were seven float CV-2B's in Vietnam. Of these seven, five had extensive crash damage. Two of the crash-damaged aircraft were placed on commercial contract with Air Vietnam for repair. One was delivered to Air Vietnam in May 1963 and returned 14 months and approximately 12,000 manhours later. The other was delivered to Air Vietnam in November 1963 and was completed 11 months and approximately 12,965 man-hours later. Thirteen months were required by the 611th DS Company to return a third crash-damaged aircraft to service.

The 330th General Support Company was repairing the remaining two damaged aircraft as of 31 October 1964. One had been down approximately one year; the other six months. Crash-damaged aircraft requiring extensive repair reduced the number of effective float aircraft by 70 percent during the first half of the evaluation period. Three new float aircraft arrived in RVN in August 1964, which raised the number of flyable float aircraft to five. The five aircraft that were provided for the out-of-country classified assignment were dropped from the 61st Aviation Company property book on 2 September 1964 and four of the float aircraft were assigned to the company for incountry support, temporarily reducing the number of flyable floats incountry to one.

c. Aircraft Availability

Figure 25 shows the aircraft availability rate by month for the period of this evaluation.

Figure 26 shows the average number of aircraft available each day and the number actually used. All available CV-2B's were flown every day during the 6-month evaluation period, with the exception of the few days when weather prevented flight.

Operational requirements did not permit holding down air-craft for maintenance. Each aircraft was inspected after each day's operations, and maintenance was performed nightly to prepare the aircraft for the next day. All maintenance, except that which was absolutely essential, was deferred to the next periodic inspection.

d. Scheduled Inspections


There were 77 normal periodic inspections (PE) performed during the 6-month evaluation period. Figure 27 shows the number of man-hours by echelon for a normal periodic inspection. The inset in figure 27 shows the average man-hours expended on each PE per month. (The tenth PE, a major inspection, is not included.) A normal PE averaged 546.8 man-hours and 11.4 days for completion. A shortage of aircraft mechanics, MOS 672.3, was the primary delaying factor.

A tenth periodic inspection averaged a total of 2,392.5 man-hours. More significantly, the downtime for a tenth PE averaged 28.7 days. There were 6 tenth periodic inspections completed during the evaluation period. There was a noticeable reduction in downtime for the tenth PE toward the end of the evaluation period. The first 3 tenth PE's averaged 40.6 days downtime; the last 3 averaged 16.3 days. This was a result of the reduction in the maintenance backlog.


Intermediate inspections after every 50 flying hours required approximately 100 man-hours. The aircraft were down for an average of 12 days.

Daily inspections required three hours. However, a maintenance team met each aircraft on its return from the day's operation and performed all of the maintenance necessary to place the aircraft in a flyable status for the next day.


Deficiencies that were not a grounding condition were deferred until the next periodic inspection. However, demand maintenance constituted 34.5 percent of the total man-hours expended on organizational maintenance. Figure 28 shows demand maintenance performed by the organizations during the evaluation. The drop in man-hours expended in demand maintenance in October 1964 was caused by




(U) FIGURE 25. CV-2B availability rate by month.



(U) FIGURE 26. Average daily CV-2B availability and utilization.



(U) FIGURE 27. Han-hours expended by easelon for normal periodic inspections.



(U) FIGURE 28. Man-hours expended by unit on demand maintenance.

the advisant allow of civilian maintenance personnel which reduced the demand-dintensace backlog that had accumulated until September 1964.

e. Crash Damage

To place crash-damaged aircraft into service, the commanding officer of the 765th Transportation Battalion requested a team of civilian sheet metal and aircraft repairmen to augment the 330th GS Company for a period of 90 days. This team of 12 sheet metal men expended 3,448 man-hours during the 90 day period in returning two Caribou to service. Two of the civilians voluntarily extended 30 additional days and three for an additional 60 days.

f. Battle Damage

Damage sustained as a result of enemy ground fire placed an insignificant work load on the sheet metal repairmen of the 326th Maintenance Detachment. Figure 29 shows the number of man-hours expended on repair of battle-damaged Caribou.

g. Reversible Pitch Propeller Modification


The reversible pitch propeller modification was accomplished on all 61st Aviation Company aircraft from 20 June to 8 October 1964. A team of 14 civilian technicians from De Havilland Corporation, and 4 from Hamilton Standard arrived in Vung Tau on the 20th of June to perform this modification. The installations were for the most part completed during a periodic inspection. However, three aircraft were held down specifically for the modification. Downtime averaged 18.2 days with an average of 958.4 man-hours expended for each modification.

h. Engine Replacement

From 1 May to 31 October 1964, 25 R-2000-7M2 Pratt and Whitney airplane engines were replaced. The rated life for the R-2000-7M2 engine is 1500 hours. Records available on 14 engines indicated that the average life of the engines in Vietnam was 583 hours or 32 percent of the rated life. Extensive oil consumption and defective impeller seals were the most common cause for the engine changes.

2. Other Maintenance

Backup maintenance for all equipment, less aircraft, was located at Tan Son Nhut Airport near Saigon. Equipment for repair was shipped by air to the supporting maintenance shop. If extensive repair was required, the item was further evacuated to Okinawa by surface or air transportation. The static situation under which the 61st Aviation Company operated presented little opportunity to use much of the organic equipment under field conditions. The few vehicles and



(U) FIGURE 29. Man-hours expended on battle-damaged Caribou.

JUL

JUN

generators that were down for parts or maintenance for an extended period had no effect on the ability of the unit to perform its mission. One bonus of this static situation was that assigned vehicle drivers, many of whom were also qualified aircraft mechanics, were not habitually required for vehicle maintenance and were thus available for aircraft maintenance. The majority of the TOE equipment was, in effect, in temporary storage, which required only that it be exercised periodically and that scheduled maintenance be performed.

3. Supply

a. Aircraft

The technical supply function of the 61st Aviation Company was performed by the attached 326th Transportation Detachment. Requisitions for supplies were prepared by the 61st Aviation Company on DA Form 979, Parts Request, which was authenticated by the company maintenance officer and hand-carried to the technical supply of the 326th located in the adjacent hangar. If parts were not in stock at the 326th, then the 326th prepared a DA Form 1546, Parts Requisition, which was hand-carried to technical supply in the direct support unit (DSU) of the 611th Direct Support Company. Parts were issued immediately if available. Total time to complete a supply action from the 61st Aviation Company through the 326th to the DSU averaged approximately one hour.

If a part was not available at the DSU, the requisition was mailed to the Army Consolidated Supply Point (ACSP) at Tan Son Nhut Airport. Requisitions not filled at the ACSP were teletyped to the Consolidated Supply Point, United States Army, Pacific, located on Okinawa. From there the requisitions not filled were electronically transmitted to the Inventory Control Point in Hawaii where they were either filled out of USARPAC stock or further transmitted to the National Inventory Control Point in St. Louis. Figure 30 shows the requisition channels.

During the evaluation there were 215 code 02, equipment down for parts (EDP) requisitions submitted. Aircraft downtime as a result of EDP's is shown in figure 31. This information was extracted from DA Forms 1352 submitted by the 61st Aviation Company. Figure 32 shows the number of EDP's by month and average fill-time during the evaluation. The average fill-time was 5.5 days. Transfer of parts between aircraft was a common practice by both the 61st Aviation Company and their backup maintenance units. The urgency of the tactical situation and the continuing demand for the maximum number of CV-2B's dictated this practice.

Requisition experience for code 05 (anticipated EDP), code 12 (normal replacement of special equipment), and code 17 (requisition for normal stockage replacement) is show in figures 33, 34, and 35, respectively.

b. Other Supply

The 61st Aviation Company was the carrier unit for four small detachments located in Vung Tau, maintained their property books, and initiated requisition action. Although there were delays in receiving EDP's for vehicles, there was no effect on the mission acceptable.


4. Petroleum, Oil, and Lubricants (POL)

POL products and dispensing facilities were available throughout Vietnam at 52 airfields. It was possible, with the range of the CV-2B, always to plan for refueling at an airfield that had adequate facilities.


POL was supplied to all airfields by Vietnamese civilian contractors. The civilian tankers were able to move freely throughout Vietnam without serious interference from the Viet Cong. Military vehicles did not have this freedom of movement. If the Viet Cong were to stop the movement of civilian tankers, a serious POL resupply problem would result in Vietnam.

5. Facilities


The administrative and maintenance facilities available to the




(U) FIGURE 30. Requisition channels (code 52).




(U) FIGURE 31. Number of days CV-2B's were grounded for parts.




(U) FIGURE 32. Code 02 requisition data.






(U) FIGURE 33. Code 05 requisition data.





CODE 12 REQUISITIONS SUBMITTED AND FILLED PER MONTH




DAYS FILL-TIME PER MONTH

(U) FIGURE 34. Code 12 requisition data.





CODE IT REQUISITIONS SUBMITTED AND FILLED PER MONTH



(U) FIGURE 35. Code 17 requisition data.

61st Aviation Company at Vung Tau were comparable to airfield facilities in CONUS. Figure 36 shows an aerial view of the Vung Tau facilities. Barracks, orderly room, supply room, company operations, communications, motor pool, and aircraft maintenance and supply were all located in weatherproof buildings. Heat, prevalent throughout the year, and torrential rains during the wet season, made a shelter essential for both vehicular and aircraft maintenance. A corrugated iron hangar, completely open on one side, fulfills the requirement in Vietnam. Usually there was no requirement to displace units, and a semi-permanent shelter was adequate. Storage space, parts bins, and office space were all included in the shelter, leaving adequate space and protection for extended maintenance operations. Semi-permanent aircraft maintenance shelters for other aircraft (UH-1B, O1A, U-6A, U1A) were provided. All unit commanders interviewed stated a preference for the semi-permanent shelter. There was no requirement for a portable, mobile CV-2B maintenance hangar in Vietnam. A sheltered maintenance stand is, however, required.

6. Conclusions

- a. Maintenance resources in Vietnam, both military and civilian, were unable to repair CV-2B aircraft with extensive crash damage in a reasonable length of time.
- b. Aircraft maintenance man-hours expended on repair of battle damage sustained by CV-2B aircraft has been insignificant when considering the overall man-hours expended.
- c. Rebuilt R-2000-7M-2 engines did not attain programmed life expectancy in Vietnam.
- d. EDP rate in Vietnam for CV-2B aircraft was above the DA goal even though there was extensive lateral transfer of parts.
- e. A semi-permanent maintenance hangar proved adequate for the CV-2B in Vietnam.
- E. (U) OBJECTIVE 5 NAVIGATION AND COMMUNICATION EQUIPMENT

Aircraft in Vietnam fly under both civil and military air traffic control. Tactical operations and support of the ground effort are under military control. Objective 5 is concerned only with tactical operations.

1. Navigational Facilities in Vietnam

Navigation and communication facilities in the delta region of III and IV Corps were adequate. The relatively flat area resulted in maximum reception distance, and missions were accomplished without



61st Avn Co

326 th Trans Det

611th DS Co

330th GS Cc

(U) FIGURE 36. Facilities at Vung Tau Airfleld.

765 th 5 4 t 15 c f difficulty during year-round weather conditions. However, in the mountain and plateau areas of I and II Corps, navigational aids were of little value at low level. Navigation under minimal conditions was accomplished almost entirely by pilotage. The maneuverability and performance of the Caribou permitted nap-of-the-earth flying in deep valleys which had abrupt changes in direction and elevation. Mission aborts because of weather were infrequent.

a. Automatic Direction Finder (ADF) and Visual Omni Range (VOR)

There were 19 ADF stations located throughout South Vietnam which provided approximately 50 percent coverage of the country at altitudes below 2500 feet. These stations proved to be invaluable for low-level navigation under marginal weather conditions.

There were 3 VOR stations in Vietnam, which provided assistance for low-level navigation in approximately 20 percent of the Republic. Figure 37 shows the location of all ADF and VOR stations in RVN.

b. Ground Control Intercept


The US Air Force operated five ground control intercept (GCI) radar facilities in Vietnam, which provided positive flight-following in approximately 80 percent of Vietnam. Figure 38 shows the location of radar facilities in RVN including airfields with a ground control approach (GCA) radar. These facilities proved to be invaluable during both dry and wet seasons, not only in providing flight-following, traffic, and weather information, but also in vectoring aircraft to isolated airfields that had no navigation or communication facilities. Many missions were accomplished only because GCI was able to vector the aircraft to its destination. The APX-44 radar transponder was essential for radar contact at low level.

c. Tactical Air Navigation (TACAN)


The US Air Force operated six tactical air navigation facilities in Vietnam. Figure 37 shows the location of TACAN facilities in RVN. The Caribou used in the evaluation were not equipped with TACAN receivers.

2. Low-Level Navigation

During the monsoon season, lasting about six months each year, low-level navigation takes on added significance in Vietnam. Resupply of isolated US advisor teams, outposts, and special forces strike force sites was possible only by air in most cases, since travel by road was an invitation to ambush by the Viet Cong. Low-level navigation procedures in Vietnam consisted of standard US Army procedures modified to meet the conditions of enemy, weather, and terrain peculiar to the RVN.



(U) FIGURE 37. Navigation facilities in RVN.



(U) FIGURE 38. Ground control facilities in RVN.

Radar, VOR, and ADF beacons were used whenever possible to aid in navigation. When ceilings permitted contact flying at 2,500 feet or above, navigation by pilotage was relatively simple once the pilots became familiar with the tactical maps and the area of operations.

Nap-of-the-earth flying, using normal contact flying procedures, was frequent in the I and II Corps zones as a technique for avoiding ground fire. The broken terrain and dense vegetation concealed the air-craft from ground observation. Prominent valleys and rivers simplified navigation. ADF and VOR was of little assistance during nap-of-the-earth flying because the mountains interfered with reception at the low altitude.

In the III and IV Corps zones where most of the terrain was flat, nap-of-the-earth flying was avoided because the Caribou could be detected in sufficient time for the VC to bring effective antiaircraft fire to bear at near maximum ranges. During contact conditions the Caribou seldom flew below 2,500 feet. They were flown in and out of the base of the clauds when ceilings were down to about 1,000 feet. This technique allowed the aviator to maintain his course by visual reference to the ground and afforded maximum protection from ground fire.

When the ceiling was below 1,000 feet the Caribou normally flew in the clouds using navigational aids available to assist in time-distance navigation. After flying the computed time to the destination airstrip, aviators let down, using their altimeters, to visual flight conditions. In the flat delta area, 200 feet above the terrain was considered the minimum safe altitude before aborting the letdown. After letdown the aviator then used pilotage to locate the airstrip. This procedure was used only when the aviator was familiar with the terrain.

When visibility was less than a mile and the ceiling 200 feet, it was difficult to locate landmarks. With no air-to-ground communication or navigation aids, Caribou were unduly exposed to ground fire while the crew searched for an airstrip. Dead reckoning under actual instrument conditions, followed by a letdown without navigation facilities, was found to be accurate to within two minutes of planned ETA. lack of a positive navigational aid, however, caused as much as 10 minutes delay in locating isolated airstrips.

The HRT-2A and HRS-8 terminal guidance beacons have been evaluated by the Advance Research Projects Agency (ARPA) in Vietnam. Accuracy of the HRT-2A and HRS-8 beacons as navigational aids was excellent for locating isolated airstrips. A type of terminal guidance beacon similar to those evaluated by ARPA would make a significant improvement in low-level navigational procedures.

3. CV-2B Electronic Equipment

The electronic equipment installed in CV-2B's in Vietnam

provided adequate communication and navigation in all areas of Vietnam. Figure 39 shows the electronic configuration of the CV-2B's assigned to the 61st Aviation Company. Differences in installation were minor, except for weather avoidance radar which was installed in only three of the Caribou.

a. FM (AN/ARC-44)

All CV-2B in Vietnam were equipped with the AN/ARC-44 radio. It was used primarily for air-to-air and air-to-ground communication with tactical units. Air-to-ground communication was reliable with digitally tuned ground radios. Difficulty was experienced, however, in establishing air-to-ground communications with the AN/PRC series of radios with continuous tuning. These radios were often miscalibrated and the operators were unable to tune accurately to the assigned frequency. Frequently paradrop and low-level extractions had to be executed without radio contact after visually determining that the drop zone was secure. If radio contact was not made, most special forces camps would mark the drop zone with smoke when the aircraft arrived over the drop zone. Although the VC had FM radios, there were no cases where they interfered with the communications of the 61st Aviation Company. An FM frequency was available in all US Army control towers. The AN/ARC-44 was reliable within stated capability.

b. UHF-VHF (AN/ARC-55 - AN/ARC-37)

The VHF and UHF radios were the primary radios used for air-to-ground communications with control towers, GCI facilities, GCA stations, approach control and civil aviation facilities. The radios proved reliable and effective in all areas of Vietnam. The long range of the sets is particularly valuable in Vietnam where there were great distances between GCI stations.

c. Single-side-band (ARC-102)

The Caribou of the 61st Aviation Company flew missions throughout Vietnem. The only radio with sufficient range to communicate from any location and at any altitude was the single-side-bandhigh frequency (HF) set. Although the majority of the missions were in range of UHF and VHF stations, mountain operations required the use of HF for constant communications with flight-following facilities. The 61st Aviation Company operated a high frequency radio net during all operational hours. This communication capability was particularly valuable when maintenance problems developed in areas remote from the maintenance facilities. Administrative information and instructions were also passed on this net.

d. AN/ANP-156 Weather Avoidance Radar (WP-103)

There were three weather avoidance radars installed in

				— т	
	1	- 1		1	1
	1	I		l	- 1
4 4					1
OB WA					1
diff of					
143 0					
1 20 3					į
186					
10 14 1 10					
Son May to Cong	×	×	×	×	×
ANONE RICE STREET STREE	×				
12/3/02/	×				
130 06 10					
41 / 42 / 45 / 20 ch	×	×	×	×	×
SILING SI	×	×	×	×	×
	×	×	×	×	×
(1) 30 36 36 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	×	×			
130 00 10 10 10 10 10 10 10 10 10 10 10 10	×	×	×		
1. 47.5 34.1	×	×	×	×	×
3 3 3 12 18					
18 18 18 18 18 18 18 18 18 18 18 18 18 1	×	×	×	×	×
138438 8 388 NA	×	×	×	×	
1384343 8 388 NA 138434 8 388 NA 13843 NA	×	×	×	×	×
	873	4	7	4	ю

THE PARTY OF THE P

CV-2B electronic configuration, 61st Aviation Company. (U) FIGURE 39.

aircraft of the 61ct Aviation Company during the evaluation. Weather avoidance radar was universally praised by US Army aviators. During the monsoon season the AN/ANP-158 enabled the aircraft to penetrate squall lines and heavy rainshowers, avoiding areas of thunderstorms. Night flights were made into areas of severe weather with confidence since the AN/ANP-158 clearly differentiated areas of thunderstorms and areas of heavy rain. It was particularly valuable during low-level flying under instrument conditions.

4. Maintenance

The 258th Signal Detachment was organized under TOE 11-500D and was authorized one officer and six enlisted men. The detachment had facilities for repair of the following equipment installed in the Caribou:


- a) AN/ARN-30D (VORNAV) (OMNI)
- b) AN/ARN-59 (ADF REC)
- c) J-2 Gyro Compass System
- d) T-366 (VHF Emer)
- e) AN/ARC-102 (HF)
- f) AN/ANP-158 (WP-103) (Repaired only by the Collins Radio Corporation's technical representative.)

The AN/APX-44 radar transponder was maintained by the 255th Signal Detachment (Avionics) at Tan Son Nhut Airport.

Avionics discrepancies were corrected by a system of direct exchange. Figure 40 shows the number of work orders accomplished for the CV-2B of the 61st Aviation Company. On the average, one man-hour was expended on each work order, which was the time required to replace the defective equipment. The equipment lost its identity after removal. When repaired it was placed in float stock. This system of direct exchange reduced aircraft downtime attributable to avionics maintenance. A Caribou company operating independently requires an attached avionics detachment with adequate float stock. Twenty percent float stock has provided adequate support for the CV-2B operation in Vietnam.

5. Supply

Avionics supply was satisfactory throughout the evaluation period. FDP's did not affect the aircraft since they were all filled from float stock. The requisition experience attributed directly to the electronics equipment installed in the CV-2B of the 61st Aviation Company is shown in figure 41.




(U) FIGURE 40. Signal work orders.

6. Conclusions


- a. The AN/ARC-102 (HF) provided the Caribou with an extended communication capability at low altitude from distant locations in Vietnam.
- b. The AN/ANP-158 weather avoidance radar was especially valuable during the monsoon season in Vietnam.
- c. A portable terminal guidance beacon similar to the HRT-2A and HRS-8 located at airfields without navigation facilities would reduce exposure and turnaround time for CV-2B aircraft operating during periods of low ceilings and reduced visibility.
- d. Air-to-ground FM communications were frequently unsatisfactory because of the inability of the operators of the AN/PRC series of radios to tune these radios accurately to the assigned frequency.
- e. Aircraft downtime attributable to defective communications and navigation equipment was negligible.








CODE 02 AVIONICS PARTS REQUISITIONS



CODE OS AVIONICO PARTO LIVERSTEINS



CODE 12 AND 17 Andrew miner to the contract of

RECOMMENDATIONS

A. GENERAL CONCLUSIONS

- 1. The CV-2B Caribou, under the operational control of the corps senior advisor, special forces, or USOM provided essential support to the counterinsurgency α existion in Vietnam.
- 2. Low-level extraction from the CV-2B is an efficient and economical means of aerial resupply.
- 3. TOE 1-59D, dated 27 March 1964, Aviation Company (Airmobile Fixed-Wing), requires augmentation to support CV-2B (Caribou) counterinsurgency operations.
- 4. Logistical resources, less rebuild facilities, necessary to support CV-2B counterinsurgency operations in Vietnam were available incountry; the organizational maintenance capability available in the 61st Aviation Company was inadequate.
- 5. Limited rebuild facilities precluded repair of aircraft with extensive crash damage in a reasonable length of time.
- 6. The electronic configuration of the CV-2B provided an adequate communication and navigation capability for counterinsurgency operations in Vietnam.
- 7. A portable terminal guidance beacon is necessary to reduce exposure time at isolated airfields and drop zones.

B. SPECIFIC CONCLUSIONS

TO A MARIE AND THE AREA OF THE THE PROPERTY OF THE PROPERTY OF

- 1. CV-2B's allocated to each corps and operating under the operational control of the corps senior advisor provided a flexible and responsive means of accomplishing the aerial movement of personnel and supplies in the corps forward areas.
- 2. CV-2B qualified aviators arriving in Vietnam received a comprehensive area checkout and required flight instruction in STOL procedures before they were released for operational missions.
- 3. One CV-2B allocated for training would expedite the operational checkout of aviators and provide a more effective unit standardization program.
- 4. The CV-2B was able to airland supplies to special forces camp sites that were previously resupplied only by paradrop.

- 5. In areas where it can be used, the DLEX method of aerial delivery of supplies was more efficient and economical than the paradrop technique.
- 6. LOLEX was the most accurate air delivery technique used by the CV-2B aircraft in Vietnam.
- 7. The CV-2B STOL characteristics and LOLEX capability provided 5th Special Forces Group with flexibility in selecting the most effective method for aerial delivery of supplies to isolated camp sites and patrol bases.
- 8. TOE 1-59D, dated 27 March 1964, Aviation Company (Airmobile Fixed-Wing), does not provide adequate command, control, and maintenance personnel and equipment for counterinsurgency operations. (See annex E.)
- 9. The AN/PRC-42 VHF radio would permit the company to tie in with existing civilian air traffic control facilities.
- 10. A maintenance stand designed specifically for the engine section of the CV-2B would expedite daily, intermediate, and periodic inspections, and demand maintenance.
- 11. A hoist platform similar to the Abbey or Hyster device provided at each airfield where CV-2B maintenance is performed would expedite maintenance on the tail section and eliminate a serious safety hazard.
- 12. Using military and civilian maintenance resources in Vietnam, approximately one year was required to repair CV-2B aircraft with extensive crash damage.
- 13. Aircraft maintenance man-hours expended on repair of battle damage sustained by CV-2B aircraft was insignificant when considering the overall man-hours expended on all types of maintenance.
- 14. Rebuilt R-2000-7M2 engines attained only 32 percent of programmed life expectancy in Vietnam.

- 15. EDP rate in Vietnam for CV-2B aircraft was above the DA desired goal even though there was extensive lateral transfer of parts. (See figure 31.)
- 16. A semi-permanent maintenance hangar proved adequate for CV-2B in Vietnam.
- 17. The AN/ARC-102 (HF) provided the Caribou with an extended communication capability at low altitudes from distant locations in Vietnam.

- 18. The AN/ANP-158 (WP-103) weather avoidance radar was especially valuable during the monsoon season in Vietnam.
- 19. A portable terminal guidance beacon similar to the HRT-2A and HRS-8 located at airfields without navigation facilities would reduce exposure and turnaround time for CV-2B aircraft operating during periods of low ceiling and reduced visibility.
- 20. Air-to-ground FM communications were frequently unsatisfactory because of the inability of the operators of the AN/PRC series of redicate to tune these radios accurately to the assigned frequency.
- 21. Aircraft downtime due to defective communication and navigation equipment was negligible.

C. GENERAL RECOMMENDATIONS

- 1. The technique of placing the CV-2B under operational control of the supported units should be considered as the normal means of control in a counterinsurgency situation.
- 2. The low-level extraction technique should be adopted by the US Army as a standard aerial delivery method.
- 3. TOE 1-5 , dated 27 March 1964, Aviation Company (Airmobile Fixed-Wing) should be augmented with additional personnel and equipment for counterinsurgency operations. (See annex E.)
- 4. CV-2B aircraft with extensive crash damage should be evacuated to an established rebuild facility for repair.
- 5. A portable terminal guidance beacon should be adopted as standard equipment for use at remote airfields and drop somes without navigational aids.
- 6. Specifications and standards of quality control for rebuilt R-2000-7M2 engines should be examined by appropriate CONUS agencies with the view of determining how programmed life of the engine can be attained.

D. SPECIFIC RECOMMENDATIONS

- 1. CV-2B aircraft should continue to operate under the operational control of the supported unit or agency.
- 2. Four CV-2B aircraft should be allocated to the 5th Special Forces Group, Vietnam.
- 3. One CV-2B should be allocated to the 61st Aviation Company for unit training.

- 4. TOE 1-59D, dated 27 March 1964, should be augmented as indicated in annex E.
- 5. The installation of the WP-103 weather avoidance radar and the AN/ARC (HF) radio on all CV-2B's in Vietnam should be expedited.
- 6. A portable terminal guidance beacon similar to the HRT-2A and HRS-8 should be issued to advisor teams and special forces teams in Vietnam for use at airfields and drop zones without navigational aids.

(U) ANNEX A

ENEMY, WEATHER, AND TERRAIN

The enemy, weather, and terrain represent three uncontrollable factors that influence Caribou operations in Vietnam.

1. ENEMY

As of 31 July 1964 the Viet Cong (VC) main force strength was estimated at between 31,000 and 32,000 with an additional 60,000 to 80,000 guerrilla force. The present organization was built around thousands of well-trained cadre personnel who infiltrated from North Vietnam during 1961 and 1962.

Extracts of captured documents and reports of interrogation of captured VC have revealed that VC personnel infiltrating from North Vietnam have received training in the use of small arms against airplanes and helicopters. Their training also included orientation on certain automatic antiaircraft weapons. Captured documents and interrogation reports in late 1962 and early 1963 revealed that specific and detailed training and technical literature on antiaircraft tactics and techniques were being written and disseminated to all echelons in the VC organization. Subjects included aircraft detection and identification; passive measures such as camouflage, fortifications, and air alert procedures; antiaircraft firing by rifles, automatic rifles, and machineguns; and defense against heliborne attacks.

Statistics on reported antiaircraft incidents indicate that the impact of this training effort was not felt for several months. The probable cause of this was the delay in the implementation of this training at individual and small-unit level.

There have been some reports that the VC have a small number of large caliber antiaircraft weapons. The very nature of their overall tactics, however, discourages the use of these heavier weapons unless their future plans call for larger scale operations. There have been no aircraft hits received to date in the RVN from larger than caliber .50 machineguns.

The best in elligence estimates predict that VC antiaircraft doctrine will remain basically the same unless the overall effort is escalated into larger scale conventional warfare operations.

2. WEATHER

The weather in the Republic of Vietnam (RVN) is largely determined by two seasonal monsoons and the effects of the topography on these winds. Frontal systems are infrequent and have little effect on the weather over RVN. (See figure A-1.)

The northeast monsoon occurs from mid-November to mid-March and brings to most of the country lower humidity, less cloudiness, and lower temperatures. All regions, except the lowlands of the eastern coast, experience clear to partly cloudy skies most of the time, producing favorable flying weather.

The spring transition period from mid-March to mid-May brings maximum temperatures and increasing humidity and thunderstorm activity to all of RVN except over the coastal lowlands.


The southwest monsoon blows from mid-May to early October. This puriod is characterized by low clouds, heavy showers, and thunderstorms in the afternoon and evening. Fairly stable tropical temperatures and high humidity prevail over most of the area. The eastern coastlands experience relatively little cloudiness and precipitation since they are protected from the prevailing flow by the Chaine Annamatique or the interior highlands.

The autumn transition occurs from early October to mid-November. The change from southwest to northeast flow is often abrupt. This period normally sees an increase in thunderstorm activity in some locations, but in general, marks the beginning of a decrease in cloudiness and precipitation, except over the eastern coast where the changing airflow results in an onshore, up-slope flow on the eastern slopes of the interior highlands.

A pronounced topographic influence on the weather is caused by the <u>Chaine Annamatique</u>. This chain of mountains and plateaus is oriented perpendicular to the monsoonal winds. During the southwest monsoon, the lifting action of the interior highlands produces more instability which increases the cloudiness and shower activity over the entire country except the eastern coastlands. During the northeast monsoon, this influence is reversed, producing poor flying weather in all other regions.


3. TERRAIN

South Vietnam is composed of three major terrain areas: the high-lands and plateaus in the north and central portion, the coastal plains or central lowlands, and the delta plain of the south (figure A-2).



(U) FIGURE A-1. Annual Precipitation.

ANNEX A



(U) FIGURE A-2. Major topographic regions of South Vietnam.

ANNEX A

The northern two-thirds of the country is dominated by the highlands region which consists of broken mountain chains and rugged hills. The area is sparsely populated, mainly by primitive, nomadic tribes.

The coastal plain (central lowlands) is an irregular narrow strip of sandy beaches and dunes, backed up by rice paddies and marshes. The plain varies from 10 to 25 miles in width, and extends from the northern boundary to the delta plain in the south. The plain is interrupted in several places by mountain chains that jut into the sea, dividing the lowlands into several compartments. This narrow strip contains several small cities and numerous heavily populated areas.

In the central position of the country the rugged mountains give way to an extensive plateau area characterized by more gently rolling terrain dotted with dense tropical forests and jungles. This region is more heavily populated than the mountainous regions and has more roads and trails.

A vast delta plain constitutes the southern one-third of the country. This area contains a dense network of rivers, streams, and unfordable canals. The area is characterized by marshes, rice paddies, and extensive mangrove swamps in the southwestern portion. The delta region is the ricebowl of the country and is heavily populated, with the largest concentration in the Saigon-Cholon area.

THIS PAGE NOT USED

(U) ANNEX B

MISSION NARRATIVES

This annex contains narratives of representative missions flown by the CV-2B's of the 61st Aviation Company in Vietnam during the evaluation. The mission reports are on file at the 61st Aviation Company.

ACTIV evaluators or the project officer were crew members on three of the four missions described.

Ъ. . .

Att_i

NARRATIVE DESCRIPTION OF A PARADROP MISSION IN SUPPORT OF SPECIAL FORCES IN VIETNAM

The special forces "B" detachment attached to the I Corps at Da Nang operated a forward area supply point which was responsible for supplying five "A" detachments. All resupply was accomplished by aircraft provided by the US Air Force and the US Army. The Caribou section, under the operational control of I Corps located at Da Nang provided about 50 percent of its available Caribou support to the special forces.

The S-4 of the WBM detachment determined the method of delivery based on the type of aircraft available. The Caribou, which can airland, LOIEX, or paradrop supplies, provided him with flexibility in determining the most effective method to be used. Economy of operations, based on the greatly reduced cost of air items when LOIEX or airlanded operations can replace the paradrop technique, was also a consideration. The capability of the CV-2R to maneuver in confined and restricted mountainous terrain provided the S-4 with a reasonably accurate means of paradropping supplies to long range patrols operating in areas without drop zones. This last capability was the determining factor in selecting the Caribou to perform a priority resupply mission on 30 August 1964.

The Caribou section received its Sunday mission on Saturday, the 29th. Special forces had no specific requirements, so the Caribou was scheduled to fly a general officer and party to several special forces camps for briefings. With an eight o'clock takeoff scheduled for the 30th, the crew checked in with I Corps Army aviation operations section at 0700 for latest instructions on the flight. They were told that an urgent request had just been received from the special forces "B" detachment for emergency resupply of food and water to a patrol.

The itinerary for the general included three hours of ground time at the first stop. The Caribou would drop off the party, return to Ba Nang, fly the resupply mission, and then continue the first mission.

At 0900 the Caribou had returned to Da Nang for the supplies to be paradropped to the special forces strike force patrol. At 0920 the Caribou was airborne with 1720 pounds of water, food, and ammunition rigged in eight bundles. Because of the difficulty of recovering supplies in the jungle and the high probability of losing supplies, light bundles are preferred in Vietnam to the 500-pound bundle normally paradropped.

The patrol was located on a narrow ridge in steep mountainous terrain. The patrol was unable to use panels or to be seen from above since they were covered by a thick jungle canopy. Smoke was used to mark the location of the patrol. FM air-ground communication was available.

B-2

About five minutes out from the drop zone, radio contact was made with the patrol. The patrol was told to use plenty of smoke and that four passes would be made, dropping two bundles on each pass. The patrol was instructed to report accuracy so that adjustments could be made in the flight path.

Over the DZ, which could be identified only by smoke drifting through the jungle cover, the aviator placed the aircraft in a steep dive toward the smoke. Airspeed climbed to 150 knots. At 150 feet above the trees, the jumpmaster was given the green light, and the aircraft was pulled into a climb just as two bundles were discharged. The parachutes deployed quickly, oscillated once, and disappeared into the jungle.

The patrol leader reported both bundles on target. A second pass was made, but the first bundle was short. Adjustments were made and the last two passes placed the remaining bundles on target. Seven of the eight bundles were recovered, an acceptable recovery rate under the circumstances.

NARRATIVE DESCRIPTION OF A SCHEDULED COURIER MISSION IN VIETNAM

Courier flights are scheduled within each of the corps tactical zones and special zones in the Republic of Vietnam. These scheduled flights provide an orderly and efficient means of transporting troops and supplies. The length and composition of some of the runways within each of the zones limit the type of aircraft that can provide this service. The Caribou, with its STOL characteristics and its 6000-pound cargo carrying capacity, meets the requirements on a continuing basis.

The Phuce Binh Thanh (PBT) Special Zone is an area in Vietnam about 60 miles wide and consists of provinces extending from the Cambodian border to a point six miles north of Saigon. The Viet Cong have a long history of activity in the area and ground fire is received regularly by both airplanes and helicopters that venture below 2000 feet. The terrain averages about 800 feet above sea level, and is generally flat with a few isolated mountains that rise to 3000 feet. The Phouc Binh Thanh courier run originates in Saigon with the first point of landing at Phuce Vinh, then to Song Be, Hon Quan, Phuce Vinh, and back to Saigon. Average flying time for the mission is 1 hour and 50 minutes.

The crew of the Caribou assigned to the Phuoc Binh Thanh mission consisted of the unit instructor and standardization pilot, the Army Concept Team in Vietnam (ACTIV) project officer for the Caribou evaluation, and a crew chief.

At Saigon, while the Caribou was being loaded with 5000 pounds of general supplies and rations that were to be delivered to the advisory teams located along the flight route, the aircraft commander received a weather briefing. Weather was predicted to be from zero-zero to 2000 feet broken with 7 miles visibility. Typical monsoon weather with rainshowers and low ceiling prevailed throughout the Phuoc Binh Thanh special zone.

The aircraft took off at 1300 hours and heavy rainshowers and a 2000-foot overcast were encountered while turning on course to Phuoc Vinh. Paris control, the Air Force ground control intercept radar facility at Saigon, was contacted and given the route of flight. Paris control was informed that the aircraft would be in and out of the clouds at 2200 feet, and flight following was requested. During the 20-minute leg to Phuoc Vinh the aircraft was under instrument flight rules (IFR) for 5 minutes. The airfield was located without difficulty, and a close-in 180 degree approach was executed in order to reduce exposure time while the aircraft was at an altitude vulnerable to ground fire (below 2000 feet). At Phuoc Vinh, cargo and passengers were off-loaded and passengers and cargo taken on.

The aircraft, after 15 minutes of ground time, departed for Song Be and immediately encountered IFR weather. The ragged bottoms of the clouds appeared to be about 1700 feet. The elevation of Song Be airfield is 797 feet with an isolated mountain 2405 feet high about a mile to the northeast. The weather and enemy situation presented two possible decisions for the aircraft commarder. First, he could fly below the clouds and attempt to circumnavigate the heavy rains. This would put the aircraft at an altitude vulnerable to ground fire. It did, nowever, have the advantage of better navigation and would reduce the possibility of not being able to let down on Song Be. The second possible solution was to go IFR at 2000 feet, 1205 feet above the ground, fly time-distance, and let down to 1500 (705 absolute) 5 minutes prior to arrival at Song Be. It was decided to maintain the 2000-foot altitude, and at the end of 15 minutes, attempt let down to visual flight rule (VFR) conditions. If VFR did not exist, the aircraft would return to Phuoc Vinh and wait out the weather.

The leg to Song Be consisted of 15 minutes of IFR and 5 minutes of VFR. Just five minutes out of Song Be, letdown was made to good VFR conditions with the mountain to the northeast of the airfield clearly visible. The Caribou was flown over the airfield at 1500 feet, the wind indicator was checked, and a steep 270-degree approach with 40 degrees of flaps was executed to avoid unduly exposing the aircraft to ground fire.

While the aircraft was being unloaded, the weather continued to deteriorate. The instructor pilot discussed the situation with the pilot, presenting various courses of action. It was decided to fly below the clouds and to go IFR only as a last resort. Navigation would not be a problem since there was a radio beacon located near the airfield at Hon Quan. The only problem would be extended exposure to ground fire, which would be countered by flying in and out of the base of the overcast.

About 4 minutes after takeoff, the aircraft was forced to fly between 200 and 500 feet above the terrain. The heavy rainfall and the intermittent IFR conditions provided good protection from ground fire. While the pilot was flying the instruments, the aircraft commander studied the terrain below. As the aircraft neared Hon Quan, he began calling out headings which would avoid the areas of zero visibility and place the ship in a position to make a 180-degree approach, with the airfield on the pilot side of the cockpit. About 1 minute out, at 800 feet altitude and with the airfield still not located, a blinding rainshower commenced. Visibility became zero except for straight down. While the pilot flew using the instruments, the aircraft commander searched for the airfield and called off headings. The field was first seen as the aircraft passed adjacent to it. The pilot immediately fixed its location and started an approach.

Hon Quan Airfield is located on a sloping ridge on the outskirts of a small town. It is a 1300-foot strip of unimpacted dirt. The runway heading is 050 degrees - 230 degrees. The 05 end is about 35 feet lower than the 23 end. A valley at the approach of the 05 end gives one the impression that he is too high on short final and there is a natural tendency to overshoot. A steep bank at the west end leaves no overrun. Making an approach over the rudder of a wrecked C-47, which had previously landed downhill and skidded off the 05 end, reduced the usable length to about 1150 feet.

There were several small gullies in the strip as a result of the interse rain. Because of the driving rain, the wrecked aircraft on the approach end of the strip, the natural tendency to overshoot, and the muddy runway, the pilot had to execute a go around. After another low pattern and an approach with 40 degrees of flars on short final, the aircraft landed about 200 feet down the muddy strip. The crosswind of about 15 knots added to the difficulty of control on the narrow muddy field. Propellers were reversed, which aided in the control of the aircraft, and the aircraft came to a stop after an 800-foot landing roll.

After 20 minutes on the ground, during which passengers and cargo were loaded and the crew and passengers were thoroughly drenched, the aircraft was readied for takeoff. The Caribou took off downhill and pulled up a little early to clear the rudder of the damaged C-47 at the end of the runway. There was no improvement in the weather and of the 15 minute leg to Phuoc Vinh, 12 minutes were solid IFR at an altitude of 1700 feet, which provided about 1000 feet of terrain clearance. Flying time-distance, the aircraft broke out of the clouds about three minutes from Phuoc Vinh with the airfield dead ahead.

After 10 minutes of ground time, the aircraft took off for Saigon. Paris Control reported Saigon with 2200 feet of broken clouds. Ten miles north of Saigon, the weather improved as predicted.

The Caribou returned to Saigon after logging one hour and fifty-five minutes of flying time, fifty-five minutes of this being under IFR conditions. During the mission 6,900 pounds of cargo were delivered and 58 passengers were transported.

NARRATIVE DESCRIPTION OF A FORWARD AREA TROOP MOVEMENT USING CV-2B AIRCRAFT

A requirement developed in the ARVN 5th Division to replace a battalion of infantry located at Dau Teng with a fresh battalion from Bien Hoa, the division headquarters. The division senior advisor requested that the switch be accomplished on 4 September 1964 by Caribou allocated to the III Corps. The Army aviation element of the corps tactical operations center approved the request and scheduled the lift directly with the operations section of the 61st Aviation Company.

There was no need for a special briefing since this would be accomplished by the American advisor with the infantry battalion that was being replaced. About 400 troops and 20,000 pounds of cargo were to be moved. Two CV-2B's were assigned the mission.

The aircraft took off from Vung Tau at 0630, and proceeded to Bien Hoa, 35 miles northwest, arriving at 0650. However, there was a 300-foot broken ceiling and the tower, controlled by the Vietnamese Air Force, would not allow the aircraft to land. After holding for about 25 minutes, the aircraft flew out of controlled airspace and let down through low broken clouds and then proceeded to Bien Hoa on the deck, landing at 0730.

The crews were met by the US Army advisor to the battalion and briefed on the mission. The battalion being replaced had suffered heavy casualties and had been under attack almost constantly for the past several nights. The Caribou were to land at Dau Teng Airfield and replace the battalion on position. The aircraft would move the troops, weapons, basic load of ammunition, food, and dependents of both battalions.

The flight leader asked the American advisor to divide the troops, equipment, ammunitions and dependents into groups forming 6000-pound loads. The groups were to be positioned so as to facilitate loading. All weapons were to be cleared. Loading would commence immediately upon arrival of the battalion.

The battalion was moved by truck to Dien Hoa Airfield from a nearby assembly area. The Vietnamese officers and NCO's quickly lined the troops up and assembled the loads. The number of troops loaded did not always coincide with the number of seat belts. When this occurred, the crew chief strapped all the personnel on one side with one cargo strap. Machineguns, mortars, recoilless rifles, ammunition, food, and packs were secured in the center aisle.

The 2 aircraft with the first loads were ready for takeoff within 30 minutes after the aircraft arrived. The tower approved a VFR takeoff with a 300-foot broken ceiling. After reaching cruising altitude of

ANNEX B

3000 feet, the flight leader called Paris Control and reported his position, altitude, and destination, and requested flight-following. Paris Control quickly established radar contact with the assistance of a transponder.

Bau Teng is located 34 miles northwest of Saigon and 13 miles east-southeast of Tay Ninh Mountain in one of the most active Viet Cong areas.

At the controls of the lead ship was a newly arrived warrant officer who was flying his first operational mission, and an instructor pilot. With Dau Teng ahead, the pre-landing check was completed, airspeed reduced to about 70 knots and, with 30 degrees of flaps, a perfect approach was made. Twenty feet from touchdown about thirty cattle were driven across the runway. The pilot and instructor hit the throttles together. The aircraft responded to the added power and, with flaps and gear on the way up, a go-around was executed.

After the cattle had been corraled, both aircraft landed and discharged their troops. The American advisor at Dau Teng briefed the pilots on the local situation. He strongly advised the crews not to overfly the area to the west of the airfield at a low altitude because of the large concentration of Viet Cong.

Loading was no problem, the troops were anxious to get out of Dau Teng and quickly responded to all orders and instructions. Takeoff was normal with both aircraft climbing above the clouds for the return trip. As the aircraft neared Bien Hoa the low overcast began to break up and by the time the aircraft were on downwind the skies were clear.

One aircraft was diverted to another mission at 1110 hours. At 1410, after a lunch and servicing break, the remaining CV-2B was again airborne.

The mission was completed at 1750. Two battalions with dependents had been switched and 20,000 pounds of cargo had been moved in a total of 25 sorties and 10 flying hours.

NARRATIVE DESCRIPTION OF A LOW-LEVEL EXTRACTION MISSION

Low ceilings and reduced visibility had prevented the normal aerial resupply of the special forces site at Go Dau Ha. Resupply had normally been accomplished by paradrop. A CV-2B allocated to III Corps was dispatched to the special forces supply base at Nha Trang, 21 August 1964, to pick up 6000 pounds of rations and ammunition.

At Nha Trang, the Caribou was met by two flatbed 2½-ton trucks loaded with three 2000-pound pallets. These pallets were quickly rolled into the Caribou and secured while the airplane was prepared for takeoff. One of the pioneers of IOLEX in Vietnam was in the cargo compartment as loadmaster. In the cockpit was a unit instructor pilot and a recently arrived warrant officer who was undergoing his operational checkout.

The flight from Nha Trang was south along the coast to Phan Thiet because of thunderstorms over the mountains. Near Phan Thiet Paris grand control intercept radar picked up the aircraft and provided assistance in avoiding areas of intense rainshowers. Paris reported a wide band of heavy rainshowers on course ot Go Dau Ha. This report was soon confirmed as the Caribou flew into rain which reduced visibility to about & mile. Altitude was held at 1500 feet as the aircraft flew in and out of low clouds. When the loadmaster was given his 20-minute warning, he rechecked the load and reported it ready for drop. At the 10-minute warning, the loadmaster carefully checked the pendulum extraction system, the load, and removed the forward and vertical restraining straps. Visibility was poor, but improving. The pilot turned on the red light and notified the drop master to perform the 6-minute check. The pendulum system was rechecked, and as the loadmaster moved from the rear to the front of the cargo compartment, he removed all tiedowns.

The aircraft continued on course, maintaining direction by following a small stream. Over Go Dau Ha, the drop zone was identified. The pilot executed a 360 degree approach in order to keep the DZ in sight. At the 180 degree point the gear was extended, flaps were set at 20 degrees, and the pilot gave the 1-minute warning.

As the Caribou was turned to final approach, the loadmaster made sure all personnel were forward of the load, untied the extraction chute safety tiedown line, and reported to the pilot that he had a "hot" load. He then drew his knife, ready to cut the extraction system from the load if one of the extraction chutes failed to deploy.

The Caribou was slowed to 75 knots on short final approach to the drop zone. The pilot steadied the ship at about eight feet over the beginning of the drop zone. Power was adjusted to maintain level flight,

ANNEX B

the green light was turned on, and the pendulum release switch was activated. Moments later, the first chute deployed, extracting the first pallet, to which was attached the extraction chute for the second load. The second and third pallets were extracted in daisy-chain fashion.

This mission was executed without ground-to-air communications, smoke, or panels to mark the DZ.

(a) WINEX C

COMMENTS OF THE SENIOR CORPS ADVISORS AND OF THE COMMANDING OFFICER, 5TH SPECIAL FORCES GROUP

The annex contains comments of the senior US Army advisor to each of the ARVN corps tactical sones, and the commanding officer, 5th and Special Forces Group, relative to the support provided by US Army conditions CV-2B aircraft.

Comment		Page
US Senior Advisor, I Corps		
US Senior Advisor, II Corps		C-6
US Senior Advisor, III Corps		G-10
US Senior Advisor, IV Corps	er - No ministratories de las companyones de las	
Commanding Officer, 5th Special Fo	orces Group	C-17
Letter, Headquarters 5th Special F subject: Request for Army Aviation Special Forces, dated 27 October 1	n Support of	C-21

COMMENTS, SENIOR ADVISOR, I CORPS

1. What role does the Caribou play in meeting your transportation and resupply mission requirements? Please comment on response time.

Answer: The Caribou plays an extremely vital role within the I Corps area, particularly in resupply of isolated outposts and patrols. In as much as the six raft are located in I Corps area, response is a immediate.

2. For what mission is the Caribou particularly suited?

Answer: Resupply. The delivery of supplies and personnel into small and relatively unimproved landing strips. The best utilization of this aircraft in I Corps is short flights (1 hour or less) with maximum payload into small strips. In addition, the CV-2 is particularly suited to resupply by airdrop into critically small DZ areas. I Corps has been resupplying platoon size and larger units under patrol where in many cases a DZ cannot be cleared. Many of these missions are accomplished where the aircraft is subject to fire and accuracy is most important. The short field capability, ease of loading and unloading, and airdrop capability makes the aircraft the workhorse of Vietnam.

3. Can the Caribou, with reversible pitch land at all airfields in your area of responsibility? If negative, list airfields.

* 1942 Att Cart Calling &

Answer: Yes.

4. Is liaison between the Caribou company and your headquarters adequate?

Answer: Reasonably adequate. It is felt that at any time a CV-2 must be recalled to the company or an exchange of aircraft effected, the company should call I Corps Aviation staff for coordination rather than calling company aviators. In most cases better utilization of aircraft and less juggling of schedules will result from this liaison.

5. If employed, comment on the effectiveness of low-level extraction (IOLEX) in your zone.

Answer: LOLEX in I Corps is becoming progressively more effective. This is a field where the skill of the aviator is very apparent and as in most cases, practice improved performance. When used correctly, it has the following advantages over other types of delivery:

a. Can be placed on target in larger pallets (up to 6,000 pounds, but 3,000 pounds is found to be preferred).

ANNEX C

- b. Repid loading and minimum rigging required after pallet is packed.
- c. Rapid off-loading. Even faster than airdrop due to the 1- or 2-pallet concept.
 - d. Fewer parachutes are required.
- e. Cuts exposure time to enemy ground fire. Entire load can usually be dropped in minutes.
- f. Overall mission requires much less time. IOLEX should be used more often or as often as feasible. The more missions flown, the more accurate the crew become. It is recommended that the most experienced eviators be utilized on these missions whenever possible.
- 6. (C) What recommendations can you make concerning the current allocation and stationing of CV-2B aircraft?

Answer: Recommend that CV-2 allocation to corps areas be considered on the basis of cargo and passengers hauled per aircraft per reporting pariod. Total flying time per month per aircraft does not tell a true story. I Corps can utilize four CV-2's and keep these aircraft busy on a fulltime schedule.

7. (C) Please comment on the validity of the current concept of placing allocated CV-2B aircraft under the operational control of the user.

Answer: All aircraft allocated to the corps should, of course, be under operational control of the user. To do any less than this would be to tie the user's hands. In addition the user should exercise OER responsibility while crews are under their jurisdiction. Company and battalion commanders will, without thinking, object to this saying the corps is taking away their authority, but it is not fair to the military or the individual to be rated by a commander whom he doesn't see but half a dozen times within many months.

COMMENTS, SENIOR ADVISOR II CORPS

1. What role does the Caribou play in meeting your transportation and resupply mission requirements? Please comment on response time.

Answer: Current assets include two CV-2B aircraft. At least one CV-2 is available daily for preplanned cargo or troop missions, and on Wednesday, Saturday, and Sunday both aircraft are available. (At present, requirements are greater than aircraft available. In late November or early December two additional CV-2 aircraft will be made available to II Corps when the 92nd Aviation Company becomes operational at Qui Nhon.) Response time is dictated by maintenance problems and regular periodic inspections. Since scheduled maintenance is performed at Yung Tau, the aircraft are frequently lost to the corps completely during these periods creating an undesirable backlog and disrupting schedules. Most of the time at least one of the two aircraft is available for the courier run, but this is a problem area due to requirements exceeding aircraft availability. This problem area should be resolved on or about 1 November when the 14th Aviation Battalion (Nha Trang) and the 92nd Aviation Company (Qui Nhon) become operational.

The Caribou provides a light cargo lift capability within the corps and from the corps to Saigon, the main supply base. Additionally, this aircraft provides an emergency cargo lift capability which becomes essential when an area is hit or when a short notice air assault mission develops that requires fuel and ammunition to be moved rapidly. Both CV-2's are stationed at corps and can be anywhere in the corps area in 01:30 flying time excluding load time.

2. For what missions is the Caribou particularly suited?

Answer: Hard cargo supply-resupply. The Caribou is particularly suited for transport of cargo and personnel that can be airlanded into short field strips. Cargo can be airdropped or dispensed by the low-level extraction method.

3. Can the Caribou, with reversible pitch propellers, land at all airfields in your area of responsibility? If negative, list airfields.

Answer: Yes.

4. Is liaison between the Caribou company and your headquarters adequate?

Answer: Communications are poor to LARK. Other than that, communication liaison is adequate considering the company is at Vung Tau and we are at Plieku. This will be solved on or about 1 November 1964 when the 14th Aviation Battalion at Nha Trang and the 92nd Aviation Company at Qui Nhon become operational.

5. If employed, comment on the effectiveness of low-level extraction (LOLEX) in your zone.

Answer: The LOLEX method of cargo delivery has been used extensively in the Corps area to deliver cargo to special forces sites. Percent of damage and unusable cargo has been less than 5 percent. In order to use the full capacity of LOLEX, qualified riggers and air items (parachutes, clear straps, pallets, etc.) must be positioned at key locations within the corps area. At present the Nha Trang Special Forces Logistical Command is the only place in II Corps that has the personnel and equipment to accommodate LOLEX.

ó. (C) What recommendations can you make concerning the current allocation and stationing of CV-2B aircraft?

Answer: Station two at Nha Trang to support special forces. These should be used when strips are too short for C-123's, and can effectively be used for LOLEX.

7. (C) Please comment on the validity of the current concept of placing allocated CV-2B aircraft under the operational control of the user.

Answer: The concept is workable with a good liaison and coordination between crews, aviation unit, and using unit to develop best utilization of hard carge movement. Maintenance coordination and understanding is required of the user unit to achieve best results. Caution must be exercised to avoid excess use of this aircraft for less than useful capacity loads.

COMMENTS, SENIOR ADVISOR, III CORPS

1. What role does the Caribou play in meeting your transportation and resupply mission requirements? Please comment on response time.

Answer: The Caribou provides tactical troop lift, resupply of III Corps units, and provides support for US advisory personnel through scheduled runs throughout the corps area. In addition, four special forces camps in the corps area are resupplied primarily by Caribou due to inaccessibility to these locations by road. Since most missions are either pre-scheduled or scheduled about 15 hours beforehand, the only comment we can make about response time is that it is adequate. On all missions the response has been extremely fast since requests for allocated aircraft go directly from III Corps advisor headquarters to the Caribou company and through no intermediate headquarters.

2. For what missions is the Caribou particularly suited?

Answer: The Caribou is particularly well suited for supply missions into tactical airfields in the III Corps area. They have performed airlanded resupply, parachute delivery of supplies as well as troop movements. It is also well suited for airlift of reaction forces into tactical airfields of III Corps, air resupply, IOLEX supply, and parachute supply delivery.

3. Can the Caribou, with reversible pitch propellers, land at all airfields in your area of responsibility? If negative, list airfields.

Answer: Yes, all established airfields in III Corps can accommodate the Caribou.

4. Is liaison between the Caribou company and your headquarters adequate?

Answer: Yes, the Caribou company supporting III Corps has been extremely cooperative and periodically the operations officer has visited the III Corps aviation officer to discuss aircraft utilization and minor problems.

5. If employed, comment on the effectiveness of low-level extraction (LOLEX) in your zone.

Answer: IOLEX has been used only for demonstration and one delivery to Camp Sui Dau; however, the special forces unit in the III Corps area anticipates using LOLEX at Nui Ba Ben as soon as rigger personnel are trained.

6. (C) What recommendations can you make concerning the current allocation and stationing of CV-2B aircraft?

Answer: The present allocation of CV-2B aircraft is adequate for III Corps. No problems have arisen due to the present stationing of the Caribou.

7. (C) Please comment on the validity of the current concept of placing allocated CV-2B aircraft under the operational control of the user.

Answer: The current concept of placing two Caribou under operational control of III Corps on a standing basis is the most fessible arrangement. This allows the users to program airlift and establish priorities based on III Corps policies and operations. Utilization is monitored by an aviator who is on duty with the corps headquarters as an aviation liaison officer.

8. Additional Comments:

- a. III Corps use of the Caribou consists mainly of emergency resupply, resupply of isolated special forces camps, and scheduled courier runs. Due to the relative compactness of the III Corps area and inaccessibility of many air fields, helicopters are the mainstay of aviation support. However, the Caribou performs an indispensable function and corps operations would be seriously hampered without the use of two Caribou aircraft.
- b. Special forces have used parachute resupply from the Caribou for one of their camps (Nui Ba Don) on the average of about two times weekly. These have been particularly successful, and during the past two months only one bundle was lost.

COMMENTS. SENIOR ADVISOR IV CORPS

1. What role does the Caribou play in meeting your transportation and resupply mission requirements? Please comment on response time.

Answer: The CV-2B is the workhorse of the transportation and resupply effort in the IV Corps Tactical Zone. At present this corps is allocated the 4th, 8th, and 12th flyable Caribou. One Caribou is allocated daily for scheduled flights, for the movement of personnel and light weight priority cargo within each of the three division areas of the IV ARVN Corps. Each division is completely serviced twice weekly and the corps and division headquarters daily in addition to the above mentioned flights. The second Caribou is normally allocated to tactical priority missions or special forces resupply missions if a tactical emergency does not exist.

Response time is adequate, normally overnight. In the past, tactical priority has been exercised simply by taking the Caribou off scheduled flights and using it on higher priority flights.

2. For what missions is the Caribon particularly suited?

Answer: The Caribou is particularly suited for missions which require the movement of passengers and high priority cargo into small airfields, aerial delivery and IOLEX flights to which the Air Force cannot react in time and for utilizing those airfields where the gross weight limitations of USAF aircraft is restrictive.

3. Can the Caribou, with reversible pitch propellers, land at all airfields in your area of responsibility? If negative, list airfields.

Answer: The Caribou can operate in every airfield we are using in IV Corps area except Hai-Yen, which is too narrow to permit turnaround.

4. Is liaison between the Caribou company and your headquarters adequate?

Answer: Yes, however, communication problems exist. This is corrected by relaying through Saigon.

5. If employed, comment on the effectiveness of low-level extraction (LOLEX) in your zone.

Answer: LOLEX has been used effectively by special forces in resupplying remote areas. In their opinion, it has proved to be a very efficient system and is much preferred to airdrop.

6. (C) What recommendations can you make concerning the current allocation and stationing of CV-2B aircraft?

C-8

COMMENTS, SENIOR ADVISOR IV CORPS

1. What role does the Caribou play in meeting your transportation and resupply mission requirements? Please comment on response time.

Answer: The CV-2B is the workhorse of the transportation and resupply effort in the IV Corps Tactical Zone. At present this corps is allocated the 4th, 8th, and 12th flyable Caribou. One Caribou is allocated daily for scheduled flights, for the movement of personnel and light weight priority cargo within each of the three division areas of the IV ARVN Corps. Each division is completely serviced twice weekly and the corps and division headquarters daily in addition to the above mentioned flights. The second Caribou is normally allocated to tactical priority missions or special forces resupply missions if a tactical emergency does not exist.

Response time is adequate, normally overnight. In the past, tactical priority has been exercised simply by taking the Caribou off scheduled flights and using it on higher priority flights.

2. For what missions is the Caribou particularly suited?

Answer: The Caribou is particularly suited for missions which require the movement of passengers and high priority cargo into small airfields, aerial delivery and LOLEX flights to which the Air Force cannot react in time and for utilizing those airfields where the gross weight limitations of USAF aircraft is restrictive.

3. Can the Caribou, with reversible pitch propellers, land at all airfields in your area of responsibility? If negative, list airfields.

Answer: The Caribou can operate in every airfield we are using in IV Corps area except Hai-Yen, which is too narrow to permit turnaround.

4. Is liaison between the Caribou company and your headquarters adequate?

Answer: Yes, however, communication problems exist. This is corrected by relaying through Saigon.

5. If employed, comment on the effectiveness of low-level extraction (LOLEX) in your zone.

Answar: LOLEX has been used effectively by special forces in resupplying remote areas. In their opinion, it has proved to be a very efficient system and is much preferred to airdrop.

6. (C) What recommendations can you make concerning the current allocation and stationing of CV-2B aircraft?

ANNEX C

Answer: It would be advantageous to have one CV-2B located at this station for quick-reaction missions such as emergency ammo, and PCL resupply missions, large medical evacuation missions, command post moves, etc. The present method of allocation of CV-2B aircraft is satisfactory considing the present limitation of resources in RVN.

7. (C) Please comment on the validity of the current concept of placing alloc. d CV-2B aircraft under the operational control of the user.

Answer: This is the most efficient method that can be used for the employment of the Caribou. It requires less administration and assures use of the Caribou for most urgent missions.

3. Additional comments: It is corps policy to utilize the South East Asia Airlift System aircraft for the movement of cargo from Saigon and other established airfields within the corps zone from which South East Asia Airlift aircraft can operate. Due to advance planning time required by the 8th Aerial Port Sqd it is often necessary to use corps-allocated CV-2Bs for the mission when time is of the essence.

Libration of the selection

19 1 3b a

 $t(\sigma) = \{ \epsilon_1, \ldots, \epsilon_n \} = \frac{1}{t(\sigma)}$

COMMENTS, 5TH SPECIAL FORCES GROUP (ABN), 1ST SPECIAL FORCES

1. What role does the Caribou play in meeting your transportation and resupply mission requirements? Please comment on response time.

Answer: The Caribou is an opportune aircraft as far as this headquarters is concerned, because there are no Caribou allocated by J3 MACV to support the special forces mission in-country. The best Caribou support to special forces goes to the "B" detachments in I and III Corps and these aircraft are requested 24 hours before the required time and approved or disapproved 18 hours before mission time.

2. For what mission is the Caribou particularly suited?

Answer: The Caribou is particularly suited for troop movements, personnel parachute operations, and delivery of supplies by IOIEX, air-drop, or airlanding.

3. Can the Caribou, with reversible pitch propeller, land at all airfields in your area of responsibility? If negative, list airfields.

Answer: No, the Caribou is not yet capable of airlanding at Camp ARO in I corps which is at present suitable only for OLE, U-10 type of aircraft.

4. Is liaison between the Caribou company and your headquarters adequate?

Answer: Liaison between the Caribou Company and this headquarters is not required since this headquarters and the "B" detachments in each corps area must refer their requests for Caribou support to the respective corps TOC. If this headquarters requires a Caribou from the Company headquarters at Vung Tau, the request must go through the TOC, Saigon and be approved there before the company can release an airplane. In otherwords, the Caribou Company has no control over the operational deployment of its airplanes. Liaison on matters other than requests for airplanes is satisfactory.

5. If employed, comment on the effectiveness of low-level extraction (LOLEX) in your zone.

Answer: Low-level extraction has achieved a high degree of success in actual delivery. Over 200,000 pounds of supplies have been delivered since 19 July 1964. Compared to airdrop, IOLEX is cheaper, takes less rigging time, less time in the drop zone area, with less exposure to enemy fire, and allows for continuous delivery of supplies to detachments which have airstrips rendered useless by rain. A recent example of the success of IOLEX was on 15 October at Camp TAKO, a small mountain special forces camp on the Vietnam-Laos border in I Corps which

is capable of landing only one helicopter. Because of cloud cover hanging 200 feet above the camp and the small drop zone, airdrop, the only practical means of resupply up to that time, had been unsuccessful for a number of days.

The Caribou pilot with a LOIFX load aboard, broke through cloud cover at 200 feet over the camp and made 3 sorties releasing the extraction parachute over the valley which 4 seconds later pulled the load from the aircraft which was then 10 feet above the camp's helicopter pad. In these 3 sorties the Caribou pinpointed 15,000 pounds of supplies into this camp.

6. (C) What recommendations can you make concerning the current allocation and stationing of CV-2B aircraft?

Answer: Recommend four CV-2B aircraft be allocated to support the Special Forces Logistic Support Center at Nha Trang. Unofficial word has been received by this headquarters that three CV-2B aircraft will be allocated to special forces effective 15 November 1964.

7. Please comment on the validity of the current concept of placing allocated CV-2B aircraft under the operational control of the user.

Answer: Placing CV-28 aircraft under the operational control of the user is fine for the user. The assignment of Caribou aircraft should be made to those activities that can best utilize the inherent capabilities of the aircraft. There are instances where this has not been done in the past.

of the real bullet

HEADQUARTERS

5TH SPECIAL FORCES GROUP (AIRBORNE) 1ST SPECIAL FORCES APO 40, San Francisco, California

ASFSU

27 October 1964

SUBJECT: Army Aviation Support of Special Forces

10:

Commander

United States Military Assistance Command Vietnam ATTN: Assistant Chief of Staff J3

And the second of the second o

APO 143, San Francisco, California

- 1. The expansion of the Special Forces mission in the Republic of Vietnam during the 2nd and 3rd quarters of fiscal year 1965 will necessitate the daily sirlift of 130,000 pounds of supplies from Nha Trang.

 Present direct supporting airlift provided from the Southeast Asia Airlift System provides Special Forces a daily lift of 72,000 pounds. The present direct supporting airlift is inadequate to meet the requirement.
 - 2. a. The present airlift supporting the Special Forces mission consists of 3 each C-123 and 2 each C-47 aircraft. The planned allowable cargo load of the C-123 is 10,000 pounds per sortie, and the C-47 carries 5,000 pounds per sortie. Flying 2 sorties daily, the aircraft have a lift capability of 80,000 pounds. Allowing for aborts due to maintenance, weather, and lack of fighter escort, the daily average is 72,000 pounds.
 - b. In the months June through September, an average monthly airlift of 2.5 million pounds was moved from Nha Trang. This averages out to a daily lift of 83,000 pounds. The additional airlift over and above 72,000 pounds is being provided by opportune C-124, C-130, CV-2B, CH-37, and U-1A aircraft. During July and August, opportune airlift has accounted for up to 20 percent of the total monthly airlift out of Nha Trang.
 - c. The 5th Special Forces Group with some 40 field detachments is now supporting some 20,000 indigenous personnel in the Civilian Irregular Defense Group and Border Surveillance (CIDG/BS) program. This supported force will increase to 30,000 personnel as the 5th Special Forces completes its buildup to some 60 operational detachments.
 - d. As far as logistical airlift is concerned, the problem is not solely one of additional airplanes, the problem is also concerned

ANNEX C

with providing using detachments with efficient direct delivery service on a year round basis which is not now possible with the present supporting aircraft.

一年のようというなどはないないできないというないないないできないないできないないできないないできないないできないないできないというないできないというないできないというできないというできないというできない

- (1) There are a total of 15 special forces camp sites having airstrips normally serviced by the C-123. These airstrips are periodically rendered useless by the rainy season causing the C-123 or C-47 to airdrop or divert the cargo to all-weather fix its with the resultant need for vehicular convoy. These strips under bad weather conditions can be serviced by the CV-2B airlanding with reversible pitch propellers or employing IOLEX delivery.
 - (2) There are eight special forces camp sites which have airstrips that can accommodate the CV-2B and lighter aircraft in the commodate the
 - (3) Eleven special forces detachments are serviced by all-weather airstrips.
 - (4) The remaining special forces camps are supplied by air-drop and 60 percent of these are capable of being resupplied by the more efficient and cheaper LOLEX delivery using the CV-2B.
 - e. Over 200,000 pounds of supplies have been delivered using LOLEX in all four corps tactical zones since !9 July 1964. Compared with conventional airdrop from the CV-2B:
 - (1) To airdrop 6,000 pounds costs \$1,600.00 in air items versus \$160.00 to LOLEX the same supplies.
 - (2) Rigging time for 6,000 pound load is reduced from 5 hours to 1 hour 10 minutes when using LOLEX.
 - (3) Aircraft exposure time over the drop zone area is reduced from 20 minutes to 6 minutes as the CV-2B can deliver its total load in a single pass.
 - (4) Accuracy is assured in LOLEX, as the pilot can pinpoint his drop, thereby reducing damage and loss significantly.
 - f. TOE 31-106E, Special Forces Group, provides for an organic Aviation Company. This headquarters has no organic or direct supporting aviation and has no priority with J3 MACV for the permanent allocation of Army aviation which the respective corps senior advisors enjoy. Notwithstanding this situation, the commanding officer of special forces has responsibilities which extend the length and breadth of the Republic of Vietnam and is responsible for supporting a force the size of two US divisions in over 60 locations.

- over the next few months will increase the requirements for sirdrop most of which can be satisfied by use of LOLEX delivery from the CV-28.
- 3. Request four each CV-2B aircraft be made available to support the Special Forces Logistic Support Center at Nha Trang. Flying up to 3 sorties daily, 4 CV-2B's can carry in the vicinity of 60,000 pounds daily, counting aborts for maintenance. Assignment of 6V-2B's aircraft will complement the large payload, large-item carrying capability of the C-123, and would insure direct delivery of supplies to camp sites not serviced by all-weather strips on a year round basis. Fuel, parking, maintenance, and flight planning facilities are available at Nha Trang, and supporting crews can be billeted at the special forces compound.

t/ John H. Spears

t/ JOHN H. SPEARS

Colonel, Intantry

Commanding

and the second of the Alexander WETOV

ANNEX C

ASPSU

如果,我们就是我们就是我们的原理,我们也是我们的,我们也是我们的,我们也是我们的,我们也是我们的,我们也是我们的,我们也是我们的,我们也会会会会,我们也会会会 1960年,1960年,我们就是我们的,我们就是我们的,我们就是我们的,我们就是我们的,我们就是我们的,我们就是我们的,我们就是我们的,我们就是我们的,我们就是

The state of the s

27 October 1964

Act SUBJECT: Airlift Support for US Army Special Forces.

NESSY.

abblide larger than appear for an army formation forces

Hq, APO 40, San Francisco, California

TO: Commander

We will but feet Featerson, a lifernie

United States Military Assistance Command Vietnam Tabusesso (CT ATTN: Assistant Chiefage Staffed3 a gradified endage hodged APO 143, San Francisco, California to Seino Amadeiro : 1278 almosfied, carboness and CAF ONA

The following airstrips are normally serviced by the C-123 by are reperiodically mendered useless by rain. They can be serviced by the CV-2B on a year round basis using airlanding or LOLEX and adding beauty

II Corps Tactical Zone:

Dougla faction bond Affi

II Corps Tacticanolones By Press

Buon Mi Ca

all of takes Chu Dron

A total Dak To

The Married Dong Ba Thin

Kannack

Buon Breing

III Corps Tactical Zone:

Bu Gia Map

Bu Dop

Long Thanh

Minh Thanh

IV Corps Tactical Zone:

Tan Hiep

An Long

Moc Hoa

Don Phuoc

C-15

ANNEX C

500

ASPSU Reserve Conserve that the reserve the Part 27 October 1964

Just of

TO: Coardad 10T

ការការ៉ាត្រីការ ក្រក់ពី នោះ នោះ នេះជា 🚱 ១៥៣ 👔

- Luciou laboroull equip II.

SUBJECT: Airlift Support for US Army Special Forces

Hq, APO 40, San Francisco, California

TO: Commander States Military Assistance Command Vietname A 1987 ATTN: Assistant Chief of Staff J3 Contain and CAR CHA APO 143, San Francisco, California

The fölloging airstrips can be serviced by the CV#2B only on year round basis using airlanding or IolkX in a label bloom when when any a se

I Corps Tactical Zone: ARO

II Corps Tactical Zone: Bu Prang

27 340

2.16. 6.66

Polei Krong

Polei Do Lim

Plei Me

Plei Mrong

Prey Srunh

III Corps Tactical Zone: Suci Da

rate to see with

(UT) ANNEX D

LOW-LEVEL EXTRACTION (LOIEX)

low-level extraction (IOIMI) is a system for delivering supplies and equipment from the CV-ZB aircraft flying in the close proximity to the ground (5 to 8 feet). An extraction parachute is used to cut the final restraint on the cargo in the aircraft, extract the load from the aircraft, and decelerate its horizontal momentum.

Low-level extraction is basically an adaptation of the standard airdrop system used for airdrop of heavy equipment from 1500-foot altitude except that it does not require the large recovery parachutes. It uses standard air items and expendable platforms or pallets and, therefore, has not involved the use of any new or untested equipment. The simplicity and the realiability of the system has permitted operational use since its inception on 29 July 1963 at Fort Lee, Virginia.

The Special Forces Logistical Support Center at Nha Trang received the necessary air items for LOLEX in July 1964. The first LOLEX mission performed in an operational theater was flown on 19 July 1964, to resupply special forces "A" detachment at Phrey Shrun, Vietnam. Prior to the introduction of LOLEX in Vietnam, all special forces "A" detachments that did not have an available airfield that would accommodate a C-123 or C-47, were resupplied by paradrop.

Low-level extraction in Vietnam has provided the special forces a significant increase in flexibility in resupplying camp sites not serviced by an airfield. It has shown certain significant advantages over the paradrop technique. These advantages are:

a) Pinpoint accuracy

神神の一方面の かんかい かんかい かんかいろう

- b) Reduction in time and cost in rigging for a given pay load
- c) Reduction in exposure time over the DZ
- d) Reduction in time required for recovery of supplies

The primary disadvantages of LOLEX are that it requires a cleared drop some and a low profile load configuration. High profile loads (more than 50 inches high) are very prone to tumble unless DZ and drop conditions are ideal. In some cases this limitation could reduce the maximum effective space use of the cargo compartment.

The ideal DZ for LOIEX is a relatively smooth cleared area at least 500 feet long. Most sites used have met that criteria, however, LOIEX was successful into one small, rough DZ of less than 500 feet, at Tako,

a newly established special forces camp site in the I Corps area. The camp site and DZ were located on the top of a mountain (figure D-1). The DZ was approximately 100 meters long and had one depression which divided the mountain top in half. The difficult terrain and the small usable area required initiation of the extraction system over the valley so that the load would lend on the end of the short DZ. Over or undershooting of the DZ meant total loss of the load. Ten successful single extractions were made to this special forces camp site during October 1964.

The pinpoint accuracy that can be achieved with LOLEX because of the constant positive extraction sequence makes LOLEX a desirable technique for a confined DZ even though the roughness of the DZ may preclude delivery of certain types of cargo.

1. RIGGING PROCEDURES

Interim rigging instructions for LOLEX have been published in a draft TM 10-500-3, dated October 1964. This manual gives detailed instructions for rigging bulk supplies and all vehicles that can be delivered by LOLEX, and details for construction of the expendable platforms (pallets).

Low-level extraction in RVN has been used to deliver bulk supplies of all types and certain small items of equipment such as generators and water purification units.

Normally, bulk items are rigged on a 48 x 96 inch or two 48 x 48 inch expendable platforms (pallets) constructed of 3/6-inch plywood and 2 x 8 inch lumber, as in figure D-2. The loads are lashed together and to the platform by 15-foot tiedown straps and 188-inch A7A slings or 20-foot slings as shown ... figure D-3.

Honeycomb shock absorbent material has not been required for delivery of bulk supplies by LOLEX in Vietnam. Rigging of vehicles, however, would require the use of this material.

2. AIRCRAFT LOADING PROCEDURES

The aircraft is prepared and loaded with the pallets for IOLEX in the same manner as for a normal airland or airdrop mission. The loads are secured and restrained in the cargo compartment of the aircraft using the aircraft's organic tiedown devices. In addition to these normal restraints to prevent shifting of the load during takeoff and in flight, the loads are secured with a final breakaway restraint.

The final restraint is a standard 60-inch shear strap connected from the bottom of the load through a shear knife of the extraction line


ANNEX D


The contract of the contract o




(U) FIGURE D-1. Tako Special Forces Drop Zone

ANNEX D








(U) PIGURE D-2. Construction details, 48-inch skidboard assembly.

ANNEX D



(U) FIGURE D-3. Lashing down a LOIEX load.

to the floor of the aircraft. This prevents the load from shifting after the tiedown devices are removed until it is cut by the force of the deploying extraction chute.

A forward restraint gate, or buffer board, is installed in front of each conveyer as a safety measure to prevent forward movement of the load in case of ground impact.

Installation of the aerial delivery system and securing of the loads in the aircraft are accomplished simultaneously by the crew chief and the special forces loadmaster as in figure D-4. A hylon safety cord is attached to the extraction parachute after it is installed in the pendulum release rack and connected tight to the side of the cargo compartment. With this simple safety device, the extraction chute would fall harmlessly to the floor in the event of an unintentional early release or a malfunction of the release.

The loading and rigging is not complete until the pilot has thoroughly checked the installation of the aerial delivery system and the loads for proper tiedowns and positioning as shown in figure D-5.

3. IN-FLIGHT PROCEDURES AND SEQUENCE

Successful accomplishment of a LOIEX mission requires a team effort between the aircraft crew and the qualified loadmaster who has



(U) FIGURE D-4. Securing a LOIEX load.



(U) FIGURE D-5. Pilot checks installation of extraction chute in pendulum release rack.

ANNEX D

THE THE POLICY OF THE PROPERTY OF THE PROPERTY



(U) FIGURE D-4. Securing a LOIEX load.



(U) FIGURE D-5. Pilot checks installation of extraction chute in pendulum release rack.

supervised the loading of the aircraft, installed the aerial delivery system, and prepared the loads for extraction.

Enroute to the drop zone the pilot gives the loadmaster a 10, 6, and 1 minute warning prior to the drop. At each of these warnings, the loadmaster, assisted by the crew chief, performs the following checks:

- a) Ten minute warning:
 - 1) Makes a visual check of the pendulum extraction system to insure that all components are in the correct position
 - 2) Makes a visual inspection of the loads and the rigging
 - 3) Reports 10 minute check complete
- b) Six minute warning (pilot turns red light on):
 - 1) Removes tiedown devices except the forward safety restraint gate
 - 2) Crew chief lowers cargo ramp three to five degrees below the horizontal position
 - 3) Insures that all personnel remain forward of the loads
 - 4) Informs pilot that six minute check is complete
- c) One minute warning:
 - 1) Crew chief positions himself by the emergency pendulum release handle
 - 2) Removes the safety line from the extraction chute
 - 3) Insures that all personnel are forward of the load
 - 4) Reports one minute check complete

Sometime during this period the pilot establishes FM radio contact with the ground party at the drop site. This is normally done from 5 to 10 minutes out. During this contact, the pilot will determine how the DZ is marked, request smoke to determine wind direction, and receive any current information on the enemy situation and condition of the DZ.

As the aircraft approaches the DZ, the pilot plans and executes an approach pattern just as if he were going to land. The only difference

is that the approach will be a little less steep than a STOL approach since the normal flap setting for LOTEX is 20 to 25 degrees, with an optimum drop speed of 70 to 75 knots. The landing gear is lowered for the drop, props are set at 2250 rpm and power used as necessary to maintain 70 to 75 knots and the desired 5 to 8 feet drop altitude.

Just prior to the release point the aircraft should be in a level flight at an altitude of 5 to 8 feet above that of the DZ. Pigure D-6 is a schematic diagram of a IOIEX approach.

At the release point the following actions take place:

- a) The pilot calls out "Execute" as the copilot simultaneously activates the green light and the pendulum release switch.
- b) If the parachute does not fall from the pendulum release as the green light comes on, the crew chief, without further command, pulls the manual pendulum release handle.
- c) The loadmaster announces to the pilot "Chute released, load extracted," or "Chute did not release," or "Chute is on the floor," or "Chute malfunctioned outside," whichever the case may be.


As the pendulum release is activated, the extraction parachute swings out of the cargo door into the slipstream, deploys, and pulls the load out of the aircraft as shown in figures D-7 through D-12. These photographs were taken of a dual extraction IOIEX at special forces "A" detachment camp site A-Ro on 22 October 1964.

After the load has cleared the aircraft, the loadmaster reports his observation of the drop as the crew chief raises the ramp door and secures all the loose tiedown devices as the pilot climbs out using METO power of 2250 rpm and 42.5 inches mainfold pressure.


L. EMERGENCY PROCEDURES

- a. Ramp and Cargo Door Failure
 - (1) Crew chief will notify pilot of failure.
- (2) On order of the pilot, the crew chief will manually open the cargo and ramp doors.
- (3) The crew chief will notify the pilot that the door and ramp are open and in the proper position (3 to 5 degrees below horizontal).
 - b. Parachute Fails to Release from Rack
 - (1) The loadmaster will notify pilot of failure.

ANNEX D



(U) FIGURE D-6. Schematic of a LOLLX approach.



AND THE STATE OF T


(U) FIGURE 5-7. Extraction chute at release point.

ANNEX D

intralin tillingungiskniket i




U) FIGURE D-8. Extraction chute prior to deg




(U) FIGURE D-9. Extraction chute deployed.

ANNEX I




44 13 WEFET #



(U) FIGURE D-11. First load slides to a stop as second extraction begins.

ANNEX D



ANNEX D

- (2) After the airplane is at a safe altitude, the pilot will direct the loadmaster to secure the load for rearward restraint. In case of a dual load, the forward load will be secured first, after which time the extraction parachute for the forward load will be disconnected from the rear load. The restraint will be reinstalled starting at the forward end of the load and working rearward. If the extraction parachute releases after the load has been secured the loadmaster will move rearward and cut the extraction line. The loadmaster will notify the pilot of such an event.
- (3) The loadmaster will reinstall the extraction parachute safety line.
- (4) The loadmaster notifies the pilot that the load is restrained for safe flight and that the extraction parachute has been made inactive.
- (5) The pilot will direct the crew chief to close the cargo door and ramp.
 - (6) The loadmaster will secure the load for forward restraint.
- (7) The crew chief notifies the pilot that the cargo door and ramp are closed and the load fully restrained.
 - c. Parachute Malfunction after Release from Rack
 - (1) Toadmaster notifies pilot as to type of malfunction.
- (2) The pilot initiates a steep climb and orders the load-master to cut the 20-foot sling from around the load, allowing the extraction system to fall away from the aircraft.
- (3) After the extraction chute and straps are clear of the airplane, the loadmaster notifies the pilot.
- (4) The loadmaster and crew chief perform the steps necessary to resecure the loads for flight with external tiedowns.

5. SUMMARY

Since 19 July 1964, over 50 IOEX missions have been flown in support of the special forces resupply effort. The procedures for IOEX described in this annex are those that have been successfully used in Vietnam. This system has added a new dimension in aerial resupply methods in Vietnam, because of its demonstrated simplicity, accuracy, and reliability.

(U) APPENDIX TO ANNEX D

SUMMARY OF LOW-LEVEL EXTRACTION MISSIONS PLOWN IN VIETNAM FROM 19 JULY 1964 TO 31 OCTOBER 1964

The first LOIEX mission executed in an operational theater was flown by a US Army Caribou 19 July 1964 at Phrey Shrunh, Vietnam.

Percent of damage was determined by dividing the total number of pounds damaged by the total number of pounds delivered, thus:

12.500 = 3.8 percent.

325,502

وسأنو ويواري ويومون	فأعلن والبادية المراجع والمراجع والمراع	أخبينا ومنواه بهره بمروم بالمربوب بيروم			فيأدموه بسيمهم وبالمواسود
DATE	AMOUNT OF CARGO	TYPE OF CARGO	DELIVERY SITE	CORPS TACTICAL ZONE	SUPPLIES DAMAGED
19 Jul 64	5800 lbs	General Cargo	Phrey Shrunh	11	22 Ker et
20 Jul 64	5800 lbs	Fortifi- cation Material	Plei Ta Nangle	Ü	
20 Jul 64	5714 lbs	Fortifi- cation Material	Soni Da	m	4 13 13 15 15 15 15 15 15 15 15 15 15 15 15 15
21 Jul 64	5800 lbs	Amunition	Dong Tre	11	
25 Jul 64	6052 lbs	Ammunition General Cargo	Dong Tre	п	3000 lbs
27 Jul 64	5800 lbs	Fortifi- cation Material	Dong Tre	п	2000 lbs
28 Jul 64	5800 lbs	Fortifi- cation Material	Go Dau Ha	m	j
31 Jul 64	5800 lbs	Fortifi- cation Material	Go Dau Ha	ш	
31 Jul 64	6216 lbs	Fortifi- cation Material	Plei Ta Nangle	п	

A A SIRE TY

	DATE		AMOUNT OF GARGO	TYPE OF CARGO	DELIVERY SITE	CORPS TACTICAL ZONE	SUPPLIES DAMAGED
ננ	. Aug	64	5800 lbs	Ammunition and Rations	Buon Brieng	п	
1	i ing		5800 lbs	Rations	Buon Brieng	TI T	四角 門 人工人
1	i Aug	64	6100 Ips	Ammunition	Bon Don	e eksterie in Herioid Kasteria	ind same; IZ. JOC
17	/ Æug	64	4000 lbs	Ammunition and Rations	ARO	I	326.555
2	2 Ang	64	6000 lbs	General Cargo	Buon Brieng	14909 11 0 - 1	7.40
2	2 Atug	64	5800 lbs	Ammunition	Ben Phouc	ŢV	2.9 6.5
2	S Ame	64	4500 lbs	General Cargo	Buon Brieng	п	1. July 11%
2	2 Aug	64	5800 lbs	Fortifi- cation Material	Go Dau Ha	III	iv. 0s
2	2 🗱 աչ	, 64	5800 lbs	Fortifi- cation Material	Mac Hoa	IA	
١L.	5 Au	·	6000 lbs	General Cargo	Saigon	ш	
1	5 A cu	:	5000 lbs	Ammunition	1	m	
2	5 k u	g 64	6000 lbs	General Cargo	Soni Da	III	
2	.5 Au	g 64	6000 lbs	Ammunition	Soni Da	ın	
[2	9 k u	g 64	6000 lbs	Ammunition	Ben Phouc	IA	

DATE	AMOUNT: OF CARGO	TYPE OF CARGO	DELIVERY SITE	CORPS TACTICAL ZONE	SUPPLIES DANAGED
ling 64	6000 lbs 6000 lbs	*	*	IA	***
7 Sep 64	4000 lbs	Ammunition	Phi Ta Nagle	11	
12 Sep 64	5500 lbs	Fortifi- cation Material	Dong Tre	H.	
12 Sep 64	5500 lbs	General Cargo	Dong Tre	п	
20 Sep 64	5500 lbs	Water Puri- fication Unit	Dong Tre	п	
22 S ep 64	4000 lbs	General Cargo and Jumber	Don Phuc	IA	
25 Sep 64	5000 lhs	Rations	Cam Dong	П	
25 Sep 64	4000 lbs	Rations	Buion Phouc	III	
27 Sep 64	5500 lbs	Construc- tion Material	Cam Dong	11	
1 Oct 64	3300 lbs	General Cargo	Don Phuc	IV:	
8 Oct 64	3800 lbs	Construc- tion Material	Don Phuc	IA	
9 Oct 64	3200 lbs	Construc- tion Material	Don Phuc	IV	:
10 Oct 64	5500 lbs	Cement and General Cargo	Plei Ta Nangle	11	
10 Oct 64	5500 lbs	Ammunition	Plei Ta Nangle not available	11	

,这是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们也是一个人,我们也是一个人,我们就是一个人,也是 一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是

1. The second of the second of

DATE	AMOUNT OF CARGO	TYPE OF CARGO	delivery 'Site	CORPS TACTICAL ZONE	SUPPLIES DAMAGED
14 Oct 64	5300 lbs	POL (55- gallon Drums)	ARC	I	3000 lbs Destroyed
14 Oct 64	5300 lbs	POL (55- gallon Browns	ARO	I	4500 lbs
14 Oct 64	4250 lbs	Ammunition and Charcoal	TAKO	1	A 1.0 M
14 Oct 64	4300 lbs	Ammunition	TAKO	Ĭ	
15 Oct 64	5200 lbs	Construc- tion Material	ARO	I	, popular
15 Oct 64	5800 lbs	Construc- tion Material	ARO	1	1 52 SX
15, Oct 64	5200 lbs	Construc- tion Material	ARO	I	1 40 JA
15 Oct 64	5600 lbs	Lumber and General Carso	TAKO	1	1 22
19 Oct 64	3500 lbs	Construc- tion Vaterial	ARO	I	
20 Oct 64	5200 lbs	Lamber	TAKO	I	
20 Oct 64	5300 lbs	Lumber	ARO	1	
20 Oct 64	5300 lbs	Rice	ARO	I	
20 Oct 64	3250 lbs	Lumber	Don Phuc	iΛ	
21 Oct 64	5220 lbs	General Cargo	ARO	I	

DATE	AMOUNT OF CARGO	TYPE OF GARGO	Delivery Site	CORPS TACTICAL ZONE	SUPPLIES DAMAGED
14 Oct 64	5300 lbs	POL (55- gallon Drums)	ARO	I	3000 lbs Destroyed
14 Oct 64	5300 lbs	POL (55- gallon Drums	ARO	I	4500 lbs Destroyed
14 Cot 64	4250 lbs	Ammunition and Charcoal	TAKO	Ţ	
14 Oct 64	4300 lbs	Ammunition	TAKO	I,	
15 Oct 64	5200 lbs	Construc- tion Material	ARO	1	
15 Oct 64	5800 lbs	Construc- tion Material	ARO	1	,
15,0ct 64	5200 lbs	Construc- tion Material	ARO	I	
15 Oct 64	5600 lbs	Lumber and General Cargo	TAKO	I	
19 Oc t 64	3500 lbs	Construc- tion Material	ARO	I	
20 Oct 64	5200 lbs	Lumber	TAKO	I	
20 Oct 64	5300 lbs	Lumber	ARO	I	
20 Oct 64	5300 lbs	Rice	ARO	I	
20 Oct 64	3250 lbs	Lumber	Don Phuc	ΪΛ	
21 Oct 64	5220 lbs	General Gargo	ARO	I	

DATE	AMOUNT OF CARGO	TYPE OF CARGO	Delivery Site	CORPS TACTICAL ZONE	SUPPLIES DAMAGED
22 Oct 64	5500 lbs	Lumber and Rations	ARO	I	
24 Oct 64	3700 lbs	General Carso	ARO	I	
26 Oct 64	4000 lbs	General Cargo	ARO	I	
26 Oct 64	3000 1ьз	Construc- tion Material	ARO	I	
28 Oct 64	.5600 lbs	General Carso	ARO	I	
29 Oct 64	5700 lbs	Construc- tion Material	ARO	I	
29 Oct 64	5800 lbs	Construc- tion Material	ARO	1	
30 Oct 64	4500 lbs	Pierced Steel Plates	ARO	I	
30 Oct 64	4500 lbs	Lumber	ARO	I	
TOTAL	325,502	4		-	12,500

224 X 25 m 4 0 m	10000000000000000000000000000000000000	egenet, two	700 44 30 042 422	%00046 (##50 4 0)	grad
					á0 a90 88
					00 500 AS
•	, 6				do tao da
Accounts when a fact of the fa					and the second
) () A 750 9 0
A second of the				A Section 1	
		THIS	PAGE NOT USED	, plant	le 350 95
-		• • • • • • • • • • • • • • • • • • • •			
:					e ya sana arawa ani
•• • • • • • • • • • • • • • • • • • •	٠	• **			

美國的政策

RECOMMENDED CHANGES TO TOE 1-59D

Acresiant

The following changes to TOE 1-59D, dated 27 March 1964, are recommended for counterinsurgency operations similar to those conducted in Vietnam.

1. SECTION II PERSONNEL

Applied the Print of Comme

jan amn og, og sembligere skræser	
Paragraph Line	Change
1944 1944 1945 1946 19	Add one Captain, Executive Officer, MOS 1983
AND	a company of the second se
salama o g ani asa da salama of gases ing distributions	Add two E-6, Airpl Tech Inspectors, MOS 679-4
 A section of the sectio	
O2 05 mp. mad a serie and a se	Add one E-5, GCA Equip Repairman, MOS 282,20
Of Of	Add four E-6, Section Chiefs, MOS 672.60
04 05	Add sixteen E-4, Asst Flight Engineers, MOS 672230
; 05 ·	Add one WO, Asst Maintenance Officer, MOS 6710
06 02	Add four E-5, Sr Airpl Mech, MOS 672.30
3	Add four E-4, Airpl Mech, MCS 672.30
07 03	Add one E-4, HV Truck Driver, Sum MOS 642.10
O/4	Add one E-4, Powerman, MOS 351.10

2. SECTION III EQUIPMENT

Paragraph	Line Item	Change
01 allocate ata	401088 The Letter of the control of	Add three Bayonet Knives, or w/scabbard for 7.62mm Rifle
(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	429280	Add one Pistol, Automatic, Caliber .45
	435965	Add two Hifles, 7.62mm Semiautomatic, Lt Barrel
02	401 088	Add one Bayonet Knife w/scabbard for 7.62 Rifle
	405638	Delete one Chassis Trailer Generator, 22 Ton, 2 Wheel
	(1917) 1918 A (1914) OWO 1914 (435965) (1917) (1910) 1914	Add one Rifle, 7.62mm, Semiautomatic, Lt Barrel
	513620 1 20 American	Add one Clock, Message Center, M-2
	1938/190 1938/940 (248 1892 1946 610280 60.000 600	Delete one Cipher Machine, TSEC/KL-7
	90601 4064 - 600 6780119 696 614915 - 110 George Gert	Delete one Electronic Tactical Teletypewriter
	and have been seen as the seen seen	Security Equip TSEC/KL-7
	616117	Delete one Generator Set, Gasoline Engine, Trailer Mounted, PU-294/G Add one Generator Set,
	gag saud oo oo ya gaasa caasa 2 Awas. Aayaa 11	Gasoline Engine, Trailer Mounted, PU-253/U
02	657222	Delete one Radio Teletype- writer Set AN/CRL-46 Add one Radio Teletypewriter
		Set AN/MRC-95 Add one TRC-42, VHF Ground Mounted Radio
04	401088	Add twenty Bayonet Knives, w/scabbard for 7.52mm mifle

	435965	Add twenty Rifles, 7.62mm Semiautomatic, Lt Barrel
-,	6373,80	Delete four Hadio Sets AN/ARC-102
05	401088	Add one Bayonet Knife w/scabbard for 7.62mm Rifle
	429280	Add one Pistol, Automatic; Caliber .45
	455410	Add two Tool Sets, Organi- wational Maintenance, Army Aircraft Set A
	455414	Add two Tool Sets, Organi-
		zational Maintemance, Army Aircraft Set B
	779922	Add one Shop Set, Ground Handling and servicing.
	ं दक्षी	Field Maintenance, Army
	785250	Delete one Tool Set, Organi- zational Maintenance, Army Aircraft, Set C
06	401.088	Add eight Bayonet Knives, w/scabbard for 7.62mm Rifle
	435965	Add eight Rifles, 7.62mm Semiautomatic, Lt Barrel
	784040	Add eight Tool Kits, Aircraft Mechanics, General
07	401088	Add two Bayonet Knives, w/scabbard for 7.62mm kifle
	435965	Add two Rifles, 7.62mm, Semiautomatic, Lt Barrel
	461460	Add one Truck Tractor, 5-tone, 6x6, SWB
	760010	Delete ce Antenna AT-791/G

THE PROPERTY OF THE PROPERTY O

THE PERSON NAMED IN COLUMN TO SERVICE AND SERVICE AND

•	tidid swehely seelles fradium emelectrophysics			<u>Žúĝĝ</u> ĝ	
	Committee of the commit		18 - 2 - 3 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4	C18783	 · · · · · · · · · · · · · · · · · · ·
	ing gas deposits and on the			550462	<u>.</u> 60
ŧ	gelizabint the offerm objective.			्रिड ्र्यूर्यः	 ••.
	And two look divises in the same and a same of the sam			ा ० देहिसूक - ० -	
	Administration of the second s			457414	
Andrew State Control of the Control	onesis idel graficio de la fig grafica al egui enclimadi graficio encrendos en adober e del Turbed de	IS PAGE	not used	SEPTIT	
,	langer og fill fillett av silvigligt Genn sæsenmennsk fillanssk fær 1916 - Hanssyl	·		0612-8¥	
	$\begin{array}{cccccccccccccccccccccccccccccccccccc$			3 . 10 ju	€
	ing the second of the second o			Some Sagar	
	eres de la deservación de la deservación de la defenda de			CV7 24	
	na terrena ang managan ang aktor kang terrena terrena ang aktor terren			Mark Control	1,5
				w (A)	


(U) APPENDIX TO ANNEX E

(U) APPENDIX TO ANNEX E

EXTRACT OF

HEADQUARTERS
AND EQUIPMENT
NO. 1-59D

The appendix to annex F contains an extract of the aviation company
(air mobile, fixed-wing) TOE.



:	16	DE 1-590						. 3	ECTION	44°44 (1 - 6	non a	ish for LNIZA	1:04	1.3.				_							
0.11	-		·	··• ·			179	hen =					focial			; .~~					MAHC				
: 1		Bearing No.	j		1404	IVIL		CADE	1 144		can.	16	بنت	CAFI	10.7	-			4.1	14	:	Land		L 2	
••• : :	-		1			194	81	. 100	. ,	-					٠.				i.			;			
7 1	2			1	1				10	11	11	ü	16	11	4		19	11	.79	31	, i	. 22	14	15	1 10
		58C 01 0590 4	- 1	;	1	1 1	1 2			Ì	Ì	l		i		L	ا. ا			i	!	:		<u>.</u>	į
-			-	-;	1	1	i	1		7			i	1		i					i	1		95.	.]"
ōi		COMPANY HEADO	ACT	5 T				† 	1	1	1	-		i	,	i				1			*****		1.
-	91 02	COMPANY COMMAN	المائقة	E N	198. C 4728	1	+	أحنا		+				 		 	-	1		-	-		+	4	44
ا	23	MESS SILVARD			7086		1	1-1		┪~-				 						1		 	 		1
: 4	03	MOTOR SERGEANT		E 'N	6794	<u> </u>		نب	-	ļ	-					ļ	ست	-				ļ	 	 	-
	04. QZ	AIRPL TECH INS FIRST COOK ARMORER		ĸ	19411	حـــــــــــــــــــــــــــــــــــــ	نسنا		ļ	ــــــــــــــــــــــــــــــــــــــ	-	<u>i</u>	ļ	 	-	ļ	_				نب	·	47	ببب	<u> </u>
i	OW	COMPANY CLERK	151	É:	7682 7161	<u> </u>	د_ا:	i : -1	1	1_			_	<u> </u>			!					11	j	1	1
	ţĢ	COOK PERSONALL SE			9411	0 2	2	1 ,] .	;		-						:				2		1	1
: ;	12	SEMEEL VEH MECH	7	L	6311	oj z	2		-	1		1	-	i.	-					-		2	14.7	100	0.1
	14	LY TRUCK DRIVE	ñ	Ľ;	7100	0 1	<u> </u>		+	1	-	!			 -							+	1		100
	15	WHEEL VEH HECH		È	7600 6300	<u>ئــــا</u> ہ	إننا	+		+	+				<u> </u>	 -			-				 - 		91
!		independent		- 			فنسك	4	+	-	-			ļ	-	-	-		-		هسبإ	 7	4	+	-
أدو	مبا	OPERATIONS SEC	LIO.	ديأني		نجداد		+		٠.	1	_	-	<u> </u>	<u>.</u>		_				1	-	J	1	11
	05 01	OPERATIONS SEC FLIGHT OF OFFI A FLIGHT OF OF FLIGHT OF CHIL	CER	O N	0 198	2]	1	1		1		-						-			<u>.</u>
7	63	PLIGHT OF CHIL	11	F M	C 9077	0 1		1	i] -	j		1	1		j .	L		1		1	1	محسط	ر بل	1:
	03	COMM CHIEF GCA EQ REPAIRM SR CON TOMER O SR FLIGHT OF S SR LANDING COM ISR RADIO MECH	AN	E !	2822	0 .)		1			-	-		1					1	1		1	1	7	45
;	05 07	SR FLIGHT OF S		<u> </u>	9011	9		ىسىدى <u>.</u> ر	+			<u> </u>		1	-	1	-			ļ	1	+		1	1-
	祭	SR RADIO MECH	-07		9012	<u>:</u>		1-	تتنا	1-	-	1			1		-	44	1		1		4	+	-
-4	Ĩο	CLERK 119131		<u> </u>	7112	91	4	 :		-		-	-				-			 	-		ļ	+	+.
	13	FONTEON OF ONE		Ę	2811		ن ــــــــــــــــــــــــــــــــــــ	1 1		<u>.</u>	ـــــ	ļ	-			-	-		بوسينة		 	وبيرا		-	-
	13	IS RADIO OPERA	FOR	ę	9012	<u> 0 i</u>	2		<u> </u>	<u> </u>	!	<u>.</u>	<u> </u>	1	, . ;	1		-			<u> </u>	1	ļ		_1_:
	. 1 🖷	LOADIO MECHENIC	. 1	£.	; 3111	0; 1	1			į	1	İ		į		!					1	1		7 -	0
-	17	SA SHOO OPERAT	OR I	•	3100	ō		1	7	T	1	i	 I	-		:]	11	1	1	0
-	† \$	FLIGHT OF HELP	-	£ -	9071 6700			1		1	7	!	 	!		1	1					 -	i	1-	1
-	뀱	SMITCHBOARD OF		<u>-</u>	3100	<u>6</u>	4				-				i	-	+		1	-	!		7-1	-	Q.
				+	· -		1 25	1	+	į.	+	┼	 -	-	+-4		<u> </u>	-		+	 - •	Y	4		4-
01		2 AIRPLANE PLA	1004	ME	APQUAR	YERS	,	,	}	-	!	; —	├	1 2		-	<u> </u>	•		 -	 	;	-	.i	ا ا
	ŏż	PLATOON COMMAN PLATOON SERGES	NT	L M	C 6747	9			1	-	٠.	; -	 	4	<u>.</u>	:	! • •		_ 2	!	 	<u>!</u>	-	: 	4
į	03	LT TRUCK DRIVE	R	E	6700	9					<u> </u>	<u> </u>	<u>!</u>		ļ	:	:	! 		<u>:</u>	!	<u>i</u>	1	u	0
04		A AIRPLANE SE	T LO	5	1	1		•	i	1				1	:		;	•		1	i 1		1	· ·	i.
	91	SECTION COMMAN	DER	O N	0 .199	8 2				1	1	,		1		2.8		:	:				!	1	1
-	**	SECTION COMMAN AIRPLANE PILO FLIGHT ENGINEE	R	Ē+-	-16725	31-1			+	+	1	:	·	1-		7	-		 		16	+	!	1	
					-+		26	4	4	+-	; -		.	+	•	- 20			 		49				-
05	דס	SERVICE PLATOC PLATOON COMMAN	DEN HE	ABO	DIGARTER OTGARZ	5 1	 	 		-	+	-		+	<u>. </u>	-			<u> </u>		-	·•·		-	-1
_	7	SO ACT BAST	3	-	5 6737	<u> </u>		-			+-	-	i	j			- -		بسا	<u> </u>	-	-	<u></u>		- <u>-</u>
	ç.	AUN ELYR EO HE	اعج	È.	7661	اه				-	4-	ļ	- -	لم	<u> </u>	٠	<u> </u>	-		<u>.</u>	ļ		·		- ! -
	0.0	CLERE TYPIST	OH j		7112 631	0			i	_	<u> </u>	<u> </u>	_		<u>:</u>	<u>. </u>	<u> </u>		∮: ∔⊶				-	.i.	į
	07	WHECKER OPERAT	.k :	E 1	7600						1		1	1. "	:	1 .	ļ		-	i		, 1	1 ,		و
_	09	RECORDS CLERK		-	7100	10			1	-	1-	1		:	!	-	1	;						, 1	1
_	10	SUPPLY CLERK		-	7600	1	1	1	1	 	+-	1	 	1	+	-	1	,	1	1	1	, -	, , , , , ,		
Õ÷		4 MAINTENANCE	586	i de	<u>s</u>	+	+	+	+	+-	+	 		+	+	·	†		+-	ļ	i	+	-	-i -	-i
	. 1	A MAINTENANCE SU MAINTENANCE SU SR AIRPLANE H	PV	Ę N	6 72	0 1	1		-	-	-	-	-	-	-	+-	- i-		┿		+-12	i	-	÷	4-
	2.	A PLANE HECH	B.C.	<u> </u>	6743	0 1	1	} <u></u>	-	4-	_	-	!		!	-	<u>.</u>	-	<u> </u>	<u> </u>	-	باا	Ľ		
	04	AIRPL MECH HEL	PER	E !	6700	10	•	٠.	<u> </u>	-	1	_	1_		-	ļ	:		<u>.</u>		ند ا			Ľ.	
07		AIRFIELD SERV	CE	Ę į	104	7		1		1	1						1					;	1		1
*1	01	SECTION CHIEF		216	278777	0	1	-	1	1	Ţ	1	1	-	_		!	·	-		1				Ī
	-			-	-			-	1	+	+-		 	+-	†					ī	†	- †		:	+
	<u> </u>	<u> </u>		-			-	+-;-			+:	1 10		18	 -	+-,-	<u>.</u>		, M			÷-;-	, p	70	+

William of the control of the contro

to the water a minister worthing at a march to be better

			, .,	,				C LIGHT	13 C	404			- : - :								TOL A	-59		
rad Las		CALMORATION	Here	B/25	Personal Control of the Control of t	76 70610	EGTH GADES	ten Ten Ten	Min.	ç (ga		Men	sag,	, L I	eng	1:1	in	194	•	I-I	· bri	 [0-4	912.403
~	,							Н	-	3	u u	и	16	<u>la</u>	V.	14	•	14)i	<u>n</u>	и		25	24
	03	CRASH RESCUE SP HY TRUCK DRIVER PRIMERMAN JACET FUELS HOUSE	14	54210 132110 58440				-zeranie idaneni			***									- 72	٠	i ·~~~~		01. 01
-	-	A COLUMN THE CO		~~~	ننب	- 19			-								7	9-20) Jan		10		2 4 3	
ء مالم ا		Action and the second second	<u> </u>		. 118	111	_41.				,	1	***	. 5	28				7.	- 50	_00			
	-	RECAPITULATION	-						1			77.7.7		-		_		-						
	-	OFFICERS	 			-							1812					-					4	
<u>.</u>	-		0 MO	1962						-	-		3	-										
	1		0 HO	1983	10				_	-		1	<u>)</u> .	-					-	-			ļ) X
	_	WARRANT OFFICERS					-		L					-			-					A. 164	1 - 1	
	-	The second secon	w.	osico	24	=:-			_		_			_	28					112	-			
	-	NON CONNISSIONED	FFIC	ERS	2A		-			-		_			24			_		-				
<u>.</u>	-	!	E NC	31160			-		-					-							7			-
<u></u>	-		ENC	63160 67260 67270	1 3	ļ			-					-	_			3	!					
		!	E NC	76860 90770 94160	-	1				-		_			-	_		1	1			7537.	7 (1)	
	-	OTHER ENLISTED	+		14		-		-			_			-	-	1	•	. 6	•		-		-
	+		E	05110	2	-			 	-	_			 	-	-		 	<u> </u>	ļ	2			_
	-		E E	05310 20220 20410	1	_			-									_		1	1 2			
	-		E	31000 31110 35110 35110					-	_	_	_		-				_	-	-	 			
			E	63000 63110 64210	1 1	-			-		-		-	-		-		-	-	-	3	1		
			Ę	67G00		-			-	-	-		!	-	-	-	-		, <u>1</u>		12	1)		-
	 	 	E .	71000 71120 71210 71610		-		_	 	 	-	-		-		-	 			!	1		-	+
_	-		E	76000 76610 76820 90110	3	1-	-		 -	-	-	-	_			 	 	-		+1	<u>. 1</u>		<u> </u>	ļ-
	-	<u> </u>	E E	90120 94000	3	-			-	-	-		-	ļ		-				i	: 2			
	-		+	-	-	-			-	-	-	-	-	-	-		-	-	· 	-	-	 	-	-
•			1010	1 4	<u> </u>	1	1.	19	111	117	10	14	11	14	IJ	14	10		1 1	11	- 11	34	11	34

,	Owanger					AND COMPANIES	1 1	44
- Tope	HEM SCICARSON	1.22	MARIE	,tri.S	ARRAN SOLL	Marie Ma Marie Marie Marie Marie Ma Ma Ma Ma Ma Ma Ma Ma Ma Ma Ma Ma Ma		
-	р дуурдуу сунбулгун бүсүн, на ттунуун нассы энь дүүлэг нассы ульбары жасын рассына нассын нассын аласын басын нассын «Даны шарары» энгэ сунан массын аласында нассын данундарын адамия бүсүн шарын нассын аласын аласын аласын аласы					-		
-	1 MBC 211 0490 9 (201)	1	2]			
	7 Field 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				7			
1	CONTANT HEADQUARTENS				1			
13.0-0	OFCORTANTA TING AGRARATUS PORTABLE I 172-07	-			300			
19227	DETECTOR REL CHEMICAL AGENT VOIL	1		! !::::-	- 600			
1 1		,	ţ.		1			
	THAN SATHE STREET ING COTTON DUCK POHOUS STITCHED SEAMS TO GAL				⊤ ες3∤			
1 37757	1 COMPASS MASNETIC GENERALIC 1.53 IN DIA CARD		ـــــد		500	~~~		
.i	F MATES IGHT	66	90	<u> </u>	899			
33564	CEMERATOR SET GAS ENG 3 KW 60 CT 1 MMD 3 PH A WIRE AC 120/240 V	1	1		400			
28961	I NEATER IMMERSION LIG FUEL FIRED 32 IN LG OF NEATER	8	i i		1326			
232624	A HEATER LANGERS LONG LONG LEVEL FIRED AT LAW IN LG OF HEATER THEATER SPACE COALTON OIL 45000 BTU 18-578 IN H		٠٠٠٠٠	 	600			
25/012	[CIGHT 551 005 HUM 25 GETEET	1 2			1000			
401/06	TRAYONET KNIFF WATERSKARD FOR TARRIE WIFE D.	20	10		620			
77.7	MANOSEL ANDER WASCARBERD FOR PARKE MIFER	5	3		ÉCO			
4171.75	COM MACHINE PACKET 3.5-INCH	2 2 - 2		7 T 2.12	1			
والمراشدة المسالم	1 MG-16: 1/UPS 2 MACHURE GHS 2-62-MM	- h-	فبسيب	, 	<u> </u>			
495750 49544	PISTOR ADDOMATIC CAL .65	10	17	ì	1 1			
49 1997	I TOOL AIT ONG MAINT NA I COMMON	1	17		1			
1	1995 KIT CHE MAINT NR 1 SUPPLYMENTAL	+			 			
457193	TRAILIN SANDO 229-TON 2-WHEEL	1	بتقييد		11			
-1-25/25	IRALLE JAN MATER 1 1/2-109 2 MAREL		المنا	سيجامعهم		· · - ÷		
46 J 00 C	Traden samen by 4-for axa symm	1	7					
-1. 420143	TERCA CARSO A 1/2-TEN DA LES TERCE UTILL'Y 1/4-TOV ANA	1			+			
	LBASE AND STARE II	<u></u>		N-942-W-944	1 500			
900772	ACCESSORY OUTFIT GASOLINE FIELD RANGE 133 COMPONENTS	1			i i			
\$99761		1	1	1	1			
- 1. 2011 20	CABINET TOR AND SPARE PARTS IL DRANESS 35 1/4 IN h 27 IN U	<u>-</u> -	2		 			
سأسينيانك أسا	CASE FIELD OFFICE MACH PLYMOOD 32-162 L 13-1/4 W 17 IN D	2						
\$15207	I COCK SET FIELD OFFICE MACH PLYMOGO ZEHIZZ L ISHIZA M LZ IN D	1 2	1 2	•	600			
\$14300	COSE 327 ELELD & COMPONENTS CESS FIELD PLYGOC 30 7/8 IN H 14 7716 IN H 15 5/8 IN D	1	1	 	1			
524160	DESK FIELD PLYNDER 27 AZA IN X 25 278 IN H 14 172 IN D. FILE VISIBLE INDEX BOOK UNIT STEEL 150 PKTS BOTH PANGLE	1-		ļ	 	has -re -		
524260	FILLING CASINET CAP SIZE STEEL GRAY DA LAZ IN B WALGER				-			
1 520100	FOOD CONTAINER INDULITED RECTANDULAR 5 GAL CAPACITY ALUMINUM GOODELS SUS WIND DUST 2 PLASTIC COLORLESS HEUTEAL GREY	4	7	1 2	306			
539965	PASEL MARKER ALSIAL LIAISON MALON & FT. 6 2 FT 4 TAP IN FLY	1	1	,				
25828	PARTY SARSES AT STATE CONTROL OF THE SECRET HIDE TYPE		4	 	 			
<u> </u>	I PARACTUTE PURSONNEL MACK 26 FT DIA DRAMGE MILLE GAMD GROUP	4			اعتفا			
357633	FRANCE COTFIT FIELD GASOLING	3	3	L	200	_		
554125	PREPAIR KELTINAGE SARCE : SHELVES I WAARR 2 COMPARTMENT 26 H 17 W 17 1/2 IN C	1	:	1				
253400	SIGN PAIRING SELLING ON SHARESTOSEL SLING CARRING UNIVERSA, INDIVIDUAL LOAD	20	70	!	1}			
كالذاغة بالم	STRAPPING FIT CIELL STRAPPING HAND BYE IN TO 2 IN STRAP &				إوعف			
- 561225 261121	TABLE FOLDING LYGG BOOG TOP AND LEGS 18 L 24 M 27-22/32 IN h		<u>}</u>	1	11			
10102-	' ASSERBER SOLLIE LISTO IN COMMONERS	7	. , 6					
	TEAT CEARRAL PURPOSE MEDIUM BUTHRUIT MINCOMS FARMS CUMPLETE.		ž	 	600			
351201	TENT SENTRAL PROPERTY SMALL CIN DUCK FMANK OR NYPINS-POLES	i			أفقف			
	TENT STICKEN FLY PROOF SHWAR GLIVE DRAB COMPLETE WIPINS AND			Ĺ	اومعا			
	TENT CINER OTH PERMEABLE TENT GENERAL PURPOSE MEDIUM	-	?	1	674			
56973			3	 	1772			
575870	1001, 431 CASPENIENS ENG 1M2-4-5180-504		1	· 	 i	~		
375870	TYPEWELTER MONTER MONELEC 15 IN PAPER SIZE 42 TO 44 KEYS CLITE	:						
	TYPE	1	ì	:				
659675	CHARGER MADIAC OSTECTOR PP-15767PD	2	Z		11			
		ļ			 			
	•	i			11			
	1	1		i	1			
	a and a second s	j			1			
				· 				

,		_				· · · · · · · · · · · · · · · · · · ·	
! !	.41	• •		CAMBAN		1	11.0
121	r Atr	THE CHATTERIA	icepa.	Staries .	HELL	HIM ASS	freb to be with
		an ening only programmy they compare strategy and recommendation was not assumed when we have a compared to the	SCEPPING - 6	(ADT SQUE	1986.0		
-						<u> </u>	
1!	2:مسلان	AADIANNUTER IN-9274D	, '		i	'	
! " ;		2.3.3.1.4.13.1.3.1.3.1.3.1.3.1.3.1.3.1.3.	7		!	•	
1 1		AAD10 (L) AN77N-25			<u>.</u>		
	226257	LEACTO JET UNIVERSA ALC TO THE TOP	1	1	1		
	el626	FELTPHONE SET TA- (E) PPT.				į į	
1	44	1 1			i		
1	21174	I MAIN A-ST TOL EAR BYPEAR EINES AND LERAM MOON SER IN BY 16 ET	··			700	
1 1		COMPOSER HES NAVIGATION DEAU PRENDATING TYPE HUMA	2	2	i	220	
		I I I E E E E E E E E E E E E E E E E E		h	1	230	
i	163814	PLOTTER AIRCRAFT SCALE 1 to 500000 AND 1 to 1000000	. 2		:	230	
	78413.	TOOL FIT MIRCHART INDPECTION TECHNICAL	1	- ^ · - i ·		1 ***	
1		المنطقة والمناف أنتمت والمناف والمنافرون والمنافرة والمنافرة والمنافرة والمنافرة والمنافرة والمنافرة والمنافرة				1	
1 1	900010	ANTEMAN 41-191/6	. 3		•	907	
t	-	er denne de descripte de la compactación de la comp		، يحيدا	(· - · ·		
1 1							
02		MOTTONS SECTION			-carleste	,	
[]		I	1		j	1	
	108050	SECON ANIMATING APPARATUS PORTABLE 1 1/2-01	5		1 77 7	600	
 							
t I	213697	BURNEP ASSIMBLY SPACE MEATER	4			600	
f		MESSES SEAL COAL ON OIL 45000 OTU 14-5/4 IN H			ļ ·	. 500	
1 1	24908#	LIGHT TRAFFIC ALRCRAFT W/2 FILTERS GREEN RED	1	1	Jan		
1	4611 de	BAYONET KRIFE W/SCABBARD FOR T.62MM KIFLE				600	
		CHASSIS JAAILER GENERATOR 2 1/2-104 2-40HEEL	1	1		~~	
1	429282	PISTOL AUTOMATIC CAL .45	2	2			
L	A29300 J	PISTOL PYROTEDIMIC	3	£		l i	
1 7	43596>	RIFLE 7.62-MM SEMIAUTOMATIC LY DARREL	22	18			
	45711£.,	JEALLER ANCHIETOUS CARGO LAS TON 2-MEEL	1				
d		- TRAILER CARGO JAN TON TON TON TON TON		~3-			~ ~~~~
1	الإفعادية	TRUCK CARGO 2 1/2-TON 6x6 LWB			·	· ·	
1 1	483110	IRUCK CARGO 2 1/2-TON 8x6 LWB	1	1	1		
1	T#4 1X	EDEROLE STALL ACTIVATOR					**
L	510924	CASE FIELD OFFICE MACH PLYHOOD 22-1/2 L 13-1/4 W 17 O	1	1	İ	1	
	- 518352				1		
J	518300	DESK FIELD PLYWOOD 20 7/8 in w 14 7/16 in H 15 5/8 in D		2	L	l	
1 1		DESK TIFLE ALYWOOD 22 5/8 IN W 25 7/8 IN H 14 1/2 IN D			T		
1	52458G				·	306	
1 1	540775	PARACHUTE PERSONAEL BACK 28 FT DIA GRANGE WHITE SAND AND OG	ī		l .	230	
	384125	SAFE 2 SHELVES I CHAVER 2 COMPARTMENT 26 H 17 W 17 1/2 18 D		-	 		
1 1	562161	TABLE FOLDING LEGS WOOD TOP AND LEGS 36 L 24 W 27-25/32 (N H	6) !	
	565875	TENT GENERAL NURPOSE REDIGE WITHOUT WITHOUTS FAWAR COMPLETE					.
li		W/PINS AND POLCS	2	2		600	
	566050	TENT LINER CIN PERMEABLE PENT GENERAL PURPOSE REDION	2			624	
h	570336 575670	TOOL KIT GENERAL USE TOOLS SIG DRAWING TE-33 TYPEWRITER NUMBER 10 IN PAPER SIZE 42 TO 44 KEYS ELITE TYPE		2	 	905	
1 1	575910		1	1			
{∤		Treat. The down to the fact of the desire that			 		
1 1	604550	SAROHETER ML-102	1	1	1	1	
	603485	BENCOM SET RADIO AN/GRN-8			 -		
11	609673		2		1	L	
1	STUDIO.	CHEST CY-6470	7		1	'	
1	51028C	CIPHER MACHINE ISEC/KL-7		1	i +	۱	
1	618107	TELECTRONIC TACTICAL TELETYPEWRITER SECURITY EQUIPMENT TSCCAREAT	1		i	1	
├ -	818117	GENERATOR SET GASOLIAE ENGINE TRAILER MOUNTED PU-456G GENERATOR SET GASOLINE TRAILER MOUNTED PU-7047G	- 1-	·i·	· · · · ·	ł ,	
į i	528135	MULTIPLIER ANYPRE-15	i	1	1		
-	628139	MULY I MEYER ANJUME TOS		j		1	** *
L	631740	GENERATOR SET GASOLINE ENGINE PE 75	2	2	1_		
		RABAR SEY ANTYPH-B			1		
1	634570			2	<u></u>	ا <u>ا</u>	
1 1	651201	RADIO SET AN/GRR-S BTO IA TRE 3/6 TON CARGO RADIO SET AN/VRC-24 MID IN TRE 1/4 TON	1		1		
1		RADIO SET ANYONG-ZA MIO IN THE 374 TON CANGO			 		
l i	65 3404	RADIO SET AN/VRC-36 MTD IN TRK 3/6 TON CARGO	, , ,	î	!		
		RADIO SET ANYVEC-48 MID IN THE 174 TON	î		· :	-	
1_ 1	656504	RADIO SET ANYVEC-49 MTD IN TRE 3/4 TON CARGO	2	ż	:		
	657:22	HADIO TELETYPEWITER SET ANYGRESES			1		
	658387		1	1	į	[
1]	661006 643040	REELING HACHINE CABLE WAND RL-39					
+	20000 P	REEL EMITPMENT CE-11 REELING MACHINE CABLE HAND AL-ST			4		
1 1			1		!		
1	87 5.38	SWITCHBOARD TELEPHONE MANUAL SE-22/PT			+		
1 1					•	i 1	
							
L	L	•			!	i l	
\Box					T	1 1	
1					1		
1 7					1	[]	
J		 			4	I 1	
;				!	i	į į	
-		1				,	·
		· · · · · · · · · · · · · · · · · · ·		<u> </u>		لسنسا	<u>*</u>

25.0	pascincing					138
Stu Stu Lavas		Santieles	23 L.S.	-	dimen	64 64
1					+	
674767	TELEPHINE SCI TA-312/PI 3 657 5CI STECTSON TOSC TV-770				1	-
486490	THERMOMETER SEEN PUBLICATING FERDING IN CLASS HL-7 THER THE KADIN SEPALAMAN TREETS TO CLASS HL-7 THYCETER VISNASO DEPALAMAN TREETS TO CLASS HL-7 THYCETER VISNASO DEPALAMAN TREETS TO CLASS HL-7		i		1 1	
689615	TING THE MADE PEPALAMAN TE-TIST TIG	- S-			1022	******
	TAVERTER VICANTOS PE-68/U		چ اپ	-	201	
698350	1 wind minimized and 1871 have been at 1/4 Mi	4.1		-	1 1	
64.63	WIRE NO-1711 ON REEK OR 8 1/4 KI WIRE NO-1717 RE-15070		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	خسيجست د	1. 1	
	1	احسا		l	1 " (
	CHAIN ALSY EST LES WIPEAR LINES AND I GRAS HOOR SIE IN EY IN PY	1			701	
1-12	TUTE PRESERVER CHOES AND AIRCRAFT GAS OR ORAL INFLATION	4	<u></u>	-	250	
763266	COMPUTER AIM MAY MATCH AND A FIRE RAPY CAS OF ONE MATCH TON LIFE VARSHAVE UNDER AND A FIRE RAPY CAS OF ONE MATCH TON PROTEEN AIRCRAFT, SCALE, TO SOURCE AND 1 TO 1600000	11	<u></u>	l	230	
J:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
990010	ANTENNA AT-T91/S	-		 	¥07	
	and the second of the second o			1	l l	
. [A CICHIANG DIAGON WARRANCE	1			7	
3 ican	2 ATAPLANE PLATOON HEADQUARTERS	-		 	·	
108050	DECONTAMINATING APPARATUS PORTABLE 1 1/2-07	2	2		600	
14.1823	DETECTOR KIT CHENICAL AGENT VOH		3.		600	
	SUVACE AKSCHELY SPACE HEAVER	 ,			-600	
19628	MEATER SPACE COAL OR OIL ASOOG BTU 18-5/A IN H	1 2	2	11.	600	
		7	~ ~ ~ ~	-	1	-
401988	DATONET KAITE WISCALDARS FOR TIGENH RIFLE	4	6	-	600	
	RIFLE 7.67-40: SENIANTOMATIC LE BARREL			ľ	1 1	
4)5965					4	
463 790	TRUCK UTILITY I/A-TON AXA	į į	2		1	
529120	T GEGGG FETTING TOURS OF THE FET PARKET COLORS FOR MESTRAL TRANSPORT	1 ,		ļ.·	506	
540775	GOGGLES SUN WIND DUST 2 PE 45X1C COLORIESE MEUTRAL GREY TRANSPORTE PERSONNEL EACH 39 TT 51A GRANGE WHITE SAND AND GO TABLE FOLDING LESS WOOD TOP AND LESS 34 L 24 - 27-25/32 IA H TENT GENERAL PURPOSE SHALL CYN DUCK FRANKEID WIPTNS-POLES		~	-	135.0	Marie T1
562161	TABLE FOLDING LEGS MOGE TOP AND LEGS 36 & 24 - 27-25/32 IN M	- 4]		
100595		.2		1	600	
657.50	RADIO SET AN/VRC-26 HID IN THE 174 ION - RADIO SET AN/VRC-66 HID IN THE 1/4 JON -				+	
}	RADIO SET AN/VRC-46 MID IN TRK 1/4 TON	5	5		1 1	
678760	TELLEHORE SET TA-312/PT	1 2		1		
	COMPUTER AIR PAVISATION SEAS RECEDNING TYPE MU-4				1-250	
744510 763200	LIFE PRESERVER UNDER ARM AIRCRAFT GAS OR ORAL INFLATION PLOTTER AIRCRAFT SCALE 1 TO SUSGOO AND 1 TO 109000C	1 2	ž	1	230	
763200	PLOTTER AIRCRAFT SCALE 1 TO SUBCION AND 1 TO 1000000	2	2	-	230	
947.316	A31 ENGA A1-791/G				967	
				<u> </u>		
	& ATRPLANE SECTIONS	 			├	
					1	
451788 429280	BAYONET KNIFE WYSCABBARO FOR T. CZNIM RIFLE	4.6	36		1.00	
435965	BISTOL AUTOMATIC CAL 145 RIFLE 7.62-MM SEMIAUTOMATIC LI BARREL		2 <u>4</u>		┧	
				j	1 1	
540?75		48	36		622	
340600	PARACHUTE PERSONNEL CHEST 28 FT GRANGE AND WHITE SAND AND OG	512	344	 	023	~
627360	RADIO SET ANYARC 162	4		!	517	
638650	RADIO SET ANZURC-10	10	12		620	
278265	TELEPHONE SET TA-312/PT	ندسب		ļ	i i	
301255	AIRPLANE TRANSPORT	16	12	1	1	
1926	AIRPLANE TRANSPORT COMPUTER AIR NAVIGATION DEAD RECKONING TYPE ME-4	32	12	1	1 250	
794410	I LIFE PRESERVER UNDER ARM AIRCRAFT GAS OR ORAL INFLATION	3 58 1	36	ļ	623	
763200	PLOTTER AIRCRAFT SCALE 1 TO 500000 AND 1 TO 1000000	518	384	į	520	
784543	COMPUTE AT NAVIGATION DEAD TEXANDERING THE BB-C LIFE PRESERVER UNDER ANN LARCHAFT DAS ON ORAL INFLATION LIFE PRESERVER UNDER ANN LARCHAFT DAS ON ORAL INFLATION B-7 PLOTTER ATRECKET BECHANICS CENTRAL TOOL KIT ATRECKET BECHANICS CENTRAL	76	!5-			
1	SERVICE PLATOON HEADQUERTERS					
109171	DECOMINATING APPARATUS PORTABLE I 1/2-97 DETECTOR KIT CHEMICAL AGENT VOH	•			600	
213497)				600	
		- -			 	
+		-	·	 		
+		- 			 	-
+				 	 	

「 Marie Commission of the Commission Action Action Commission C

SECTION HI - EQUIPMENT

106 1-59

						1	
, p. q 	184 0 0 10 0	was performed		Charatt Constitution		me-18)	LUCAL
*	RESIDENT.		10271	rischen in	NEX.		Ar
<u>``</u>			 				
25	1	NEATER SPACE COAL OF OIL ASCOC BILL 18-5/8 IN H	2			-000	
	29280	BANNAS I ANTE WASABOARD FOR TEACHER SIFEE	1-17		i	100	
	435905	RIFLE 7.62-MA SEMIALICHATIC LT BARREL	1	10,			
	457110	TRACER UTILITY TAGEOR ONE TON THREET	1	1			
	461834 461385	PISTON AUTOMITE CALL 407 RIFLE FOR-MY SCHAMICHAFTE LI HARREL TRAILER ANDMIBICUS CARGO IVA TON 2-MELL INGER VITALIEV LLS-TOR 648 INGER WAS LAND LAND LAND 646 INGER WASCREA MEDIUM S-TON 646 LNGER WASCREA MEDIUM S-TON 646 LNGER WASCREA MEDIUM S-TON 646 LNGER WASCREA MEDIUM S-TON 646		٠. ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ			
			1			i	
-	510332	CASE FIELD OFFICE MAIN PLYSOOD 22-1/2 L 13-1/6 M 17 D CASE FIELD OFFICE MAIN PLYSOOD 12 1/2 L 12 1/3 W 17 IN D 16 DESK FIELD PLYSOOD 22 5/6 IN W 15 7/6 IN M 1 1/2 IN D DISPHASING PUMP HAND CRIVEN PASSION TYPE 15 CAL FER 100 HEV FILE VISITE INSTEAD BOOM UNIT HETAL AN TO 1/0 PCCEF1X				1	
	510065	DISPENSING PUMP HAND GRIVEN PISTON TYPE IS GAT PER THE HEY				 	
	524300	DISPENSING PUNP HAND GREVEN PESSION TYPE IS GAL PER 100 TREV PILE VISIBLE INDEA BOOK UNIT METAL NO TO 120 DOCKETS. FILE VISIBLE TABLES CASTRET STEET CHAY CHARRET TO NY SLIDES FILLED CASINAT CAR SIZE SIZE, GRAY DO 12, IA D MALOCK COUNLES SON WIND DUST 2 PLASTIC CONDRIESS NEUTRAL CREY PURACHUTE DIFFORMENT HATE JOH TO JOE GRANGE WHITE HAND AND GAS	3		·		
	574580	FILING CASINET CAP SIZE STEEL GRAY DY 1/2 IN D M/LOCK	1				
	\$29100 340775	COUNTES SUN WIND DUST 2 PLASTIC COUCRLESS NEUTRAL GREY		•		230	
	341175	PAULIN CIN ALLE PRING OD 62 FT LG 21 FT W				60 c	
		PUMPTED ASSY STAMMARE RIGOTS BULK TRANSFER SO COM S HE TABLE FOLDING LEGS BOOK TOP AND LEGS SO L 26 & 27-25/32 IN H		2			
	265879	I LENT GUNERAL PUEPOSE MEDIUM HITHOUL HINGONS FINDIR COMPLETE				ll	
			1	1		600	
	371323	TENT LINES THE PERSTAGES THAT GENERAL PURPOSE BEDION TOOL SIT RADAR AND RADIO OF COMPONENTS LYSENSLER MONETAL IS IN PAPER SITE OF TO SALESYS FALLE TYPE VALUE TO BE THE BOOK OF THE TYPE	2	2		221	
	575910	TYPEWRITER NUMBER 20 IN PAPER SIZE AZ TO 44 KEYS ELITE TYPE					
	ALLATC	RADIACHETIR IN-93/40		2		1	
	655201 674260	RADIO SEI ANVECTA STO IN IRS 1/2 TON TELEPHONE SEI TA-312/81	1				
	711740		1	<u> </u>		700	
	711740	COMPUTER AIR NAVIGATION DEAD RECKONING TYPE P5-4				-201 230	
		LIFE PRESERVER WAREN ASSESSET WAS ON ORAL INFLATION PLOTTER ASSESSED SEALE 1 TO SOCOOD AND 1 TO 1000000	ii			1 230	
	763200 	PLOTTER AIRCRAFT STALE 1 TO 500000 AND 1 TO 1000000 TOOL SET ORGANIZATIONAL MAINTENANCE ARMY AIRCRAFT SET C	1	i		530	
		ANIZHAA AJ-791/A				907	
			 				
-64		5 MAINTENANCE SECTIONS				 	
-		DECONTAMINATING APPARATUS DERYABLE 1 1/2-01	-			.505	
	239910.	GENERATOR SET GAS ENG 1.5 KM AC CY 1 PM 2 MIRE AC 120 W SELD MID		·		600	
	239623_	EST FIRE CARRON DION CHARGES HAND 15 LB GENERATOR SET GAS ENG 1.5 KW 60 CY 1 PM 2 WIRE AC 120 V SKID NID HEATER SUCT TIPE PIBL GAS 2509CC DIQ LIGHT SET GEN ILLUM 25 GUTLET	1			-608	
[•	4	i	636	
1	401098	BAYOMET ANIFE W/SCABBARD FOR TAGEMM RIFLE	36	32			
	457220	RIFLE TAGE-MM SUMMANIONALIC LT BANKEL TRAILER CARGO 1 1/2-TON 2-WHSEL	36				
	A&C11C	18UCH CARGO 2 1/2:10h 6x6 146				├ Ì	
_	519896	DISPONSING PURE HAND DELVEN CONTINUOUS FLOW 12 OF PER 100 REV		4			
	529100 525794	DISREMAING PURE HAND DELYEN CONTINUOUS FLOW 12 GL PER 130 REV CORGUES DUR WIND DUST 2 PLASTIC COLORLESS NEUTRAL GREV JENT FRAME TYPE MAINT MED 11 METAL FRAME 00 32 FT LG TENT LINGE FOR 32 FT TENT FRAME 17PE MAINT MOM LT METAL		•		506 206	
	365059	TENT LINER FOR 32 FT TENT FRAME TYPE MAINT MOM LT METAL	•			625	
	711746	CHAIN ASSY SOL LEG MIPEAR LINES AND 1 GRAB HOOK 3/8 IN 6Y 16 FT	1			750	
	784040	TOOL KIT ATRERAFT MECHANICS GENERAL	32	<u> 4</u>		761	
07		AIRFIELD SERVICE SECTION				 	
-	108050	DECONTAMINATING APPARETUS PORTABLE : 1/2-01	6	3		600	~~ ~~
-	224910	EX! FIRE CARSON DIDX CHARGED HAND IS LO	•			1	
\dashv	239821 242842	FET FIRE CARSON GLOS CHARGE WHO SO IS	 			 	
	232845	FILTER TARKON THE STARRED WHO SO LA FILTER SEPARATOR LID FUEL SC GOM 75 PSI 2 IN INLET 2 IN DUTLEY FIRE FIGHT SWIP SET TRE MID ARMY LIRCRAFT CRASH CS CL 5100	1	· · · · · ·			
-		TO THE PERSON AND THE PERSON AND THE PERSON ASSESSMENT AND ADMINISTRATION OF THE PERSON AND THE					
			1				
						1-1	
\Box			1			1	

1	aprel .			PUANTIT		HMARI	100
::	ALT PROPER	HEAR DESCRIPTION	tanking in	MCDC11	I like of	100	4/4 4 /431 \$40
		 		,		 - 	
\neg					1	1	
19	154655	HEATER SPACE COAL OR GIL ASOOD BYU 18-5/6 IN H.	2-			- 500	
.]	401548	HAYONET ANIFE W/SCABBARD FOR 7.62MM REFLE	. 13	H_	i	600	
1	429280 435965	RIFLE 7.62-MM SEMIAUTOMATIC CT BARREL	1 2	10	!		
1	457110	TRASLES AMPHIBIOUS CARGO 174 TON 2-WHEEL	A				
	463.790		1	}		1 1	
1	461834 463885	LINDER AND CHOICE TASTION BYD	2	1]		
1					- · · · · ·		
	510324	CASE FIEL: OFFICE MACH PLYMOOD 22-1/2 L 33-1/4 % 17 D CASE FIELD OFFICE MACH PLYMOOD 3% 1/2 L 13 1/4 % 17 IN D ID DESK FIELD PLYMOOD 22 5/8 IN W 25 7/8 IN H 14 1/2 IN D DISPENSING PUMP HAMD ORIVEN PISTON TYPE 13 GAL PER 100 REV	· ·		 -		•
- 1	518320	DESA FIELD PLYMODO 22 5/8 IN W 25 7/8 IN H 14 1/2 IN D	1	i_	L	11	
T	519840 524300	DISPENSING PUMP HAND URIVER PISTON TYPE 15 GAL PER 100 REV	2	2			
-+	524380	FILE VISIBLE INDEX BOOK UNIT METAL AD TO 120 POCKETS FILE VISIBLE INDEX CABINET STEEL GRAY ENAMEL : # OR 9 SCIDES		1	· ·	1	•
_	524580	FILING CABINIT LAP SIZE STEEL GRAY 33 172 IN D WYLUCK GOGGLES SUR WIND DUST 2 PLASTIC COLORLES NEUTRAL GREY		1		1	
- 1	\$29100 \$46775	GOGGLES SUM WIND DUST 2 PLASTIC COLORLESS REGINAL SKEY PARACHUTE PERSONNEL BACK 28 FT DIA GRANGE WHITE SAND AND GG (1	1	1	230	
-1	541175	PARACHUTE PENSONNLL BACK 28 FT DIA GRANGE WHITE SAND AND OG PAULIN CON DUCK FRANK OD 40 FT LG 20 FT W		- 5	i	600	
	546780	PRINTING ASSY FLANMABLE LIGHT BOLK TRANSFER 50 CPM 5 HP	<u>2</u>	<u>2</u>		ļ	
- 1	562161 365275		8	'	1	1 1	
7		W/PINS AND POLES		1		600	-,
-4		TENT LINER OTH PERMEANIE IENT GENERAL RURPOGE MEDIUM	1 2	1 2		624	
- 1	571325 575870	TOOL KI HADAR AND RADIO AT COMPONENTS TYPEWRITER NONPTEL II IN PAPER SIZE 42 TO 44 KEYS ELITE TYPE TYPEWRITER NONPTEL ZO IN PAPER SIZE 42 TO 44 KEYS ELITE TYPE	1	1	L	1 ***	
	575915	TYPEWRITER MONPTEL ZO IN PAPER SIZE 42 TO 44 FEYS ELITE TYPE	7	1		11	
}	634670	RAMIACHTES IN-STAIN		2	 	1- 1	
IJ	_ 655291	RADIO SEE AM/VBS-66 MID IN IRS 1/4 JON TELEPHONE SET TA-312/PT	1	1	L	J	
1	678260	TELEPHONE SET TA-312/PT	ı	1	1	1 1	
+	711745	CHAIN ASST SEL LEG WIPEAR LINKS AND 1 GRAB HOOK 3/8 IN BY 16 FT	1	i		700	
_1	711749	lge	?			701	
1	712730 744410	COMPUTER AT HAVIGATION DEAD RECKONING TYPE M8-A	1	1	1	230 230	
1	763200	LIFE PRESERVER UNDER ARM AIRCRAFT GAS OR DRAI INFLATION PLOTTER AIRCRAFT SCALE 1 TO 500000 AND 1 TO 1000000 TOOL JET, ORGANIZATIONAL MAINTENANCE ARMY AIRCRAFT SCI.	1	1		230	
}	785250	TOOL SET ORGANIZATIONAL MAINTENANCE ARMY AIRCRAFT SET, C	\			 	
-	960010	ANIENNA A1-191/6				.901	
6		* MAZHIENANCE SECTIONS				 	
-	108050	DECONTAMINATING APPARATUS PORTABLE 1/2-GT		4		600	
1	222913	EXT FIRE CARDON DIOX CHARGED HAND 15 LB	- 4		L	11	
	235163	GENERATOR SET GAS ENG 1.5 KW 60 CY 1 PH 2 WIRE AC 170 V SKID MID	4	4		600	
	239623	LIGHT SET GEN TELOM 25 COTLET		4	 	606	
_1					!		
	64.1088	BATONET RNIFE W/SCAUDARD FOR 7.62MM RIFLE	36	32	1	1	
-	. <u>445965</u> 457270	RIFLE 7.62-MM SLMIAUIOMAIIC LI BARREL TRAILEF CARGO 1 1/2-TON 2-WHEEL	36_		 	† ·	
1	4AC11C_	JRUCE CARGO 2 1/2-TON 616 LWB	·····	·	 	 	
	51580C	OLIGENBUING PUMP HAND DRIVEN CONTINUOUS FLOW 12 GL PER 100 REV.			l	1	
7	527100	GOGGLE' SUN WIND DUST 2 PLASTIC COLORLESS NEUTRAL GREY	4	4	I	506	
-+	566019	JENT FRAME TYPE MAINT MED LT METAL FMWYR OD 32 FT LG.		4	·	- 600 625	
					ļ	1 1	
- 1	711740 711740	CHAIN ASSY SGE LEG WIPEAR L'HKS AND ; GRAB HOOK 5/8 IN BY 16 FT	1	i]	700	
1	784040	TOOL KIT AIRCRAFT MECHANICS GENERAL	32	28	1	1.77	
-†		page again			1		
7		AIRFIELD SERVICE SECTION				† 	
1	100050	DECOMPENDENTING APPARATUS PORTABLE 1 1/2-01	6	5		600	
1	229910	EXT FIRE CARBON DIDA CHARGED HAND 15 LB		4	 	11	
-+	232542	EXI FLOR CARBON GLOW CHARGED WHILE SO IN			 -	1	-
		FIRE FIGHT FOUTS SET TER MID ARMY LINCRAST CRASH OS CL 3100	L 1				
1							
							-
_ [
-1							
					 	†•- ·-	
+	7			,		 	
			~~-~~~	·			

SECTION IN EQUIPMENT

) - up 1	<u>' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' </u>	<u></u>	G- ASIDIY	 	. 154
	n. 781	iii,≈ La Cheffee	my gran	(ACA):	1	ii.
		and the state of the state of the second state			 	
	249.93	CTERRATOR SEE DAY EAS LAS NO BE CY L BH. 2 HERE AC LES V 1KLG MEE CLEVE DET COURT AREA ATROPART I 1/2 KM ATRELED RUSMEY LIGHT SE, MARKER EMERGENCY ATROPARTE RUSMAY PLDE DATES GROED			 600	
-	4,36963	EAUMER' NEIT WISCHARD FOR PARKEL HITCH 1,02-MM SEMIAUTOMATIC LT CARREL SEMITABLES TAK CASOLING SOCO CAL AMBUER THALLES TAK CASOLING SOCO CAL AMBUER		10	 	
	640086 856198	TRUCK 1ANK FUEL SERVICING 2 1/2-10N 6x6			 	
	738788 214699	CONTINOL PRESSURE FILLING NOT VENTED ORUM 5 PST SHUT OFF DISKENSING PUMP HAND GRIVEN CONTINGUOS PLOW 12 OL FER 100 HEV DESCLES SUM MEND DUST 2 PLASTIC COLORIESS NEUTRAL OREM		2	 125_	
	664300	AMERIFIES-POWER DOWNER DAILBASTERGIS AND DE SET 4-YPP TELEFORM SELLIFORM			¥16	
	711749 711740	CHAIN A SY JULY 1 THE THE CORP. CORP. THILL TRANSPORT TO A PROPERTY OF	2		 700 701	
	960010	ANTENNA A1-753/G	1	1	907	

वस्य एक क्रांक्ट स्टाइट

THIS PAGE NOT USED

(U) ANNEX F

DATA COLLECTION FORMS

	he data collection forms	s used during the CV-28	(1
Form.		no Page	(3
Evaluators Mission	Report	escapola 122 m	į,
Mission Report, Ai	rdrop Techniques	NOTE WAST DESIGNATED TO	÷ .
menter of restrict displacements of the contract to a facility and the contract of the contrac		F-7	
Maintenance Data,		0.490. 14 0 MI US. 38 810	
Supply Data, Requi	isition Summary	THE PROPERTY OF THE PROPERTY O	14,45
Maintenance Data,	Battle Damage	3 to 25 10.	i , '
Maintenauce Data,	Recapitulation	\@Bad.ko.as	
Crew Chief Work L	og signer vensens silver avgerner	12.	ņ
Aircraft Hit Repo			
	on the second second second second second second second second second second second second second second second	Albitode.	
a management of the second of		7 ·	

CV-2B (CARIBOU) EVALUATION EVALUATION REPORT

dera collegator and

	The Marian Boordard.
1)	DIG MISSION RECEIVED.
2)	Mission No:
3)	Mission No: Type Mission: Crew Chief
	warming a serious and a serious married of the serious and the
	DIG Scheduled Take Off/Neturn: Asst Crew Chief Consequinted be reconce costs - consequented
	DTG Actual Time of Departure/Returns 1950 dol 5000 total total
6)	Delays (Length & Type): Visania noliticinas asset gives
~?)~	the second secon
8)	Altitude: nocamitation force विरुद्ध
9)	Approach and Landing Technique (Selected): 307 From Seids ward
	a) Pattern: 3 County of the officers of the
	b) Altitude:
	c) Flap Setting:
	d) Angle of Descent/Hate of Descent:
	e) Landing Roll:
	f) Winds/Density Altitude:
10)	Landing Area (Selected):
	a) Length/Width:
	b) Obstructions:
	c) Composition of Landing Area:
	d) Condition of Landing Area:
	e) Communications:
	f) Loading/Unloading Procedure:

F-2

ANNEX F

11)	Take Off	Technique: (Normal) (Maximum Performance) (Flap Setting)
12)	Enemy Si	tuation:
13)	Weather:	
·	*****	
14)	Evasive	Action Taken:
15)		Techniques Used (Describe):
بوت ٠٠٠ ب	Section of the Control of Section 1	CERTAIN BOOKSTED ON
	• • •	() (Basis And)
16)	Conmuni	cation/Radar/Navigation Equipment Used: Time Operated
	a)	Single Band Radio:
	b)	UHF/VHF/FM:
	c)	Weather Avoidance Radar:
	d)	ADF/Quni/Doppler/Decca:
	e)	Describe Malfunctions:
	-,	
	f)	Contribution of Equipment to Mission Accomplishment:
	17	
17) Aircra	ft Maintenance Problems:
• • •	,	
18) Summar	y: Pax Hauled/Pex Miles:
		Type & Amount Cargo/Cargo Miles:
		Total A/C Flying Time:
		Weather Time:

enomeser Transcription
Cantidae qui f/ Agasta S/A Time
Number-Missions/Sorties:
Renarks:
CANALL RELEASE (1)
the land of the second of the
(Evaluators Name) (Rank)
(Branch) (Title) Detagraph only : Detail density in A/C Comdr/Filot/Observer (A)
ed basic death and the
the fact of the same of the sa
the state of the s
් න ව ස්ථාව රක්ෂණ වන සහ ප්රතිකාරය විසින් වන සහ ප්රතිකාරය වන සහ ප්රතිකාරය වන සහ ප්රතිකාරය සහ ප්රතික සහ ප්රත
n de la composition br>La composition de la
المحافظ الم
the entire experience of the first of a market of the temporal experience.
Fig. Distance of the second control and the s
and the second s
ng ngangan nganggan digitanggan nganggan nganggan nganggan nganggan nganggan nganggan digitanggan nganggan nga
and the second of the second o

DATA COLLECTION RECORD: caupinated saying

AIR DROP TECHNIQUES 2011 Q 0000 CARIBOU EVALUATION

The state of the s

ANNEX F

Evaluator: L. Mission: Cargo Personnel Daylight Dark DTG Requested DTG Scheduled DTG Executed 2. Method of Delivery: Door Bundles LOLEX HIVEL Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation (c) Describe DZIZ surrounding terrain	Date:	C)	೧ ಇಕ್∀೦ ಕರ್	दक्षत् ५० स्टब्स्स	
Personnel Daylight-Dark Daylight-Dark DTG Requested VALUE CONTROL STREET AND STREET A	Evaluator:		After Similar constraints	No Mission	No:
Daylight Dark DIG Requested your assumed as a service of the serv	i. Mission	: Cargo	(ow char	ं क्यां राहाका	
DTG Requested For DTG Scheduled DTG Executed 2. Method of Delivery: (Check) (Type Parachu Door Bundles LOLEX HIVEL Cravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width)	gay chi () ya dhag eshinan eshing gan dhe ()	Personnel	o Dia Selection	realine action	<u> </u>
DTG Scheduled DTG Scheduled 2. Method of Delivery: (Check) (Type Parachu Door Bundles LOLEX HIVEL Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation				•	
DTG Scheduled DTG Executed 2. Method of Delivery: (Check) (Type Parachules Door Bundles LOLEX HIVEL Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation	sample from a self gardy to a second of the second from a second of	DTG Requested	र् रोक्ट्रव ्यः	n in occurr	
DTG Executed 2. Method of Delivery: (Check) (Type Parachu Door Bundles LOLEX HIVEL Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation		-DIG Requested Fo	r isangan	, daoi dhear	72
2. Method of Delivery: (Check) (Type Parachu Door Bundles LOLEX HIVKL Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation	an gilin ya am ing ganggaliyanan ka daki n <i>iliya add</i>			•	•
2. Method of Delivery: (Check) (Type Parachu Door Bundles LOLEX HIVKL Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation	(M) OTA	DTG Executed	The second secon		
LOLEX HIVEL Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation	7.			(Check)	(Type Parachute
HIVEL Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation	and the second s	of Heavy Drop	رومين دو استياده در مس <u>ي پيموندي</u> از پاکينيو		
Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation		Door Bundles	-	1.12(17)(0.0)	market the statement
Gravity Drop 3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation	the state of the s	LOLEX	e species and a second		
3. Delivery site/Drop zone: (a) Size (Length/Width) (b) Elevation	a de la composición de la composición de la composición de la composición de la composición de la composición	HIVEL			
(a) Size (Length/Width) (b) Elevation	and the same	Gravity Drop			
(b) Elevation	3. Delive	ery site/Drop zone:			
	AND AND AND AND AND AND AND AND AND AND	(a) Size (Lens	th/Width)		
(c) Describe DZLZ surrounding terrain		(b) Elevation			
		(c) Describe D)ZIZ surro	unding terra	in
(d) Describe terminal guidance used		(d) Describe	terminal g	ruidance used	

j -- j

4. Flight T	echniques: Direct Roll Policy	the state of the s
	Drop Airspeed	
	Drop Altitude	30 May
	Number of passes over D	and the control of th
		And the second s
	Timetover DZ	
·	Ground fire (Yes, No)	gugar andrækki k
	Evasive action by A/C c	rew Carenceres
5. Effectiv	eness of drop:	Herealth State of Grant
	Estimate of accuracy	ted panest endi
		(%, on UZ);
· · · · · · · · · · · · · · · · · · ·	· ·	ris Lubanica Vall
6. Weather:	(eky cover)	(aloft) (ground) (winds)
(Tees jamejane)		(winds)
And the second second second	(visibility)	(ceiling)
7. Evaluate	ors Comments:	an Makati data
		Sec. Sec. Sec. Sec. Sec. Sec. Sec. Sec.
		3 - At - 4.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 - 2.5 -
• • • • • • • • • • • • • • • • • • • •		. W. S
		and the second second second second second second second second second second second second second second second
	<u> </u>	<u> </u>

DATA COLLECTION RECOFD

Scheduled Organizational Faintenance - Daily and Intermediate Inspections

ate:_	ift Num	b er	No.	Daily Insp	Intermediate	Beginnin	tme g-Fnd Konth	(1) F10	'n
	Days			22	AT 1189 HOLAU III	diaments.			
sylsi	auta.	000		[348-11], will (5	No. and the state of the		The state of the s	(AC)	
23. Water-1542 -		*******	**************************************				\$ 8.		
							The second secon	evetice as a	
AST HE WAY		قة معنيد سن	Andreas and a second	-					
			(ر د ده جمعیت بید و مهمید صدو بنوست					
		:							-
	· · · · · · · · · · · · · · · · · · ·	: :		د د د د د د د د د د د د د د د د د د د		A TOTAL CONTRACTOR STATE OF COMMAND			
				————————————————————————————————————				-	+
				والمراجعة والمراجعة والمراجعة والمراجعة والمراجعة والمراجعة والمراجعة والمراجعة والمراجعة والمراجعة والمراجعة					7
		:						-	+
	. .	ا مستنج					The second secon		i
		1		·					+
	ا مادو ما در مادو	: ; ,,k =	.	and any or analysis and section to the	and the second s		* * * * * * * * * * * * * * * * * * *		4
		i					1	-	÷
		1		a designativo de la compansión de la compansión de la compansión de la compansión de la compansión de la compa	man and the second control of the second second second second second second second second second second second		سره وحصص سميره بدأت	**************************************	_,
		-	Ĭ					<u> </u>	
					·				
	.,								
	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		1					1	
I				randon e e e e e e e e e e e e e e e e e e e	and the second s	and the second s	and the second s		,,,,,,

The state of the s

ACTIV FORM (28 July 1964)

ANNEX F

- Posesature: E aprime increase by Papario ? ere en thaify and Intermedia WIN SUPPORTED: TYPE SUPPORT (DS - GS) unit en porting JOB ORDER REGISTER Aircraft Julian Date Down-Number Description Started Fireshed Time randers

ANNEX P

ACTIV FORM (29 July 1964)

de de la light de la collection de collectio

Christian of the

92.025	·				<u> </u>			المنسس
CODE	02	1	<u> </u>		12	17		1 1
ubnitted	gas angagan ki ng day aka annan musi na aan s						المحاولة المحاولة المحاولة المحاولة المحاولة المحاولة المحاولة المحاولة المحاولة المحاولة المحاولة المحاولة ا	
							<u>ئۆنىڭىنى</u> خۇخسىيىلىس	
eceived					The second secon			
)ne-In	and phaging sharpers with the transfer of the	-			and the second desired the second		د بازدی در است. ماهندی در است.	
(efill-Time (Days)	The same strangers of the same						و د د د د د د د د د د د د د د د د د د د	
						ga (pagada adapa persena pagada pagada pagada pagada adapa persena pagada pagada pagada pagada pagada pagada p		
Grand Total								-
				_	· ·			====
Total Filled					y v wy v vyden	1000st.	oost spa 1820-pa	1
		_	·					-
Percent Filled	. <u></u>				م د معمد د المعمد ال		: 38.	iii č
REMARKS:								
							- Company of the Comp	

DATA COLLECTION NEWORD

Battle Damage

Summary of Aircraft Bits

Date	Corps Area	Altitude	In the Pattern	Man-Hours for Repair
			3.0	
				ro id the ste
				1002
				BUIT-HITE
				(10)
		was a series of the series		and the state of t
	· ;			
	·		÷	
verage Numb	er Hits:		:	
verage Alti	tude:			
verage Man-	Hours:	A STATE OF THE STA		
envela russen .	i .	:	<u>.</u>	\$,167 same
EMARKS:				

ACTIV Form (28 July 1964)

ANNEX P

DATA COLLECTION RECORD

Recapitulation Organizational Maintenance

* ******		an a minima managari s						
1.51	·		*, *, *, ***			4	1 · • · · • · • ·	
' •	•		1				اد اداده میسیده	
A .				DATA_CO	LECTION	LAPCOAD		
			Recapitul	stion O	rasnizat	ionel Kei	ntenance	
* & ·		****						
`	D - 4							
	Date:			- 2 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	≝:.		Aug Lie Mari Allia	WENT I
	Acft SN	PE	Acft SM		www.Acft	SN PE	Act.Si	Top RE
		DM		DM	i ee i	DM		DM
		DI INT	گهی در در مشترکتو دست. آدرک و∑اژ	INT	Audio (G)	INT	Ym lo nolas	ing INT
						-	paling 	
	To	tal:	Te	tal:	galler Mariantan	Total:	may made 19	otal:
!	Acet SN	ara	Anft SN	Dir	Acet	SM DVP	Acft Si	יוסו ו
	ACLU DA	DM	ULLER STEER	DM		DM	TOTAL STATE	DM
		DI		DI		DI		DI
•		INT		INT	១០១៨៦ ប៊ុ	INI	A 14 Voltage	INT_
	То	tal:	Te	stal: AF		Total:	<u>s jo seumal</u>	'otal.
The State of the S		The state of the s		and the second second second			<mark>diginal de la companya de la compan</mark>	
	Acft SN		Acit SN	PE	Acft		Aeft Si	
		DM		DM_		DM_		DM_
		INT	نو پور د هم دار ۱۳۰۰ د اول دووا	INT	· · · · · · · · · · · · · · · · · · ·	INT	ئەمەمەر ئالىمۇر _	INT
•								
	To	tal:	<u></u>	otal:	· ·	Total:_		cotal:
	Acft SN	PE	Acft SN	PE	Acft	SN PE	Acft Sh	I PE
	•	DM	•	DM		DM		Jи
		DI		DI		DI		DI
		TM1		INT		INT	· ·	INT
	To	tal:	To	otal:		Total:_		lotal:
	*							
	REMARKS:					•	•	
					·	·····	·	· .
				·····				
							;	
				· .	· 	······································		, , , , , , , , , , , , , , , , , , ,
				·····		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
		L.						
						······································		
	ACTIV Fo							
	(28 July	1704)						
•								
•	-				y			45-11-00-
•					F-11			ANNEX I

CREW CHIEF WORK LOG

india.	·		DATE	
	1.	I was awakened at	hours.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	2	I began work at	hours.	100 mg 25.
		Preparation of my aircraft fo	_ ·	
	4	Take off time was	nours.	
	5	Total flying time for the day	was house mins	al worth
		Total number of operational s		<u></u>
	7.	Total number of passengers ha	uled was	13.00
	8.	lotal amount of cargo hanled	<u> </u>	and the second
	9.	Time spent for lunch break wa	hours mins	e en en en en en en en en en en en en en
		hours mins		
	11.	2		
	12.	My after-flight mintenance and including myself there were		hours mins
	13.	I finished work at	hours.	
		I ate supper after	wo:k.	
		I took a hour mins	_supper break.	e.
	14.	I have (didn't) flight.	an assistant crew chie	f during the
	15.	nbMAnKS: (Include anything difficulty; such as demand loading problems.)	unusal that caused yo maintenance during the	u extra work or day or unusal
ANNE	X F		F-1 2	

	36 11 0 10.
9	
	(a) 1311 lin.
	11 11 11 11 11 11 11 11 11 11 11 11 11
·····	
	96 11 44 17.
1	
•	
	Jan 1 te a in.
	ATT
(9 ft 6 la.
Data of Hit	Geographical Location
Date of Hit Number of	of Aircraft
Hits	Altitudes of Aircraft When Hit
Location of Hits on	
Aircraft	

ANNEX F

THIS PAGE NOT USED

to compare leavened and be considered

DISTRIBUTION - Notice of the second of the

ないできるないのかのできることがある。これできることがあるともなっていましているというできると

	Control of the second second second second
Office of the Chief of Staff of the Army (ATTN: Director of Coordination and Analysis, Coordination Division)	To the separate and have a fine
Deputy Chief of Staff for Personnel Department of the Army	otesio nen i mosambi <mark>o</mark> mosimo sen sen sen seto
Deputy Chief of Staff for Logistics Department of the Army	•
Deputy Chief of Staff for Military Operations Department of the Army	-
Assistant Chief of Staff for Intelligence (ATTN: Director of Surveillance and Reconnaissance, Doctrine Division	name en Nest deposit
Assistant Chief of Staff for Force Development Department of the Army	
Office of the Assistant Chief of Staff for Force Development, ATTN: ACTIV Limison Officer, Department of the Army	10
Chief of Research and Development (ATTN: Special Warfare Office) Department of the Army	3
Office of the Chief of Communications-Electronics Department of the Army	4
Commanding General, US Army Materiel Command	35
Office of Personnel Operations Department of the Army	2
Office of the Surgeon General Department of the Army	1
Commanding General, US Continental Army Command	30
Commander-in-Chief, US Army Pacific	5
Commanding General, US Army Combat Developments Command	50

Joint Test and Evaluation Task Force (JTETF) USSTRICOM MacDill AFB, Fla. (ATTN: Major General Rosson)	1
Commandant, Command and General Staff College	2
Commandant, US Army War College and this is Their to the content out :	0 00 2 0014
Commanding General, Defense Documentation Center	.29v i
Commanding General, 11th Air Assault Division	o ya s gad
Commandant, The Infantry School, ATTN: AJIIS-A	3
Commandant, The Armor School	
Commandant, US Army Artillery and Missile School	
	10
Commanding General, US Army Special Warfare School	
Commanding General, US Army Civil Affairs School	Total
Commandant, Signal School, US Army Signal Center	a hakeyi bakeyi a dalah katebake
Commanding General, US Army Electronics Proving Ground	400
Commanding General, US Army Aviation Center	33 mg 54.7
Commanding General, US Army Forces Southern Command (ATTN: SCARCD)	3
Commanding Officer, US Army Limited War Laboratory	2
Commander, US Military Assistance Command, Vietnam	15
Commanding General, US Army Support Command, Vietnam	20
Director, Joint Research and Test Activity (For distribution to COMUSMACV and CINCPAC)	6
Chief, OSD ARPA R & D Field Unit, Vietnam	5
Chief, OSD ARPA R & D Field Unit, Thailand	1
Commanding Officer, US Army Special Forces, Vietnam	10
Director, United States Overseas Mission Saigon, Vietnum	1

Ĭ.	Commanding General, USAREUR, ATTHE G-3 124 201 (2010) Lavall 01500 (0.0 000) 1200 (2010)	The basis deck offi	• 5 .£
	Commanding General, Seventh US Army, ATTN: G-3		5
١.	Commanding General, USARCARIB	yen e te	1
	Commanding General, US Army Test & Evaluation Command	Conditi	
٤	Commanding General, US Tray Ordnance Center & Schools Command	integral Literra	
	Commanding General, US Army Mobility Command	*2 15 gr	1 بول
*	Commanding General, US Army Special Forces Additional? Fort Bragg, North Carolina	्यश्चित्	
<u>*</u> -	Commanding Officer, Combat Developments Command Special Warfare Agency, Fort Bragg, North Carolina		2
	President, US Army Armor Board	pares	
ب ب	President, US Army Infantry Board	TETTA	1
	President, US Army Aviation Test Board	india 14	2
	Commanding Officer, Combat Developments Command Aviation Agency, Pt Rucker, Alabama	maina.	
	Commanding Officer, US Army Special Forces, Okinawa	* 15, 44.	2
İ	Commanding General, US Army Special Warfare Center Fort Bragg, North Carolina		2
	Commanding Officer, 1st Psychological Warfare Battalion (B&I Fort Bragg, North Carolina	.)	1
	Commanding Officer, 5th Psychological Warfare Co (Field Army Germany	•)	1
	Commanding Officer, 13th Psychological Warfare Battalion (Be	T)	1
	Commanding Officer, USABAVPAC, APO US Forces 96331		2
	Chief of Naval Operations, Department of the Navy Washington, D.C. 20310		1

Bureau of Naval	Weapons, Department of the May	<u></u>
ALLM: War Curer	for RDTes, Washington, D.C. 20310	of Trial Suppose
Commandant, U.S.	Marine Corps, Washington, D.C. 20310	1
Tamulan Maine of	Ctaff (DED) Ha H & Marine Counc	puint y pol
Washington, D.C.	Staff (P&D), Hq, U.S. Marine Corps. 203160 number land a color of the corps.	A CONTRACTOR
Masistant Chief Washington, D.C.	of Staff 6-3, Bq, U.S. Marine Corps 20010	
	Corps Landing Forces Development Center	waring real of the
Quantico, Virgir	nia alicabă (alicați vant ni arano) ; Alicabi distini S. Air Force, Washington, D.C. 20310	
	The second state of the second	
AFCCS	આદાતિવાદન હીંવડમાં કુકુકારો છે તોવે કું કહેદુકું, જ્હેદીઓ	er leisens 1
AFRDC		
AFRST	ক্ষানাই কুলাই বুলকা স্থ	1 1 1 1 1 1 1 1 1 1
AFRDD	Between States of the Samuel States	weist will 1
AFROP	tan mary 17 ilia diti wasan 1944 kilonga katalonga 1937, sa 1931 ilianga tang bandan sa tang bandan sa tangga	
AFPRQ	រដ្ឋការកុរ៉ា ទំនួន (ស្នងក្នុងក្នុងក្នុងក្នុងក្នុងក្នុងក្នុងក្	1 70 07 08 08 08 08 08 08 08 08 08 08 08 08 08
AFORQT	te transfer and the second	1
AFXPDA	w	1
AFXPDR		1
AFXOPI	Program Description	2
	ir Force Systems Command, ATTN: SCS-6 ce Base, Washington, D.C. 20331	3
Commander, Air l	Proving Ground Center, ATTN: PCBAP-1	1
	esearch & Technology Division ling AFB, Washington, D.C.	1
	ics Laboratory, ATTN: AVP n AFB, Ohio 45433	1

Headquarters, Aeronautical Systems Division, ATTN: ASJ Wright-Patterson AFB, Ohio 45433	1
Headquarters, Aeronautical Systems Division, ATTN: ASZ Wright-Patterson AFB, Ohio 45433	1
Headquarters, Aeronautical Systems Division, ATTN: ASR Wright-Patterson AFB, Ohio 45433	
Air Force Flight Dynamics Laboratory, ATTN: FDG Wright-Patterson AFB, Ohio 45433	1
Air Force Aero Propulsion Laboratory, ATTN APS-Maj D.L. Summer Wright-Patterson AFB, Ohio 45433	1
Systems Engineering Group, ATTN: SESJ, Director of Limited War Wright-Patterson AFB, Ohio 45433	1
Headquarters, Tactical Air Command, ATTN: DOPQ Langley AFB, Virginia	T
Headquarters, Tactical Air Command, ATTN: DMEM-AC Langley AFB, Virginia	ı
Headquarters, Tactical Air Command, ATTN: DORF-SW Langley AFB, Virginia	1
Commander, 1st Air Command Wing, Hurlburt Field, Flordia	1
Commander, Special Air Warfare Center, Eglin AFB, Flordia	1
Commander, 1st Combat Application Group Eglin AFB, Flordia 32542	1
Headquarters, Pacific Air Force, ATTN: PFORQ Hickem AFB, Hawaii	1
Headquarters, Pacific Air Force, ATTN: PFLPL Hickam AFB, Hawaii	1
Headquarters, Pacific Air Force, ATTN: PFMSS Hickam AFB, Hawaii	4
Commander, Tactical Air Warfare Center Eglin AFE, Flordia 32542	ב
Commander, 2d Air Div, 13th Air Force, APO US Forces 96307	2
Commander, 13th Air Force, APO US Forces 96274	2
· G-5	ANNEX G

A STATE OF THE PROPERTY OF THE

The second secon

THE PROPERTY OF THE PROPERTY O

The state of the s